## Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

DEPARTMENT OF THE INTERIOR  BUREAU OF LAND MANAGEMENT  ALLO 106. Delations						Expires: Janua		
BUREAU OF LAND MANAGEMENT AUG 100 DOME LES SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for the proposal residence of the proposal res					5. Lease Serial No. NMNM81217			
					f Indian,	Allottee or T	ribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					. If Unit or CA/Agreement, Name and/or No. NMNM91013			
Type of Well     Gas Well □ Other					8. Well Name and No. NAGOOLTEE PEAK 5 FED 3			
Name of Operator Contact: DAVID STEWART OXY USA WTP LIMITED PTNRSHIP E-Mail: david_stewart@oxy.com					9. API Well No. 30-015-29900-00-S1			
3a. Address		3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area			
HOUSTON, TX 77210		Ph: 432-685-5717			INDIAN BASIN-STRAWN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County			nty or Parish, State		
Sec 5 T22S R24E SWSW 1230FSL 800FWL					EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE, REI	ORT,	OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
□ Notice of Intent	Acidize Deep		pen Production		n (Start/Resume)		☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing		☐ Reclamation		(	■ Well Integrity	
Subsequent Report	Report Casing Repair New Co		Construction	☐ Recomplete	Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	☑ Plug and Abandon		oorarily Abandon			
	☐ Convert to Injection	Plug	g Back					
If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 7/12/18 - MIRU PU, NDWH, N POOH.	rk will be performed or provide to operations. If the operation restondonment Notices must be file inal inspection.	the Bond No. on ults in a multiple d only after all r	file with BLM/BIA completion or reco	. Required subseques mpletion in a new in ing reclamation, have	ent repor nterval, a re been c	ts must be file Form 3160-4	ed within 30 day must be filed o	/S nce
7/16/18 - RIH & tag CIBP @ 7964', PUH, circ hole w/ 10# MLF, M&P 70sx CL F				PUH, WOC.			TION PROCE TTACHED	DURE
7/17/18 - RIH & tag cmt @ 76 & tag cmt @ 6186', PUH & se cmt, got returns to surface.	73', verified by BLM. PUH t pkr @ 4693', RIH & perf	l to 6385', M8 <u>@ 4950</u> ', EIR	P 40sx CL C cn @ 2bpm @ 100	nt, PUH, WOC. 00#, M&P 60sx (	RIH CL C	Accepted	8-17-1 for record	NWOC
7/18/18 - RIH & tag cmt @ 48 pressure to 1850#, no rate or to EIR, pressure to 2200#, no	loss. Notify BLM, request	perf @ 2935'	. RIH & perf @	2935', attempt			AMAT  - 24-	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #4	30438 verifie	hy the RI M Well	I Information Sys	tom			
Comm	For OXY USA WTI	P LIMITED P†I	NRSHIP, sent to	the Carlsbad		nee\		
Name (Printed/Typed) DAVID ST		GULATORY AD		,3E,				
			· · · · · ·		400	COTCO	TOD DE	CODI
Signature (Electronic Submission)			Date 08/09/20	018	AU	EPIEU	FOR RE	COKL
	THIS SPACE FO	R FEDERA	OR STATE	OFFICE USE			4 16 0040	
Approved By			Title			AUG	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office		Bi		AND MANAGE D FIELD OFFI	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c	crime for any per to any matter wit	son knowingly and	willfully to make to	any depa			

#### Additional data for EC transaction #430438 that would not fit on the form

#### 32. Additional remarks, continued

RIH to 3012', M&P 70sx CL C cmt, POOH, WOC. RIH w/ pkr & tag cmt @ 2875', notify BLM of tag, request perf @ 2864'. PUH & set pkr @ 2536', RIH & perf @ 2864', attempt to EIR, pressure to 1700#, no rate or loss.

7/19/18 - POOH w/ pkr, RIH w/ tbg to 2853', M&P 45sx CI C cmt, POOH, WOC. RIH & tag cmt @ 2588', notified BLM of tag. PUH & set pkr @ 1426', RIH & perf @ 1670', attempt to EIR, pressure to 2200#, no rate or loss. Rec BLM Approval to spot plug. RIH to 1712', M&P 45sx CL C cmt, PUH, WOC.

7/23/18 - RIH & tag cmt @ 1451', POOH. RIH & set pkr @ 1046', RIH & perf @ 1290', EIR @ .5bpm @ 1900#. Pkr came unset, POOH w/ pkr, RIH w/ tbg to 1371', M&P 45sx CI C cmt, PUH, WOC.

7/24/18 RIH & tag cmt @ 1188', POOH. RIH & perf @ 405', EIR @ 1.5bpm @ 1000# w/ full returns to surface. ND BOP, NU adapter flange, M&P 135sx CI C cmt, circ cmt to surface on all strings. RDPU.



## United States Department of the Interior

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612