Form 3160-5 (Jurge 2015)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

No. 549

5.	Lease	Serial	N
	NMN	M10	0

SUNDRY N	OTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

abandoned wei	i. Use form 3160-3 (APD) for su	icn proposais.		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
SUBMIT IN T	RIPLICATE - Other instructions	s on page 2		7. If Unit or CA/Agreem	ent, Na	une and/or No.
Type of Well Oil Well	er			Well Name and No. Multiple—See Attacf	ied	#5H
2. Name of Operator CHEVRON USA INCORPORA	Contact: LAURA			9. API Well No. 36 Multiple See Atta		15-45/19
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		ne No. (include area code) 32-687-7665		10. Field and Pool or Ex PURPLE SAGE-V		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish, Sta	ate	
MultipleSee Attached			1	EDDY COUNTY, NM		
Carlsb	ad Field Office					· · · · · · · · · · · · · · · ·
12. CHECK THE	PPPRATETOSIA) TO IND	ICATE NATURE OF	F NOTICE,	REPORT, OR OTHE	ER DA	ATA
TYPE OF SUBMISSION		TYPE OF	ACTION			
Notice of Intent	☐ Acidize ☐	Deepen	☐ Producti	ion (Start/Resume)	o Wa	ater Shut-Off
_	☐ Alter Casing	Hydraulic Fracturing	☐ Reclama	ation		ell Integrity
☐ Subsequent Report	☐ Casing Repair	New Construction	☐ Recomp	lete	Other	her ge to Original A
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Tempor	arily Abandon	PD	inge to Original A
	☐ Convert to Injection ☐) Plug Back	☐ Water D	Pisposal		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for five are requesting a variance	ally or recomplete horizontally, give subsite will be performed or provide the Bond operations. If the operation results in a repart of the operation results in a repart of the original APD to use the spic continue drilling operations 10/23 owing wells on this pad: 015-45115 015-45117 015-45118 015-45119	urface locations and measur No. on file with BLM/BIA nultiple completion or reco- iter all requirements, including udder rig to pre-set sur	red and true ve Required sub impletion in a r ing reclamation face casing	rtical depths of all pertiner isequent reports must be fi new interval, a Form 3160- n, have been completed an	nt mark iled with 4 must d the op	ers and zones. hin 30 days be filed once perator has
14. I hereby certify that the foregoing is	true and correct.	T				
Con	Electronic Submission #432040 v For CHEVRON USA INCO nmitted to AFMSS for processing b	ORPORATED, sent to t	he Carlsbad	-		
Name (Printed/Typed) LAURA BI		·	TTING SPE	•		
· · · · · · · · · · · · · · · · · · ·	4					
Signature (Electronic S	Submission)	Date 08/21/20	018			
	THIS SPACE FOR FED	ERAL OR STATE	OFFICE U	SE		
_Approved_By_ZOTA_STEVENS	. 	TitlePETROLE	UM ENGIN	EER		Date 09/10/2018
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the subject le		d			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime for statements or representations as to any magnetic statements.		willfully to m	ake to any department or a	gency o	of the United

Additional data for EC transaction #432040 that would not fit on the form

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM100549	NMNM100549	HH SO 8 5 FED 003 1H	30-015-45115-00-X1	Sec 17 T265 32.048035 N
NMNM100549	NMNM100549	HH SO 8 5 FED 003 2H	30-015-45116-00-X1	Sec 17 T265 32.048103 N
NMNM100549	NMNM100549	HH SO 8 5 FED 003 3H	30-015-45117-00-X1	Sec 17 T265 32.048172 N
NMNM100549	NMNM100549	HH SO 8 5 FED 003 4H	30-015-45118-00-X1	Sec 17 T265 32.048241 N
NMNM100549	NMNM100549	HH SO 8 5 FED 003 5H	30-015-45119-00-X1	Sec 17 T26:
NMNM100549	NMNM100549	HH SO 8 5 FED 003 6H	30-015-45120-00-X1	Sec 17 T26

Location
Sec 17 T26S R27E NENW 629FNL 2308FWL 32.048035 N Lat, 104.213425 W Lon Sec 17 T26S R27E NENW 604FNL 2308FWL 32.048103 N Lat, 104.213425 W Lon Sec 17 T26S R27E NENW 579FNL 2309FWL 32.048172 N Lat, 104.213425 W Lon Sec 17 T26S R27E NENW 554FNL 2309FWL 32.048241 N Lat, 104.213425 W Lon Sec 17 T26S R27E NENW 554FNL 2309FWL 32.048241 N Lat, 104.213425 W Lon Sec 17 T26S R27E NENW 529FNL 2310FWL 32.048309 N Lat, 104.213417 W Lon Sec 17 T26S R27E NENW 504FNL 2310FWL 32.048378 N Lat, 104.213417 W Lon

32. Additional remarks, continued

See attachments for detailed program and rig layout.

Chevron U.S.A. Inc. (CUSA) SUNDRY ATTACHMENT: SPUDDER RIG

DATA OPERATOR NAME: Chevron U.S.A. Inc.

1. SUMMARY OF REQUEST:

CUSA respectfully requests approval for the following operations for the surface hole in the drill plan:


1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
 - a. After drilling the surface hole section, the spudder rig will run casing and cement following all the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
 - b. The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and then tested offline after the WOC time has been reached.
- 3. An abandonment cap at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on one wing-valve.
 - a. A means for intervention will be maintained while the drilling rig is not over the well.
- 4. Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- 6. Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
 - a. The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
 - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. CUSA will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- 8. Once the rig is removed, CUSA will secure the wellhead area by placing a guard rail around the cellar area.

: [, , , ,				1 1 5		1	
	Pad Name	Well-No.	Surface Rig Start	Surface Rig Finish	Surface Rig Duration (Days)	Larger Dev Rig Spud Date	Well Status	Days Between Rigs	APD Approved	APD Expires	Lease Status
	SD EA 18 19 FED P14	12H – 15H	5/4/2018	5/12/2018	.8	3/25/2019	SI	317	10/11/2017	10/11/2019	Held by production by existing producing wells
	SD EA 18 19 FED COM P13	8H – 11H	5/12/2018	5/20/2018	8	2/22/2019	SI	278	9/28/2017	9/28/2019	Held by production by existing producing wells
	SD EA 29 32 FED COM P10	17H – 20H	5/20/2018	5/28/2018	8	10/4/2018	SI	129	2/8/2018	2/8/2020	Held by production by existing producing wells
Ī	SD EA 29 32 FED COM P11	13H – 16H	5/28/2018	6/5/2018	. 8	11/6/2018	SI	154	12/20/2017	12/20/2019	Held by production by existing producing wells

Surface Rig Layout



PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: Chevron USA Incorporated

LEASE NO.: | NMNM118108

WELL NAME & NO.: | HH SO 8 5 Fed 003 Multi-Wells Pad

SURFACE HOLE FOOTAGE: BOTTOM HOLE FOOTAGE

LOCATION: | Section 17, T.26 S., R.27 E., NMPM

COUNTY: | Eddy County, New Mexico

All COAs still apply expect the following:

1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.

- a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
- b. Operator proposes to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.

ZS 091018