Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Artesia SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC028731A 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM111789X		
1. Type of Well    Ø Oil Well Other				8. Well Name and No. DODD FEDERAL UNIT 62		
2. Name of Operator Contact: DANA KING COG OPERATING LLC E-Mail: dking@concho.com				9. API Well No. 30-015-26282-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-818-2267	de) 10. Field and Pool or Ex DODD-GLORIET			0	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 14 T17S R29E SESW 33			EDDY COUNTY, NM			
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, R	EPORT, OR OTH	ER DATA	<u></u>
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	UWater Shut-C	Off
-	Alter Casing	Hydraulic Fracturing	🗖 Reclamatio	on	🗖 Well Integrity	у
Subsequent Report	Casing Repair	New Construction	Recomplet	e	Other	
Final Abandonment Notice	Change Plans	🛛 Plug and Abandon	Temporari	-		
	Convert to Injection	Plug Back	U Water Disj	posal		
13. Describe Proposed or Completed Opt If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re- bandonment Notices must be fil-	give subsurface locations and measure the Bond No. on file with BLM/BIA sults in a multiple completion or reco	red and true vertic Required subse mpletion in a new	cal depths of all pertin quent reports must be (interval, a Form 316	ent markers and zone filed within 30 days 0-4 must be filed one	es.
08/14/18 MIRU plugging equipment. Dug out cellar, ND well head. NU BOP. 08/15/18 Set 5 1/2" CIBP @ 3790'. Spotted 25 sx class C cmt @ 3790-3538'. Set 5 1/2" CIBP @ 2698'. Circulated hole w/ MLE. Pressure tested csg, held 500 psi/ Spotted 25 sx class C cmt @ 2698-2444'.						URE
<u>Spotted 25 sx class</u> C cmt @ 1 08/16/18)Tagged plug @ 783' Rigged down & moved off. 08/22/18 Moved in backhoe a Dry Hole Marker". Backfilled	940-687'. WOC. . ND BOP. Spotted 65 sx nd welder. Dug out cellar.	class C cmt @ 455' & circulat	ed to surface. "Above Grour		_	
14. I hereby certify that the foregoing is	#Electronic Submission For COG O	432774 verified by the BLM Wel PERATING LLC, sent to the Ca ssing by DEBDRAH MCKINNEY	Irisbad		TESIA O.C.D.	
Name (Printed/Typed) DANA KII	Title SUBMIT	Title SUBMITTING CONTACT				
Signature (Electronic S	Date 08/24/20	<sub>018</sub>	ACCEPTED I	OR RECOR	2D	
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FC	OR FEDERAL OR STATE	OFFICE USE	:		
Approved By	<u> </u>	Title		AUG 2	7 201 <b>8</b> Date	T
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	not warrant or					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any person knowingly and to any matter within its jurisdiction.	willfully to make	to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	SED ** BLM REVISED	) ** BLM REVISED ** BLM	REVISED *	* BLM REVISEI	) **	



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## **Reclamation Objectives and Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Appropriate time for submittal would be when filing the Vell Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

1