In Reply Refer to 3162.4 (P0220)

## United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Carlsbad Field Office - 620 E. Greene Carlsbad, New Mexico 88220-6292

HOBBS OCO.blm.gov

OCT 1 0 2018

RECEIVED

September 24, 2018

Cimarex Energy Corporation 202 S. Cheyenne Ave, Suite 1000 Tulsa, OK 74103

Carlsbad Field Office

Gentlemen:

HODDS enced well has expired because drilling has not Your Application for Permit to Drill (APD) for the below referenced well commenced per Onshore Order #1:

LEASE	WELL NAME & NUMBER	API#	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
NM96835	LIBERTY 24 FED COM – 3H	3001542261	03/24/2016	03/24/2018

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the \$9,790 application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely,

Assistant Field Manager, Lands and Minerals

Whitlork &

RECEIVED

OCT 1.7 2018

DISTRICT II-ARTESIA O.C.D.

Page 1 of 1