## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

6. If Indian; Allottee or Tribe Name

NMNM067896

abandoned well. Use form 3160-3 (APD) for such proposals.					,					
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. SHUGART WEST 19 6						
Name of Operator Contact: MELISSA SZUDERA     MARATHON OIL PERMIAN LLC E-Mail: mszudera@marathonoil.com				9. API Well No. 30-015-30689-00-S1						
3a. Address 5555 SAN FELIPE ST HOUSTON, TX 77056	one No. (include area code) 13-296-3179		10. Field and Pool or Exploratory Area SHUGART							
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State						
Sec 19 T18S R31E SWNE 1980FNL 2310FEL				ÉDDY COUNTY, NM						
12 CHECK THE AF	PPROPRIATE BOX(ES) TO IND	DICATE NATURE OF	NOTICE	RFPC	ORT OR OTH	FR DATA				
TYPE OF SUBMISSION	TROTALITE BOX(ES) TO INE	TYPE OF		, c				—		
☐ Notice of Intent	☐ Acidize ☐ Deepen		_	-	art/Resume)	· —				
Subsequent Report     ■     Subsequent Report     Subsequent Report				Reclamation		☐ Well Integrity				
	_ ~ , _	New Construction Recor		orarily Abandon		☐ Other				
☐ Final Abandonment Notice	-	Plug and Abandon Plug Back	☐ Water D	-						
3/6/2019 - Set CIBP @ 7650'. Test CIBP and notified BLM, TIH with tbg tag up on plug @ 7650'.  3/7/2019 - Pump 35sx cmt. POOH. TIH run 3000ft tbg. Move up hole to 4500'.  3/8/2019 - POOH to 5403'. Set packer and perforate @ 5850'. LD wireline. Pump 80sx TOC @ 5634'. Set pkr @ 4146' and shoot perf @ 4650'. Attempt to aquz but pressured up. Notified BLM.  3/9/2019 - Pump 30sx cmt. WOC. TIH @ 4525'. Got approval from BLM to continue. POOH and LD tbg to 28600'. Perf @ 2860'. Pump 50sx. WOC.  3/10/2019 - TIH and tag @ 2745'. Perf @ 2650'. POOH. Pump 59sx cmt and WOC. TIH to tag up cmt @						MATION PROCEDURE ATTACHED  CLAMATION E 9-11-191  RECEIVED				
14. I hereby certify that the foregoing is	s true and correct.		<del></del>			ADD & E 20	110			
Electronic Submission #458485 verified by the BLM Well Information For MARATHON OIL PERMIAN LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 03/19/2019  Name (Printed/Typed) MELISSA SZUDERA Title REGULATORY CO				(19PP	0991SE)	APR 2 5 20 Ctii-Artes		),D.		
Signature (Electronic S	Submission)	Date 03/19/20	119	ACÇ	EPTED F	OR RECC	RD	L		
THIS SPACE FOR FEDERAL OR STATE OFFICE				SE						
Approved By		Title			APR 2	2 2 <b>019</b> Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				BU	REAU OF LANE CARLSBAD FI	MANAGEMEN	11			
Title 18 II S.C. Section 1001 and Title 43	U.S.C. Section 1212 make it a prime for	any nercon knowingly and	willfully to	ike to o			utod.			



Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.bhn.gov/nin



In Reply Refer To: 1310

## Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure) Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD. Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filling the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filling the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Hom Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612