# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

		January	
5.	Lease Serial No. NMNM9818		

SUI	NDRY N	OTICES A	AND REP	ORTS C	N WELLS	3
Do not	use this	form for p	roposals	to drill oi	r to re-ente	r an
bandoi	ned well.	Use form	3160-3 (A	PD) for s	such propo	sals.

6. If Indian, Allottee or Tribe Name

abandoned wei	II. Use form 3160-3 (APD	)) for such pi	oposals.		o. If findian, finotice	or tribe runne		
SUBMIT IN TRIPLICATE - Other instructions on page 2				· · · · · · · · · · · · · · · · · · ·	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. GOVERNMENT S 7			
Name of Operator					9. API Well No. 30-015-28504-00-S1			
3a. Address		3b. Phone No. Ph: 432-685			10. Field and Pool or OLD MILLMAN	Exploratory A	rea	
HOUSTON, TX 77210  4. Location of Well (Footage, Sec., T	R M or Survey Description)		- RECEIVE	D)	11. County or Parish,	State		
··· -	., ic., ii., or burvey Description	•						
Sec 3 T20S R28E SESE			JUL 23	2019	EDDY COUNT	Y, NM		
12. CHECK THE AR	PPROPRIATE BOX(ES)	TO INDI	ARIOWANIE	SMOICE	, REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Produc	tion (Start/Resume)	☐ Water	Shut-Off	
_ '	☐ Alter Casing	☐ Hydr	aulic Fracturing	□ Reclam	nation	□ Well In	ntegrity	
Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recom	plete	Other		
☐ Final Abandonment Notice	□ Change Plans	🛛 Plug	and Abandon '	☐ Tempo	rarily Abandon			
	☐ Convert to Injection	Plug	Back	☐ Water 1	Disposal			
following completion of the involved testing has been completed. Final At determined that the site is ready for final 7/8/19 - MIRU PU, ND WH, NI 7/9/19 - RIH w/ tbg & tag cmt CaCl2, PUH to 3738', WOC.  7/10/19 - Work stuck tbg, RIH Notified BLM. RIH w/ bit, tag 7/11/19 - Continue to drill out tag and to continue. Start to Final RIH w/ DOOH w	wandonment Notices must be file in all inspection.  U BOP  @ 5952', circ hole w/ 10#  & tag cmt @ 3443' (high), up @ 3443', circ clean, stacemt, fell thru @ 3450', RIFPOOH w/ bit, circ hole w/ 1 w/ bit. RIH & set pkr @ 29	MLF, PUH to start to POO art to drill out 0  ### Accepte  ### Accepte	d for record.  4550', M&P 35s  H, bottom 6 jts cmt, got to 3527  4419' notified due to weather	MMOCD  SX CI C cmt  packed w/ c  ", SION.  BLM, appr	w/ 2%  cmt.  RECLA  W/ 2%	AMATION PE ATTACHE	OT HAS ROCEDURE D ATION	
14. I hereby certify that the foregoing is  Commi  Name (Printed/Typed) DAVID ST	Electronic Submission #4 For OXY USA WT itted to AFMSS for process	P LIMITED P†I	NRSHIP, sent to AH MCKINNEY o	the Carlsba on 07/18/201	id .			
Signature (Electronic S	Submission)		Date 07/18/2		CCEPTED FO	R RECO	RD	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	ISE JUL 19	2019		
Approved By		!	Title		Drewinney	ANAGEMEN		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t		Office	L	CARLSBAD FIEL	D OFFICE			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to m	ake to any department o	r agency of the	United	

## - Additional data for EC transaction #474144 that would not fit on the form

## 32. Additional remarks, continued

pump & circ hole clean w/ 197bbl gel brine, PUH & set pkr @ 77', SION.

7/15/19 - Notify BLM, appr circ cmt to surf. Pkr set @ 77', EIR @ 1-1.5bpm @ 700-800#, w/ full circ out 5-1/2" X 8-5/8" annulus, M&P 734sx CI C cmt followed by 66sx CL C cmt w/ 2% CaCl2. Circ 180bbl gel brine out of 5-1/2" X 8-5/8" annulus and lost circ, disp cmt to 500', SI, WOC and notified BLM and appr to tag cmt and perf above TQC.

7/16/19) RIH & tag cmt @ 530', notifified BLM, PUH & perf @ 460', attempt to EIR, pressure up to 1000# with no rate or loss. BLM appr spotting cmt plug. POOH w/ pkr, RIH w/ tbg to 512', M&P 130sx CL C cmt, circ to surf. ND BOP, top off 5-1/2" csg & 5-1/2" X 8-5/8" annulus w/ cmt. RDPU.



## United States Department of the Interior

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

### **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612