Form 3160-5 (June 2015)

Sec 18 T17S R28E SESE 330FSL 990FEL

EDDY COUNTY, NM

DEPARTMEN'	ED STATES T OF THE INTERIOR AND MANAGEMENT OCD Artes	Expires: January 31, 2018
SUNDRY NOTICES A Do not use this form for p	5. Lease Serial No. NMLC045818B	
abandoned well. Use form	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well		8. Well Name and No. HASTIE 3
Name of Operator EOG Y RESOURCES INC E-Ma	Contact: TINA HUERTA ail: tina_huerta@eogresources.com	9. API Well No. 30-015-01416-00-S1
3a. Address 104 S 4TH STREET ARTESIA, NM 88210	3b. Phone No. (include area code) Ph: 575-748-4168	10. Field and Pool or Exploratory Area EMPIRE-ABO
4. Location of Well (Footage, Sec., T., R., M., or Sur	11. County or Parish, State	

CHECK THE ADDRODDIATE DOV(ES) TO DIDICATE NATION OF NOTICE DEPORT OF OWNER DATE

12. CHECK THE AFFROFRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION .	TYPE OF ACTION							
□ Notice of Intent☑ Subsequent Report□ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity □ Other				

Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. **RECLAMATION PROCEDURE**

6/25/19 - MIRU and POOH production equipment. NU BOP. 6/27/19 - Pumped a 35 sx Class C cement plug from 518 ft - 320 ft calc TOC. WOC to tag. Tagged TOC at 358 ft. Witnessed by Joe Salcido with Carlsbad BLM. Loaded casing with 20 bbls fresh water with

partial returns to surface. Unable to pressure test due to casing restrictions and parted 7 inch casing. Perforate 7 inch casing at 350 ft. Pumped 86 sx Class C cement from 358 ft and circulated up to surface. Topped off with cement. Cement level showed slow drop from surface. Per Carlsbad BI M will tag plug and top off casing.
6/28/19 Tagged TOC at 40 ft. Pumped 10 sx Class C cement from 40 ft up to surface. Topped off

with cement. 7/30/19 - Cut off wellhead and installed dry hole marker. Cut off anchors and cleaned location.

WELL IS PLUGGED AND ABANDONED. MOCD

ATTACHED RECLAMATION

DUE 12-28-19

NM OIL CONSERVATION ARTESIA DISTRICT

AUG 2 1 2019

14. I hereby certify that u	Electronic Submission #476049 verifie For EOG Y RESOURCES Committed to AFMSS for processing by DEBC	NC, se	ent to the Carlsbad	•			EIVED		
Name (Printed/Typed)	TINA HUERTA	Title	REGULATORY	SPEC	ALSTER	LOC	DEC	ממנ	l
				AU	PIPIEL	TUT	KEU	טאנ	
Signature	(Electronic Submission)	Date	07/31/2019						
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FOR FEDERA	L OR	STATE OFFICE	USE	JUL	3 1	20 19		Ī.
Approved By		Title		PI	Makin DEALL OF L		ANIA CERAL	NT	
certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease licant to conduct operations thereon	Offic	ρ .		CARLSBA	D FIELD	OFFICE		

Accepted for record

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.







United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612