Submit 1 Copy To Appropriate District Office District I – (575) 393-6161  State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
1625 N. Franch Dr., Hobbs, NM 99240	WELL API NO.
District II - (575) 748-1283 SEP 272010 SERVATION DIVISION	30-015-29445
District III = (505) 334-6178 1990 1990 1990 1990 1990 1990 1990 199	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NMSIBIRICTI APTESIA Santa Fe, NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Rosens
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
OXY USA Inc.	16696
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Hoka Glorieta Yeso
4. Well Location	
Unit Letter H: 2310 feet from the North line and 3	
Section 73 Township US Range 26E	NMPM County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	The state of the second
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
nronosed completion or recompletion	ved for plugging of well bore only.
Liabili	ty under bond is retained pending receipt  33 (Subsequent Report of Well Plugging)
	may be found at OCD Web Page under
9/18/19 – Continue to POOH w/ rods & pump. NDWH, NU BOP, rel TAC, st	www.cmnrd.state.nm.us/ocd.
5, 15, 15 Continue to Cont wy rous & paints. No Will, No Bor, Tel TAC, Start to FOOT wy tog.	
9/19/19 – Continue to POOH w/ tbg. RIH w/ gauge ring & tag up @ 2875', POOH. RIH & set CIBP @ 2856', POOH.	
RIH w/ tbg & tag CIBP @ 2856', notified NMOCD, circ hole w/ 10# MLF, M&P 25sx CI C cmt, PUH.	
, 6 6 2 22 7 1 2 2 2 2 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2	233x Cr C CMC, 1 O11.
9/20/19 – RIH & tag cmt @ 2492', notified NMOCD. PUH to 1120', M&P 25sx CL C cmt, PUH, WOC. RIH & tag cmt	
@ 780', notified NMOCD, POOH. ND BOP, RIH to 310', M&P 35sx CI C cmt,	circ to surface, POOH. RDPU.
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.
SIGNATURE TITLE Sr. Regulatory Advisor	DATE 9 24 (19
Type or print name David Stewart E-mail address: david_stewart@c	oxy.com PHONE: <u>432-685-5717</u>
For State Use Only	
APPROVED BY: ATTOM TITLE STATE ME	DATE_/0/1//9
Conditions of Approval (if any):	