

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6100
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 342-6788
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO. 30-015-04701
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stovall Wood
8. Well Number 2
9. OGRID Number 258350
10. Pool name or Wildcat Barber (Yates)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
VANGUARD OPERATING, LLC

3. Address of Operator
5847 SAN FELIPE, STE. 3000, HOUSTON, TEXAS, 77057

4. Well Location
Unit Letter F : 2,310 feet from the SOUTH line and 2,310 feet from the EAST line
Section 20 Township 20S Range 30E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3207' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Vanguard Operating, LLC is requesting to temporarily abandon (TA) this well to evaluate any future uphole recompletion opportunities. TA procedure is as follows:

1. MIRU WS. LD production equipment.
2. RU WL. Set 6-5/8" CIBP @ 1,200' (Open hole completion from 1,252-1,473'). Cap w/ 35' of cement via bailer.
3. Contact NMOCD prior to running MIT test. Fill casing with treated water and pressure test to 500 psig for at least 30 minutes. Record pressure chart.
4. RD WS & WL.
5. File subsequent C-103 and MIT chart.

Temporary Abandoned Status approved
w/ 12-1-2021

TA status may be granted after a successful MIT test is performed. Contact the OCD to schedule the test so it may be witnessed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Zimmermann TITLE Operations Engineer DATE 11/20/2019

Type or print name Kyle Zimmermann E-mail address: kzimmerman@vnrenergy.com PHONE: 432-202-0145

For State Use Only

APPROVED BY: Dustin TITLE Compliance Officer DATE 12-5-2019
Conditions of Approval (if any):

LEASE/WELL: STOVALL-WOOD FEE No. 2
LOCATION 2,310' FSL & 2,310' FEL
UT F, SEC 20, T 20S, R 30E
CO/ST: EDDY COUNTY, NM
API NO. 30-015-04701
FIELD: BARBER (YATES)

GR 3207'
SPUDDED 07/18/38
COMPLETED 08/27/38

LAT 32.5597725
LONG -103.9954605

10" HOLE

8 5/8" 28 PPF
W/50X CMT &
35 SX MUD

394' 8/1/1938

TOC CALC --801'

8" HOLE

7" 17 PPF (AKA 6 5/8")
W/50 SX CMT
75 SX MUD

1,252' 8/11/1938

1,415' TD 8/27/1938

1,473' DDTD 01/26/1941

