Form 3160-3 (June 2015) RECEIVED	REC	EIVED		FORM A OMB No Expires: Ja	APPROVED 0. 1004-0137 nuary 31, 2018
MAR DEPARTMENT OF THE I	NTERIOR			5. Lease Serial No. NMNM013996	
EMARTLEAPIEN FOR PERMIT TO D	RILLOR	HEENTER CC	A N	6. If Indian, Allotee	or Tribe Name
1a. Type of work: DRILL 1b. Type of Well:	EENTER	an a		7. If Unit or CA Agr 8. Lease Name and V	eement, Name and No.
1c. Type of Completion: Hydraulic Fracturing Si	ngle Zone	✔ Multiple Zone		RADIUS CC 6-7 F	
2. Name of Operator OXY USA INCORPORATED				9. API Well No. 30-0/	<u>/ 30 /</u> 15-46826
3a. Address 5 Greenway Plaza, Suite 110, Houston, TX 77046	3b. Phone N (713) 366-	No. <i>(include area cod</i> 5716	e)	10. Field and Pool, of PURPLE SAGE W	OLFCAMP/PURPLE S
 Location of Well (Report location clearly and in accordance w At surface LOT 3 / 170 FNL / 1350 FWL / LAT 32.2538 At proposed prod. zone SESW / 20 FSL / 2300 FWL / LA 	vith any State 3181 / LONC AT 32.22505	e requirements.*) G -104.0279805 518 / LONG -104.02	48277	11. Sec., T. R. M. or SEC 6/T24S/R29E	Blk. and Survey or Area /NMP
14. Distance in miles and direction from nearest town or post offi 8 miles	ice*			12. County or Parish EDDY	n 13. State NM
15. Distance from proposed* location to nearest property or lease line, ft. (Also to nearest drig, unit line, if any)	16. No of a 199.71	cres in lease	17. Spa	acing Unit dedicated to the	his well
 18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft. 	19. Proposo 10715 feet	ed Depth t / 21644 feet	20. BL FED: I	M/BIA Bond No. in file ESB000226	
21. Elevations (Show whether DF, KDB, RT, GL, etc.) 2959 feet	22. Approx 07/21/2020	imate date work will)	start*	23. Estimated durati 20 days	on
The following, completed in accordance with the requirements o (as applicable)	24. Atta f Onshore Oi	chments l and Gas Order No. 1	I, and th	e Hydraulic Fracturing r	ule per 43 CFR 3162.3-3
 Well plat certified by a registered surveyor. A Drilling Plan. A Surface Use Plan (if the location is on National Forest Syste SUPO must be filed with the appropriate Forest Service Office 	m Lands, the	 Bond to cover the Item 20 above). Operator certification Such other site space. BLM. 	e operat cation. pecific in	ions unless covered by an formation and/or plans as	n existing bond on file (see may be requested by the
25. Signature (Electronic Submission)	Name David	e <i>(Printed/Typed)</i> J Stewart / Ph: (713	3) 366 <mark>-</mark> 5	5716	Date 08/14/2019
Title Sr. Regulatory Advisor					
Approved by <i>(Signature)</i> (Electronic Submission)	Name Cody	e (Printed/Typed) Layton / Ph: (575)	234-59	59	Date 03/04/2020
Title Assistant Field Manager Lands & Minerals Application approval does not warrant or certify that the applicar applicant to conduct operations thereon. Conditions of approval, if any, are attached.	Offic Carls at holds legal	e bad Field Office or equitable title to the tot	hose rigi	nts in the subject lease w	hich would entitle the
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, r of the United States any false, fictitious or fraudulent statements	nake it a crim or representa	e for any person kno tions as to any matter	wingly a within	nd willfully to make to a its jurisdiction.	any department or agency
د به بو ب ت ب ب		TH CONDIT	TON	4.0-	

(Continued on page 2)
----------------------	---

Approval Date: 03/04/2020

Aľ

*(Instructions on page 2) NSL Required

٢

INSTRUCTIONS

GENERAL: This form is designed for submitting proposals to perform certain well operations, as indicated on Federal and Indian lands and leases for action by appropriate Federal agencies, pursuant to applicable Federal laws and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from local Federal offices.

ITEM I: If the proposal is to redrill to the same reservoir at a different subsurface location or to a new reservoir, use this form with appropriate notations. Consult applicable Federal regulations concerning subsequent work proposals or reports on the well.

ITEM 4: Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local Federal offices for specific instructions.

ITEM 14: Needed only when location of well cannot readily be found by road from the land or lease description. A plat, or plats, separate or on the reverse side, showing the roads to, and the surveyed location of, the wen, and any other required information, should be furnished when required by Federal agency offices.

ITEMS 15 AND 18: If well is to be, or has been directionany drilled, give distances for subsurface location of hole in any present or objective productive zone.

ITEM 22: Consult applicable Federal regulations, or appropriate officials, concerning approval of the proposal before operations are started.

ITEM 24: If the proposal will involve hydraulic fracturing operations, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The Privacy Act of 1974 and regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 25 U.S.C. 396; 43 CFR 3160

PRINCIPAL PURPOSES: The information will be used to: (1) process and evaluate your application for a permit to drill a new oil, gas, or service wen or to reenter a plugged and abandoned well; and (2) document, for administrative use, information for the management, disposal and use of National Resource Lands and resources including (a) analyzing your proposal to discover and extract the Federal or Indian resources encountered; (b) reviewing procedures and equipment and the projected impact on the land involved; and (c) evaluating the effects of the proposed operation on the surface and subsurface water and other environmental impacts.

ROUTINE USE: Information from the record and/or the record win be transferred to appropriate Federal, State, and local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecution, in connection with congressional inquiries and for regulatory responsibilities.

EFFECT OF NOT PROVIDING INFORMATION: Filing of this application and disclosure of the information is mandatory only if you elect to initiate a drilling or reentry operation on an oil and gas lease.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM conects this information to anow evaluation of the technical, safety, and environmental factors involved with drilling for oil and/or gas on Federal and Indian oil and gas leases. This information will be used to analyze and approve applications. Response to this request is mandatory only if the operator elects to initiate drilling or reentry operations on an oil and gas lease. The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Conection Clearance Officer (WO-630), 1849 C Street, N.W., Mail Stop 401 LS, Washington, D.C. 20240.

Additional Operator Remarks

Location of Well

0. SHL: LOT 3 / 170 FNL / 1350 FWL / TWSP: 24S / RANGE: 29E / SECTION: 6 / LAT: 32 2538181 / LONG: -104.0279805 (TVD: 0 feet, MD: 0 feet) PPP: LOT 3 / 100 FNL / 2300 FWL / TWSP: 24S / RANGE: 29E / SECTION: 6 / LAT: 32.2539842 / LONG: -104.0249077 (TVD: 10671 feet, MD: 11118 feet) PPP: NESW / 2660 FSL / 2300 FWL / TWSP: 24S / RANGE: 29E / SECTION: 6 / LAT: 32.246938 / LONG: -104.024889 (TVD: 10682 feet, MD: 13651 feet) PPP: NENW / 1 FNL / 2300 FWL / TWSP: 24S / RANGE: 29E / SECTION: 7 / LAT: 32.239626 / LONG: -104.024868 (TVD: 10693 feet, MD: 16291 feet) BHL: SESW / 20 FSL / 2300 FWL / TWSP: 24S / RANGE: 29E / SECTION: 7 / LAT: 32.2250518 / LONG: -104.0248277 (TVD: 10715 feet, MD: 21644 feet)

BLM Point of Contact

Name: Tenille Ortiz Title: Legal Instruments Examiner Phone: (575) 234-2224 Email: tortiz@blm.gov

Approval Date: 03/04/2020

(Form 3160-3, page 3)

Review and Appeal Rights

A person contesting a decision shall request a State Director review. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Approval Date: 03/04/2020

(Form 3160-3, page 4)

PECOS DISTRICT SURFACE USE CONDITIONS OF APPROVAL

WELL NAME & NO.: 51H – Radius CC 6-7 Federal COM 51H SURFACE HOLE FOOTAGE: 170'/N & 1285'/W BOTTOM HOLE FOOTAGE 20'/S & 1000'/W LOCATION: Section 6 T.24 S., R.29E., NMP

WELL NAME & NO.: RADIUS CC 6-7 FEDERAL COM / 52H SURFACE HOLE FOOTAGE: 170'/N & 1350'/W BOTTOM HOLE FOOTAGE 20'/S & 2300'/W LOCATION: Section 6, T.24 S., R.29 E., NMPM

WELL NAME & NO.: DEPTH CC 6-7 FEDERAL COM 43H SURFACE HOLE FOOTAGE: 25'/S & 1074'/E BOTTOM HOLE FOOTAGE 20'/S & 2260'/E LOCATION: Section 23, T.29 S., R.29 E., NMP

WELL NAME & NO.: DEPTH CC 6-7 FEDERAL COM 44H SURFACE HOLE FOOTAGE: 25'/S & 1004'/E BOTTOM HOLE FOOTAGE 20'/S & 940'/E LOCATION: Section 23, T.29 S., R.31 E., NMP

WELL NAME & NO.: 42H – Depth cc 6-7 Federal COM SURFACE HOLE FOOTAGE: 170'/N & 1320'/W BOTTOM HOLE FOOTAGE 20'/N & 1700'/W LOCATION: SECTION 6, T24S, R29E, NMPM

WELL NAME & NO.: 41H – Depth cc 6-7 Federal COM SURFACE HOLE FOOTAGE: 170'/N & 1250'/W BOTTOM HOLE FOOTAGE 20'/N& 330'/W LOCATION: SECTION 6, T24S, R29E, NMPM

TABLE OF CONTENTS

Standard Conditions of Approval (COA) apply to this APD. If any deviations to these standards exist or special COAs are required, the section with the deviation or requirement will be checked below.

- General Provisions
- **Permit Expiration**
- Archaeology, Paleontology, and Historical Sites
- **Noxious Weeds**
- 🔀 Special Requirements
 - Fee Fee Fed
 - Cave/Karst
 - VRM
 - Cultural
 - Construction
 - Notification

Page 1 of 24

Topsoil
Closed Loop System
Federal Mineral Material Pits
Well Pads
Roads
Road Section Diagram
Production (Post Drilling)
Well Structures & Facilities
Pipelines
Electric Lines
Interim Reclamation
Final Abandonment & Reclamation

Page 2 of 24

I. GENERAL PROVISIONS

The approval of the Application For Permit To Drill (APD) is in compliance with all applicable laws and regulations: 43 Code of Federal Regulations 3160, the lease terms, Onshore Oil and Gas Orders, Notices To Lessees, New Mexico Oil Conservation Division (NMOCD) Rules, National Historical Preservation Act As Amended, and instructions and orders of the Authorized Officer. Any request for a variance shall be submitted to the Authorized Officer on Form 3160-5, Sundry Notices and Report on Wells.

II. PERMIT EXPIRATION

If the permit terminates prior to drilling and drilling cannot be commenced within 60 days after expiration, an operator is required to submit Form 3160-5, Sundry Notices and Reports on Wells, requesting surface reclamation requirements for any surface disturbance. However, if the operator will be able to initiate drilling within 60 days after the expiration of the permit, the operator must have set the conductor pipe in order to allow for an extension of 60 days beyond the expiration date of the APD. (Filing of a Sundry Notice is required for this 60 day extension.)

III. ARCHAEOLOGICAL, PALEONTOLOGY & HISTORICAL SITES

Any cultural and/or paleontological resource discovered by the operator or by any person working on the operator's behalf shall immediately report such findings to the Authorized Officer. The operator is fully accountable for the actions of their contractors and subcontractors. The operator shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the Authorized Officer. An evaluation of the discovery shall be made by the Authorized Officer to determine the appropriate actions that shall be required to prevent the loss of significant cultural or scientific values of the discovery. The operator shall be held responsible for the cost of the proper mitigation measures that the Authorized Officer assesses after consultation with the operator on the evaluation and decisions of the discovery. Any unauthorized collection or disturbance of cultural or paleontological resources may result in a shutdown order by the Authorized Officer.

IV. NOXIOUS WEEDS

The operator shall be held responsible if noxious weeds become established within the areas of operations. Weed control shall be required on the disturbed land where noxious weeds exist, which includes the roads, pads, associated pipeline corridor, and adjacent land affected by the establishment of weeds due to this action. The operator shall consult with the Authorized Officer for acceptable weed control methods, which include following EPA and BLM requirements and policies.

Page 3 of 24

V. SPECIAL REQUIREMENT(S)

Fee Fee Fed

Cave/Karst Mitigation Measures for project portions occurring on BLM Surface or intersecting Federal Minerals:

The following stipulations will be applied to minimize impacts during construction, drilling and production:

Construction:

In the advent that any underground voids are opened up during construction activities, construction activities will be halted and the BLM will be notified immediately.

No Blasting:

No blasting will be utilized for pad construction. The pad will be constructed and leveled by adding the necessary fill and caliche.

Pad Berming:

- The entire perimeter of the well pad will be bermed to prevent oil, salt, and other chemical contaminants from leaving the well pad.
- The compacted berm shall be constructed at a minimum of 12 inches high with impermeable mineral material (e.g., caliche).
- No water flow from the uphill side(s) of the pad shall be allowed to enter the well pad.
- The topsoil stockpile shall be located outside the bermed well pad.
- Topsoil, either from the well pad or surrounding area, shall not be used to construct the berm.
- No storm drains, tubing or openings shall be placed in the berm.
- If fluid collects within the bermed area, the fluid must be vacuumed into a safe container and disposed of properly at a state approved facility.
- The integrity of the berm shall be maintained around the surfaced pad throughout the life of the well and around the downsized pad after interim reclamation has been completed.
- Any access road entering the well pad shall be constructed so that the integrity of the berm height surrounding the well pad is not compromised. (Any access road crossing the berm cannot be lower than the berm height.)
- Following a rain event, all fluids will vacuumed off of the pad and hauled off-site and disposed at a proper disposal facility.

Tank Battery Liners and Berms:

Tank battery locations and all facilities will be lined and bermed. A 20 mil permanent liner will be installed with a 4 oz. felt backing, or equivalent, to prevent tears or punctures. Tank battery berms must be large enough to contain 1 ¹/₂ times the content of the largest tank.

Leak Detection System:

Page 4 of 24

A method of detecting leaks is required. The method could incorporate gauges to measure loss, situating values and lines so they can be visually inspected, or installing electronic sensors to alarm when a leak is present. Leak detection plan will be submitted to BLM for approval.

Automatic Shut-off Systems:

Automatic shut off, check values, or similar systems will be installed for pipelines and tanks to minimize the effects of catastrophic line failures used in production or drilling.

Cave/Karst Subsurface Mitigation

The following stipulations will be applied to protect cave/karst and ground water concerns:

Rotary Drilling with Fresh Water:

Fresh water will be used as a circulating medium in zones where caves or karst features are expected. SEE ALSO: Drilling COAs for this well.

Directional Drilling:

Kick off for directional drilling will occur at least 100 feet below the bottom of the cave occurrence zone. SEE ALSO: Drilling COAs for this well.

Lost Circulation:

ALL lost circulation zones from the surface to the base of the cave occurrence zone will be logged and reported in the drilling report.

Regardless of the type of drilling machinery used, if a void of four feet or more and circulation losses greater than 70 percent occur simultaneously while drilling in any cavebearing zone, the BLM will be notified immediately by the operator. The BLM will assess the situation and work with the operator on corrective actions to resolve the problem.

Abandonment Cementing:

Upon well abandonment in cave karst areas additional plugging conditions of approval may be required. The BLM will assess the situation and work with the operator to ensure proper plugging of the wellbore.

Pressure Testing:

The operator will perform annual pressure monitoring on all casing annuli and reported in a sundry notice. If the test results indicated a casing failure has occurred, remedial action will be undertaken to correct the problem to the BLM's approval.

BURIED PIPELINES:

• The BLM, Carlsbad Field Office, will be informed immediately if any subsurface drainage channels, passages, or voids are intersected by trenching, and no pipe will be laid in the trench at that point until clearance has been issued by the Authorized Officer.

Page 5 of 24

- If a void is encountered alignments may be rerouted to avoid the karst feature and lessen; the potential of subsidence or collapse of karst features, buildup of toxic or combustible gas, or other possible impacts to cave and karst resources from the buried pipeline.
- Special restoration stipulations or realignment may be required at such intersections, if any.
- A leak detection plan <u>will be submitted to the BLM Carlsbad Field Office for</u> <u>approval</u> prior to pipeline installation. The method could incorporate gauges to detect pressure drops, situating values and lines so they can be visually inspected periodically or installing electronic sensors to alarm when a leak is present. The leak detection plan will incorporate an automatic shut off system that will be installed for proposed pipelines to minimize the effects of an undesirable event.
- Regular monitoring is required to quickly identify leaks for their immediate and proper treatment.
- All spills or leaks will be reported to the BLM immediately for their immediate and proper treatment.

FLOWLINES (SURFACE):

- Flowlines will be routed around sinkholes and other karst features to avoid or lessen the possibility of encountering near surface voids and to minimize the possibility of leaks and spills from entering karst systems.
- If a void is encountered alignments may be rerouted to avoid the karst feature and lessen; the potential of subsidence or collapse of karst features, buildup of toxic or combustible gas, or other possible impacts to cave and karst resources from the buried pipeline.
- Regular monitoring is required to quickly identify leaks for their immediate and proper treatment.
- All spills or leaks will be reported to the BLM immediately for their immediate and proper treatment.

POWERLINES:

- Smaller powerlines will be routed around sinkholes and other karst features to avoid or lessen the possibility of encountering near surface voids and to minimize changes to runoff or possible leaks and spills from entering karst systems. Larger powerlines will adjust their pole spacing to avoid cave and karst features.
- The BLM, Carlsbad Field Office, will be informed immediately if any subsurface drainage channels, cave passages, or voids are penetrated during construction.
- No further construction will be done until clearance has been issued by the Authorized Officer.
- Special restoration stipulations or realignment may be required.

Page 6 of 24

. .	EXHIBIT NO. 1		Date of Issue:
MENT OF T	·		9/24/2018
	Bureau of Land Management, Car 620 E. Greene Street Carlsbad	lsbad Field Office , NM 88220	NM-13996
ARCH 3. BAS	Cultural and Archaeologica	l Resources	BLM Report No.
	NOTICE OF STIPUI	ATIONS	18-5436

Historic properties in the vicinity of this project are protected by federal law. In order to ensure that they are not damaged or destroyed by construction activities, the project proponent and construction supervisors shall ensure that the following stipulations are implemented.

<u>Project</u> <u>Name</u> :	Crawford Buried Pipeline Right-of-Way
	1). A 3-day preconstruction call-in notification. Contact BLM Inspection and Enforcement at
Required	2. Professional archaeological monitoring. Contact your BLM project archaeologist at (575) 234-5917 for assistance.
A. 🛛	These stipulations must be given to your monitor at least <u>5 days</u> prior to the start of construction.
B . 🔀	No construction, including vegetation removal or other site prep may begin prior to the arrival of the monitor.
	<u>3. Cultural site barrier fencing.</u> (Your monitor will assist you).
A .	<u>A temporary site protection barrier(s)</u> shall be erected prior to all ground-disturbing activities. The minimum barrier(s) shall consist of upright wooden survey lath spaced no more than ten (10) feet apart and marked with blue ribbon flagging or blue paint. There shall be no construction activities or vehicular traffic past the barrier(s) at any time.
B.	A permanent, 4-strand barbed wire fence strung on standard "T-posts" shall be erected prior to all ground-disturbing activities. No construction activities or vehicle traffic are allowed past the fence.
Required	4. The archaeological monitor shall:
A. 🖂	Insure that the proposed project bores under HCIP-40428.
B . 🛛	Observe all ground-disturbing activities within 100 feet of cultural site.
C. 🛛	Submit a brief monitoring report within 30 days of completion of monitoring.
D. 🗌	
E. 🗌	
	If subsurface cultural resources are encountered during the monitoring, all activities shall cease and a BLM-CFO archaeologist shall be notified immediately.
Other:	IF THE CONTRACT ARCHAEOLOGIST DOES NOT KNOW WHERE THE SITE(S) ARE LOCATED AT PLEASE COME BY THE CARLSBAD BLM AND MAPS AND OTHER DATA WILL BE PROVIDED UPON REQUEST TO THE CONTRACT ARCHAEOLOGIST

Site Protection and Employee Education: It is the responsibility of the project proponent and his construction supervisor to inform all employees and subcontractors that cultural and archaeological sites are to be avoided by all personnel, vehicles, and equipment; and that it is illegal to collect, damage, or disturb cultural resources on Public Lands.

For assistance contact:

Aaron Whaley (575) 234-5986

Page 7 of 24

Elia Perez (575)-234-6231 Garrett Leitermann (575) 234-2239 Bruce Boeke (575) 234-5917

• The entirety of the well pads and CTB would be bermed to prevent oil, salt, and other chemical contaminants from leaving the well pads. Topsoil should not be used to construct the berm.

No water flow from the uphill side(s) of the pads should be allowed to enter the well pads. The berm should be maintained through the life of the wells and after interim reclamation has been completed.

 Any water erosion that may occur due to the construction of the well pads or facilities during the life of the project would be quickly corrected and proper measures would be taken to prevent future erosion.

Page 8 of 24

VI. CONSTRUCTION

A. NOTIFICATION

The BLM shall administer compliance and monitor construction of the access road and well pad. Notify the Carlsbad Field Office at (575) 234-5909 at least 3 working days prior to commencing construction of the access road and/or well pad.

When construction operations are being conducted on this well, the operator shall have the approved APD and Conditions of Approval (COA) on the well site and they shall be made available upon request by the Authorized Officer.

B. TOPSOIL

The operator shall strip the top portion of the soil (root zone) from the entire well pad area and stockpile the topsoil along the edge of the well pad as depicted in the APD. The root zone is typically six (6) inches in depth. All the stockpiled topsoil will be redistributed over the interim reclamation areas. Topsoil shall not be used for berming the pad or facilities. For final reclamation, the topsoil shall be spread over the entire pad area for seeding preparation.

Other subsoil (below six inches) stockpiles must be completely segregated from the topsoil stockpile. Large rocks or subsoil clods (not evident in the surrounding terrain) must be buried within the approved area for interim and final reclamation.

C. CLOSED LOOP SYSTEM

Tanks are required for drilling operations: No Pits.

The operator shall properly dispose of drilling contents at an authorized disposal site.

D. FEDERAL MINERAL MATERIALS PIT

Payment shall be made to the BLM prior to removal of any federal mineral materials. Call the Carlsbad Field Office at (575) 234-5972.

E. WELL PAD SURFACING

Surfacing of the well pad is not required.

If the operator elects to surface the well pad, the surfacing material may be required to be removed at the time of reclamation. The well pad shall be constructed in a manner which creates the smallest possible surface disturbance, consistent with safety and operational needs.

F. EXCLOSURE FENCING (CELLARS & PITS)

Page 9 of 24

Exclosure Fencing

The operator will install and maintain exclosure fencing for all open well cellars to prevent access to public, livestock, and large forms of wildlife before and after drilling operations until the pit is free of fluids and the operator initiates backfilling. (For examples of exclosure fencing design, refer to BLM's Oil and Gas Gold Book, Exclosure Fence Illustrations, Figure 1, Page 18.)

G. ON LEASE ACCESS ROADS

Road Width

The access road shall have a driving surface that creates the smallest possible surface disturbance and does not exceed fourteen (14) feet in width. The maximum width of surface disturbance, when constructing the access road, shall not exceed twenty-five (25) feet.

Surfacing

Surfacing material is not required on the new access road driving surface. If the operator elects to surface the new access road or pad, the surfacing material may be required to be removed at the time of reclamation.

Where possible, no improvements should be made on the unsurfaced access road other than to remove vegetation as necessary, road irregularities, safety issues, or to fill low areas that may sustain standing water.

The Authorized Officer reserves the right to require surfacing of any portion of the access road at any time deemed necessary. Surfacing may be required in the event the road deteriorates, erodes, road traffic increases, or it is determined to be beneficial for future field development. The surfacing depth and type of material will be determined at the time of notification.

Crowning

Crowning shall be done on the access road driving surface. The road crown shall have a grade of approximately 2% (i.e., a 1" crown on a 14' wide road). The road shall conform to Figure 1; cross section and plans for typical road construction.

Ditching

Ditching shall be required on both sides of the road.

Turnouts

Vehicle turnouts shall be constructed on the road. Turnouts shall be intervisible with interval spacing distance less than 1000 feet. Turnouts shall conform to Figure 1; cross section and plans for typical road construction.

Drainage

Page 10 of 24

Drainage control systems shall be constructed on the entire length of road (e.g. ditches, sidehill outsloping and insloping, lead-off ditches, culvert installation, and low water crossings).

A typical lead-off ditch has a minimum depth of 1 foot below and a berm of 6 inches above natural ground level. The berm shall be on the down-slope side of the lead-off ditch.

Cross Section of a Typical Lead-off Ditch



All lead-off ditches shall be graded to drain water with a 1 percent minimum to 3 percent maximum ditch slope. The spacing interval are variable for lead-off ditches and shall be determined according to the formula for spacing intervals of lead-off ditches, but may be amended depending upon existing soil types and centerline road slope (in %);

Formula for Spacing Interval of Lead-off Ditches

Example - On a 4% road slope that is 400 feet long, the water flow shall drain water into a lead-off ditch. Spacing interval shall be determined by the following formula:

400 foot road with 4% road slope: $\underline{400'}_{4\%}$ + 100' = 200' lead-off ditch interval

Cattle guards

An appropriately sized cattle guard sufficient to carry out the project shall be installed and maintained at fence/road crossings. Any existing cattle guards on the access road route shall be repaired or replaced if they are damaged or have deteriorated beyond practical use. The operator shall be responsible for the condition of the existing cattle guards that are in place and are utilized during lease operations.

Fence Requirement

Where entry is granted across a fence line, the fence shall be braced and tied off on both sides of the passageway prior to cutting. The operator shall notify the private surface landowner or the grazing allotment holder prior to crossing any fences.

Public Access

Public access on this road shall not be restricted by the operator without specific written approval granted by the Authorized Officer.

Page 11 of 24





Page 12 of 24

VII. PRODUCTION (POST DRILLING)

A. WELL STRUCTURES & FACILITIES

Placement of Production Facilities

Production facilities should be placed on the well pad to allow for maximum interim recontouring and revegetation of the well location.

Exclosure Netting (Open-top Tanks)

Immediately following active drilling or completion operations, the operator will take actions necessary to prevent wildlife and livestock access, including avian wildlife, to all open-topped tanks that contain or have the potential to contain salinity sufficient to cause harm to wildlife or livestock, hydrocarbons, or Resource Conservation and Recovery Act of 1976-exempt hazardous substances. At a minimum, the operator will net, screen, or cover open-topped tanks to exclude wildlife and livestock and prevent mortality. If the operator uses netting, the operator will cover and secure the open portion of the tank to prevent wildlife entry. The operator will net, screen, or cover the tanks until the operator removes the tanks from the location or the tanks no longer contain substances that could be harmful to wildlife or livestock. Use a maximum netting mesh size of 1 ½ inches. The netting must not be in contact with fluids and must not have holes or gaps.

Chemical and Fuel Secondary Containment and Exclosure Screening

The operator will prevent all hazardous, poisonous, flammable, and toxic substances from coming into contact with soil and water. At a minimum, the operator will install and maintain an impervious secondary containment system for any tank or barrel containing hazardous, poisonous, flammable, or toxic substances sufficient to contain the contents of the tank or barrel and any drips, leaks, and anticipated precipitation. The operator will dispose of fluids within the containment system that do not meet applicable state or U. S. Environmental Protection Agency livestock water standards in accordance with state law; the operator must not drain the fluids to the soil or ground. The operator will design, construct, and maintain all secondary containment systems to prevent wildlife and livestock exposure to harmful substances. At a minimum, the operator will install effective wildlife and livestock exclosure systems such as fencing, netting, expanded metal mesh, lids, and grate covers. Use a maximum netting mesh size of 1 ½ inches.

Open-Vent Exhaust Stack Exclosures

The operator will construct, modify, equip, and maintain all open-vent exhaust stacks on production equipment to prevent birds and bats from entering, and to discourage perching, roosting, and nesting. (*Recommended exclosure structures on open-vent exhaust stacks are in the shape of a cone.*) Production equipment includes, but may not be limited to, tanks, heater-treaters, separators, dehydrators, flare stacks, in-line units, and compressor mufflers.

Containment Structures

Page 13 of 24

Proposed production facilities such as storage tanks and other vessels will have a secondary containment structure that is constructed to hold the capacity of 1.5 times the largest tank, plus freeboard to account for precipitation, unless more stringent protective requirements are deemed necessary.

Painting Requirement

All above-ground structures including meter housing that are not subject to safety requirements shall be painted a flat non-reflective paint color, <u>Shale Green</u> from the BLM Standard Environmental Color Chart (CC-001: June 2008).

B. PIPELINES

STANDARD STIPULATIONS FOR SURFACE INSTALLED PIPELINES

A copy of the application (Grant, Sundry Notice, APD) and attachments, including stipulations, survey plat and/or map, will be on location during construction. BLM personnel may request to you a copy of your permit during construction to ensure compliance with all stipulations.

Holder agrees to comply with the following stipulations to the satisfaction of the Authorized Officer:

1. The holder shall indemnify the United States against any liability for damage to life or property arising from the occupancy or use of public lands under this grant.

2. The holder shall comply with all applicable Federal laws and regulations existing or hereafter enacted or promulgated. In any event, the holder shall comply with the Toxic Substances Control Act of 1976 as amended, 15 USC 2601 <u>et seq</u>. (1982) with regards to any toxic substances that are used, generated by or stored on the right-of-way or on facilities authorized under this right-of-way grant. (See 40 CFR, Part 702-799 and especially, provisions on polychlorinated biphenyls, 40 CFR 761.1-761.193.) Additionally, any release of toxic substances (leaks, spills, etc.) in excess of the reportable quantity established by 40 CFR, Part 117 shall be reported as required by the Comprehensive Environmental Response, Compensation, and Liability Act, section 102b. A copy of any report required or requested by any Federal agency or State government as a result of a reportable release or spill of any toxic substances shall be furnished to the authorized officer concurrent with the filing of the reports to the involved Federal agency or State government.

3. The holder agrees to indemnify the United States against any liability arising from the release of any hazardous substance or hazardous waste (as these terms are defined in the Comprehensive Environmental Response, Compensation and Liability Act of 1980, 42 U.S.C. 9601, et seq. or the Resource Conservation and Recovery Act, 42 U.S.C. 6901, et seq.) on the Right-of-Way (unless the release or threatened release is wholly unrelated to activity of the Right-of-Way holder's activity on the Right-of-Way), or resulting from the activity of the Right-of-Way holder on the Right-of-Way. This agreement applies without regard to whether a release is caused by the holder, its agent, or unrelated third

Page 14 of 24

parties.

4. The holder shall be liable for damage or injury to the United States to the extent provided by 43 CFR Sec. 2883.1-4. The holder shall be held to a standard of strict liability for damage or injury to the United States resulting from pipe rupture, fire, or spills caused or substantially aggravated by any of the following within the right-of-way or permit area:

- a. Activities of the holder including, but not limited to construction, operation, maintenance, and termination of the facility.
- b. Activities of other parties including, but not limited to:
 - (1) Land clearing.
 - (2) Earth-disturbing and earth-moving work.
 - (3) Blasting.
 - (4) Vandalism and sabotage.
- c. Acts of God.

The maximum limitation for such strict liability damages shall not exceed one million dollars (\$1,000,000) for any one event, and any liability in excess of such amount shall be determined by the ordinary rules of negligence of the jurisdiction in which the damage or injury occurred.

This section shall not impose strict liability for damage or injury resulting primarily from an act of war or from the negligent acts or omissions of the United States.

5. If, during any phase of the construction, operation, maintenance, or termination of the pipeline, any oil, salt water, or other pollutant should be discharged from the pipeline system, impacting Federal lands, the control and total removal, disposal, and cleaning up of such oil, salt water, or other pollutant, wherever found, shall be the responsibility of the holder, regardless of fault. Upon failure of the holder to control, dispose of, or clean up such discharge on or affecting Federal lands, or to repair all damages resulting therefrom, on the Federal lands, the Authorized Officer may take such measures as he deems necessary to control and clean up the discharge and restore the area, including, where appropriate, the aquatic environment and fish and wildlife habitats, at the full expense of the holder. Such action by the Authorized Officer shall not relieve the holder of any responsibility as provided herein.

6. All construction and maintenance activity will be confined to the authorized right-ofway width of <u>20</u> feet. If the pipeline route follows an existing road or buried pipeline right-of-way, the surface pipeline must be installed no farther than 10 feet from the edge of the road or buried pipeline right-of-way. If existing surface pipelines prevent this distance, the proposed surface pipeline must be installed immediately adjacent to the outer surface pipeline. All construction and maintenance activity will be confined to existing roads or right-of-ways.

7. No blading or clearing of any vegetation will be allowed unless approved in writing

Page 15 of 24

by the Authorized Officer.

8. The holder shall install the pipeline on the surface in such a manner that will minimize suspension of the pipeline across low areas in the terrain. In hummocky of duney areas, the pipeline will be "snaked" around hummocks and dunes rather then suspended across these features.

9. The pipeline shall be buried with a minimum of <u>24</u> inches under all roads, "two-tracks," and trails. Burial of the pipe will continue for 20 feet on each side of each crossing. The condition of the road, upon completion of construction, shall be returned to at least its former state with no bumps or dips remaining in the road surface.

10. The holder shall minimize disturbance to existing fences and other improvements on public lands. The holder is required to promptly repair improvements to at least their former state. Functional use of these improvements will be maintained at all times. The holder will contact the owner of any improvements prior to disturbing them. When necessary to pass through a fence line, the fence shall be braced on both sides of the passageway prior to cutting of the fence. No permanent gates will be allowed unless approved by the Authorized Officer.

11. In those areas where erosion control structures are required to stabilize soil conditions, the holder will install such structures as are suitable for the specific soil conditions being encountered and which are in accordance with sound resource management practices.

12. Excluding the pipe, all above-ground structures not subject to safety requirement shall be painted by the holder to blend with the natural color of the landscape. The paint used shall be a color which simulates "Standard Environmental Colors" – **Shale Green**, Munsell Soil Color No. 5Y 4/2; designated by the Rocky Mountain Five State Interagency Committee.

13. The pipeline will be identified by signs at the point of origin and completion of the right-of-way and at all road crossings. At a minimum, signs will state the holder's name, BLM serial number, and the product being transported. Signs will be maintained in a legible condition for the life of the pipeline.

14. The holder shall not use the pipeline route as a road for purposes other than routine maintenance as determined necessary by the Authorized Officer in consultation with the holder. The holder will take whatever steps are necessary to ensure that the pipeline route is not used as a roadway.

15. Any cultural and/or paleontological resource (historic or prehistoric site or object) discovered by the holder, or any person working on his behalf, on public or Federal land shall be immediately reported to the authorized officer. Holder shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the authorized officer. An evaluation of the discovery will be made by the

Page 16 of 24

authorized officer to determine appropriate cultural or scientific values. The holder will be responsible for the cost of evaluation and any decision as to proper mitigation measures will be made by the authorized officer after consulting with the holder.

16. The operator shall be held responsible if noxious weeds become established within the areas of operations. Weed control shall be required on the disturbed land where noxious weeds exist, which includes the roads, powerline corridor, and adjacent land affected by the establishment of weeds due to this action. The operator shall consult with the Authorized Officer for acceptable weed control methods, which include following EPA and BLM requirements and policies.

17. Surface pipelines must be less than or equal to 4 inches and a working pressure below 125 psi.

BURIED PIPELINE STIPULATIONS

A copy of the application (Grant, APD, or Sundry Notice) and attachments, including conditions of approval, survey plat and/or map, will be on location during construction. BLM personnel may request to you a copy of your permit during construction to ensure compliance with all stipulations.

Holder agrees to comply with the following stipulations to the satisfaction of the Authorized Officer:

1. The Holder shall indemnify the United States against any liability for damage to life or property arising from the occupancy or use of public lands under this grant.

2. The Holder shall comply with all applicable Federal laws and regulations existing or hereafter enacted or promulgated. In any event, the holder shall comply with the Toxic Substances Control Act of 1976 as amended, 15 USC 2601 <u>et seq.</u> (1982) with regards to any toxic substances that are used, generated by or stored on the right-of-way or on facilities authorized under this right-ofway grant. (See 40 CFR Part 702-799 and especially, provisions on polychlorinated biphenyls, 40 CFR 761.1-761.193.) Additionally, any release of toxic substances (leaks, spills, etc.) in excess of the reportable quantity established by 40 CFR Part 117 shall be reported as required by the Comprehensive Environmental Response, Compensation, and Liability Act, section 102b. A copy of any report required or requested by any Federal agency or State government as a result of a reportable release or spill of any toxic substances shall be furnished to the authorized officer concurrent with the filing of the reports to the involved Federal agency or State government.

3. The holder agrees to indemnify the United States against any liability arising from the release of any hazardous substance or hazardous waste (as these terms are defined in the Comprehensive Environmental Response, Compensation and Liability Act of 1980, 42 U.S.C. 9601, <u>et seq</u>. or the Resource Conservation and Recovery Act, 42 U.S.C.6901, <u>et seq</u>.) on the Right-of-Way (unless the release or threatened release is wholly unrelated to the Right-of-Way holder's activity on the Right-of-Way), or resulting from the activity of the Right-of-Way holder on the Right-of-Way. This agreement applies without regard to whether a release is caused by the holder, its agent, or unrelated third parties.

Page 17 of 24

4. If, during any phase of the construction, operation, maintenance, or termination of the pipeline, any oil or other pollutant should be discharged from the pipeline system, impacting Federal lands, the control and total removal, disposal, and cleaning up of such oil or other pollutant, wherever found, shall be the responsibility of holder, regardless of fault. Upon failure of holder to control, dispose of, or clean up such discharge on or affecting Federal lands, or to repair all damages resulting therefrom, on the Federal lands, the Authorized Officer may take such measures as he deems necessary to control and clean up the discharge and restore the area, including where appropriate, the aquatic environment and fish and wildlife habitats, at the full expense of the holder. Such action by the Authorized Officer shall not relieve holder of any responsibility as provided herein.

Page 18 of 24

5. All construction and maintenance activity will be confined to the authorized right-of-way.

6. The pipeline will be buried with a minimum cover of <u>36</u> inches between the top of the pipe and ground level.

7. The maximum allowable disturbance for construction in this right-of-way will be $\underline{30}$ feet:

- Blading of vegetation within the right-of-way will be allowed: maximum width of blading operations will not exceed <u>20</u> feet. The trench is included in this area. (*Blading is defined as the complete removal of brush and ground vegetation.*)
- Clearing of brush species within the right-of-way will be allowed: maximum width of clearing operations will not exceed <u>30</u> feet. The trench and bladed area are included in this area. (Clearing is defined as the removal of brush while leaving ground vegetation (grasses, weeds, etc.) intact. Clearing is best accomplished by holding the blade 4 to 6 inches above the ground surface.)
- The remaining area of the right-of-way (if any) shall only be disturbed by compressing the vegetation. (Compressing can be caused by vehicle tires, placement of equipment, etc.)

9. The holder shall minimize disturbance to existing fences and other improvements on public lands. The holder is required to promptly repair improvements to at least their former state. Functional use of these improvements will be maintained at all times. The holder will contact the owner of any improvements prior to disturbing them. When necessary to pass through a fence line, the fence shall be braced on both sides of the passageway prior to cutting of the fence. No permanent gates will be allowed unless approved by the Authorized Officer.

10. Vegetation, soil, and rocks left as a result of construction or maintenance activity will be randomly scattered on this right-of-way and will not be left in rows, piles, or berms, unless otherwise approved by the Authorized Officer. The entire right-of-way shall be recontoured to match the surrounding landscape. The backfilled soil shall be compacted and a 6 inch berm will be left over the ditch line to allow for settling back to grade.

11. In those areas where erosion control structures are required to stabilize soil conditions, the holder will install such structures as are suitable for the specific soil conditions being encountered and which are in accordance with sound resource management practices.

Page 19 of 24

12. The holder will reseed all disturbed areas. Seeding will be done according to the attached seeding requirements, using the following seed mix.

(X) seed mixture 1	() seed mixture 3
() seed mixture 2	() seed mixture 4
() seed mixture 2/LPC	() Aplomado Falcon Mixture

13. All above-ground structures not subject to safety requirements shall be painted by the holder to blend with the natural color of the landscape. The paint used shall be color which simulates "Standard Environmental Colors" – **Shale Green**, Munsell Soil Color No. 5Y 4/2.

14. The pipeline will be identified by signs at the point of origin and completion of the right-ofway and at all road crossings. At a minimum, signs will state the holder's name, BLM serial number, and the product being transported. All signs and information thereon will be posted in a permanent, conspicuous manner, and will be maintained in a legible condition for the life of the pipeline.

15. The holder shall not use the pipeline route as a road for purposes other than routine maintenance as determined necessary by the Authorized Officer in consultation with the holder before maintenance begins. The holder will take whatever steps are necessary to ensure that the pipeline route is not used as a roadway. As determined necessary during the life of the pipeline, the Authorized Officer may ask the holder to construct temporary determined structures.

16. Any cultural and/or paleontological resources (historic or prehistoric site or object) discovered by the holder, or any person working on his behalf, on public or Federal land shall be immediately reported to the Authorized Officer. Holder shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the Authorized Officer. An evaluation of the discovery will be made by the Authorized Officer to determine appropriate actions to prevent the loss of significant cultural or scientific values. The holder will be responsible for the cost of evaluation and any decision as to proper mitigation measures will be made by the Authorized Officer after consulting with the holder.

17. The operator shall be held responsible if noxious weeds become established within the areas of operations. Weed control shall be required on the disturbed land where noxious weeds exist, which includes associated roads, pipeline corridor and adjacent land affected by the establishment of weeds due to this action. The operator shall consult with the Authorized Officer for acceptable weed control methods, which include following EPA and BLM requirements and policies.

18. <u>Escape Ramps</u> - The operator will construct and maintain pipeline/utility trenches that are not otherwise fenced, screened, or netted to prevent livestock, wildlife, and humans from becoming entrapped. At a minimum, the operator will construct and maintain escape ramps, ladders, or

Page 20 of 24

other methods of avian and terrestrial wildlife escape in the trenches according to the following criteria:

- a. Any trench left open for eight (8) hours or less is not required to have escape ramps; however, before the trench is backfilled, the contractor/operator shall inspect the trench for wildlife, remove all trapped wildlife, and release them at least 100 yards from the trench.
- b. For trenches left open for eight (8) hours or more, earthen escape ramps (built at no more than a 30 degree slope and spaced no more than 500 feet apart) shall be placed in the trench.

C. ELECTRIC LINES

STANDARD STIPULATIONS FOR OVERHEAD ELECTRIC DISTRIBUTION

A copy of the grant and attachments, including stipulations, survey plat and/or map, will be on location during construction. BLM personnel may request to you a copy of your permit during construction to ensure compliance with all stipulations.

Holder agrees to comply with the following stipulations to the satisfaction of the Authorized Officer:

1. The holder shall indemnify the United States against any liability for damage to life or property arising from the occupancy or use of public lands under this grant.

2. The holder shall comply with all applicable Federal laws and regulations existing or hereafter enacted or promulgated. In any event, the holder shall comply with the Toxic Substances Control Act of 1976 as amended, 15 USC 2601 <u>et seq</u>. (1982) with regards to any toxic substances that are used, generated by or stored on the right-of-way or on facilities authorized under this right-of-way grant. (See 40 CFR, Part 702-799 and especially, provisions on polychlorinated biphenyls, 40 CFR 761.1-761.193.) Additionally, any release of toxic substances (leaks, spills, etc.) in excess of the reportable quantity established by 40 CFR, Part 117 shall be reported as required by the Comprehensive Environmental Response, Compensation, and Liability Act, section 102b. A copy of any report required or requested by any Federal agency or State government as a result of a reportable release or spill of any toxic substances shall be furnished to the authorized officer concurrent with the filing of the reports to the involved Federal agency or State government.

3. The holder agrees to indemnify the United States against any liability arising from the release of any hazardous substance or hazardous waste (as these terms are defined in the Comprehensive Environmental Response, Compensation and Liability Act of 1980, 42 U.S.C. 9601, <u>et seq</u>. or the Resource Conservation and Recovery Act, 42 U.S.C. 6901, <u>et seq</u>.) on the Right-of-Way (unless the release or threatened release is wholly unrelated to the Right-of-Way holder's activity on the Right-of-Way), or resulting from the activity of the Right-of-Way holder on the Right-of-Way. This agreement applies without regard to whether a release is caused by the holder, its agent, or unrelated third parties.

Page 21 of 24

4. There will be no clearing or blading of the right-of-way unless otherwise agreed to in writing by the Authorized Officer.

5. Power lines shall be constructed and designed in accordance to standards outlined in "Suggested Practices for Avian Protection on Power lines: The State of the Art in 2006" Edison Electric Institute, APLIC, and the California Energy Commission 2006. The holder shall assume the burden and expense of proving that pole designs not shown in the above publication deter raptor perching, roosting, and nesting. Such proof shall be provided by a raptor expert approved by the Authorized Officer. The BLM reserves the right to require modification or additions to all powerline structures placed on this right-of-way, should they be necessary to ensure the safety of large perching birds. Such modifications and/or additions shall be made by the holder without liability or expense to the United States.

Raptor deterrence will consist of but not limited to the following: triangle perch discouragers shall be placed on each side of the cross arms and a nonconductive perching deterrence shall be placed on all vertical poles that extend past the cross arms.

6. The holder shall minimize disturbance to existing fences and other improvements on public lands. The holder is required to promptly repair improvements to at least their former state. Functional use of these improvements will be maintained at all times. The holder will contact the owner of any improvements prior to disturbing them. When necessary to pass through a fence line, the fence shall be braced on both sides of the passageway prior to cutting the fence. No permanent gates will be allowed unless approved by the Authorized Officer.

7. The BLM serial number assigned to this authorization shall be posted in a permanent, conspicuous manner where the power line crosses roads and at all serviced facilities. Numbers will be at least two inches high and will be affixed to the pole nearest the road crossing and at the facilities served.

8. Upon cancellation, relinquishment, or expiration of this grant, the holder shall comply with those abandonment procedures as prescribed by the Authorized Officer.

9. All surface structures (poles, lines, transformers, etc.) shall be removed within 180 days of abandonment, relinquishment, or termination of use of the serviced facility or facilities or within 180 days of abandonment, relinquishment, cancellation, or expiration of this grant, whichever comes first. This will not apply where the power line extends service to an active, adjoining facility or facilities.

10. Any cultural and/or paleontological resource (historic or prehistoric site or object) discovered by the holder, or any person working on his behalf, on public or Federal land shall be immediately reported to the Authorized Officer. Holder shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the Authorized Officer. An evaluation of the discovery will be made by the

Page 22 of 24

Authorized Officer to determine appropriate actions to prevent the loss of significant cultural or scientific values. The holder will be responsible for the cost of evaluation and any decision as to proper mitigation measures will be made by the Authorized Officer after consulting with the holder.

- 11. Special Stipulations:
 - For reclamation remove poles, lines, transformer, etc. and dispose of properly.
 - Fill in any holes from the poles removed.

VIII. INTERIM RECLAMATION

During the life of the development, all disturbed areas not needed for active support of production operations should undergo interim reclamation in order to minimize the environmental impacts of development on other resources and uses.

Within six (6) months of well completion, operators should work with BLM surface management specialists (Jim Amos: 575-234-5909) to devise the best strategies to reduce the size of the location. Interim reclamation should allow for remedial well operations, as well as safe and efficient removal of oil and gas.

During reclamation, the removal of caliche is important to increasing the success of revegetating the site. Removed caliche that is free of contaminants may be used for road repairs, fire walls or for building other roads and locations. In order to operate the well or complete workover operations, it may be necessary to drive, park and operate on restored interim vegetation within the previously disturbed area. Disturbing revegetated areas for production or workover operations will be allowed. If there is significant disturbance and loss of vegetation, the area will need to be revegetated. Communicate with the appropriate BLM office for any exceptions/exemptions if needed.

All disturbed areas after they have been satisfactorily prepared need to be reseeded with the seed mixture provided below.

Upon completion of interim reclamation, the operator shall submit a Sundry Notices and Reports on Wells, Subsequent Report of Reclamation (Form 3160-5).

IX. FINAL ABANDONMENT & RECLAMATION

At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land are restored.

Earthwork for final reclamation must be completed within six (6) months of well plugging. All pads, pits, facility locations and roads must be reclaimed to a satisfactory revegetated, safe, and stable condition, unless an agreement is made with the landowner or BLM to keep the road and/or pad intact.

Page 23 of 24

After all disturbed areas have been satisfactorily prepared, these areas need to be revegetated with the seed mixture provided below. Seeding should be accomplished by drilling on the contour whenever practical or by other approved methods. Seeding may need to be repeated until revegetation is successful, as determined by the BLM.

Operators shall contact a BLM surface protection specialist prior to surface abandonment operations for site specific objectives (Jim Amos: 575-234-5909).

Seed Mixture 1 for Loamy Sites

Holder shall seed all disturbed areas with the seed mixture listed below. The seed mixture shall be planted in the amounts specified in pounds of pure live seed (PLS)* per acre. There shall be no primary or secondary noxious weeds in the seed mixture. Seed shall be tested and the viability testing of seed will be done in accordance with State law(s) and within nine (9) months prior to purchase. Commercial seed shall be either certified or registered seed. The seed container shall be tagged in accordance with State law(s) and available for inspection by the Authorized Officer.

Seed shall be planted using a drill equipped with a depth regulator to ensure proper depth regulator to ensure proper depth of planting where drilling is possible. The seed mixture shall be evenly and uniformly planted over the disturbed area (small/heavier seeds have a tendency to drop the bottom of the drill and are planted first). Holder shall take appropriate measures to ensure this does not occur. Where drilling is not possible, seed shall be broadcast and the area shall be raked or chained to cover the seed. When broadcasting the seed, the pounds per acre shall be doubled. The seeding shall be repeated until a satisfactory stand is established as determined by the Authorized Officer. Evaluation of growth may not be made before completion of at least one full growing season after seeding.

Species to be planted in pounds of pure live seed* per acre:

Species

	<u>lb/acre</u>
Plains lovegrass (Eragrostis intermedia)	0.5
Sand dropseed (Sporobolus cryptandrus)	1.0
Sideoats grama (Bouteloua curtipendula)	5.0
Plains bristlegrass (Setaria macrostachya)	2.0

*Pounds of pure live seed:

Pounds of seed x percent purity x percent germination = pounds pure live seed

Page 24 of 24

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OXY USA INC.
NMNM013996
52H – Radius CC 6-7 Federal COM 51H
170'/N & 1350'/W
20'/S & 2300'/W
Section 6, T.24 S., R.29 E., NMPM
Eddy County, New Mexico

	C	0Å	
 -			

H2S	C Yes	• No	
Potash	None	C Secretary	C R-111-P
Cave/Karst Potential	C Low	Medium	
Cave/Karst Potential	Critical		
Variance	∩ None	• Flex Hose	C Other
Wellhead	Conventional	C Multibowl	🖲 Both
Other	☐ 4 String Area	Capitan Reef	F WIPP
Other	Fluid Filled	Cement Squeeze	F Pilot Hole
Special Requirements	☐ Water Disposal	COM	🔽 Unit
			•

Break Testing	C Yes	• No	

A. HYDROGEN SULFIDE

Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area shall meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.

B. CASING

Casing Design:

- 1. The 10-3/4 inch surface casing shall be set at approximately 320 feet (a minimum of 70 feet (Eddy County) into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run

Page 1 of 9

to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

- b. Wait on cement (WOC) time for a primary cement job will be a minimum of <u>8</u> <u>hours</u> or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.

Intermediate casing must be kept fluid filled to meet BLM minimum collapse requirement.

2. The minimum required fill of cement behind the 7-5/8 inch intermediate casing is:

Option 1 (Single Stage):

• Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

a. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.

b. Second stage above DV tool:

• Cement to surface. If cement does not circulate, contact the appropriate BLM office.

Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.

In <u>Medium Cave/Karst Areas</u> if cement does not circulate to surface on the first two casing strings, the cement on the 3rd casing string must come to surface.

Operator has proposed to pump down 10-3/4" X 7-5/8" annulus. <u>Operator must run</u> a <u>CBL or ECHO-METER from TD of the 7-5/8" casing to surface. Submit results to BLM.</u>

Page 2 of 9

3. The minimum required fill of cement behind the 5.5 \times 5 inch production casing is:

Option 1 (Single Stage):

• Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- a. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- b. Second stage above DV tool:
 - Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.

C. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'
- 2.

Option 1:

- a. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **5000 (5M)** psi.
- b. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the intermediate casing shoe shall be 10,000 (10M) psi. Variance is approved to use a 5000 (5M) Annular which shall be tested to 5000 (5M) psi.

Option 2:

1. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the

Page 3 of 9

blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 10,000 (10M) psi. Variance is approved to use a 5000 (5M) Annular which shall be tested to 5000 (5M) psi.

- a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
- b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
- c. Manufacturer representative shall install the test plug for the initial BOP test.
- d. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- e. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.

D. SPECIAL REQUIREMENT (S)

Communitization Agreement

- The operator will submit a Communitization Agreement to the Carlsbad Field Office, 620 E Greene St. Carlsbad, New Mexico 88220, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.
- In addition, the well sign shall include the surface and bottom hole lease numbers. <u>When the Communitization Agreement number is known, it shall also be on the sign.</u>

Offline Cementing

Contact the BLM prior to the commencement of any offline cementing procedure.

BOP Break Testing Variance

• BOP break testing is not permitted on this well pending submittion of break testing sundry.

Page 4 of 9

GENERAL REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)
 - Eddy County

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

🛛 Lea County

Call the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575) 393-3612

- 1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
 - a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
 - b. When the operator proposes to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.
- 2. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.
- 3. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

Page 5 of 9

A. CASING

- 1. Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.
- <u>Wait on cement (WOC) for Potash Areas:</u> After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi for all cement blends, 2) until cement has been in place at least <u>24</u> hours. WOC time will be recorded in the driller's log. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 3. <u>Wait on cement (WOC) for Water Basin:</u> After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least <u>8 hours</u>. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 4. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. Have well specific cement details onsite prior to pumping the cement for each casing string.
- 5. No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.
- 6. On that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be performed before drilling more than 20 feet of new hole.
- 7. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- 8. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.

Page 6 of 9

B. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. If a variance is approved for a flexible hose to be installed from the BOP to the choke manifold, the following requirements apply: The flex line must meet the requirements of API 16C. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor.
- 3. 5M or higher system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
- 4. If the operator has proposed a multi-bowl wellhead assembly in the APD. The following requirements must be met:
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.
 - e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including

Page 7 of 9

lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).

- b. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time, except the casing pressure test can be initiated immediately after bumping the plug (only applies to single stage cement jobs).
- c. The tests shall be done by an independent service company utilizing a test plug not a cup or J-packer. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (8 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
- d. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- e. The results of the test shall be reported to the appropriate BLM office.
- f. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- g. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.
- h. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the Wolfcamp formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.

Page 8 of 9
C. DRILLING MUD

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the Wolfcamp formation, and shall be used until production casing is run and cemented.

D. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

NMK02132020

Page 9 of 9

Approval Date: 03/04/2020

WAFMSS

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Operator Certification

I hereby certify that I, or someone under my direct supervision, have inspected the drill site and access route proposed herein; that I am familiar with the conditions which currently exist; that I have full knowledge of state and Federal laws applicable to this operation; that the statements made in this APD package are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed in conformity with this APD package and the terms and conditions under which it is approved. I also certify that I, or the company I represent, am responsible for the operations conducted under this application. These statements are subject to the provisions of 18 U.S.C. 1001 for the filing of false statements.

COLD & CLARKER

ator Certification Data Report

03/06/2020

NAME: David Stewart		Signed on: 02/07/2020
Title: Sr. Regulatory Advisor		
Street Address: 5 Greenway Plaza	a, Suite 110	
City: Houston	State: TX	Zip: 77046
Phone: (713)366-5716		
Email address: david_stewart@ox	y.com	
· · · · · · · · · · · · · · · · · · ·		
Field Representative		
Representative Name: Mike Wilso	n	
Street Address: P.O. Box 50250		
City: Midland	itate: TX	Zip: 79710
Phone: (575)631-6618		
Email address: Michael_wilson@c	xy.com	

AFMSS Application Data Report U.S. Department of the Interior 03/06/2020 BUREAU OF LAND MANAGEMENT APD ID: 10400045743 Submission Date: 08/14/2019 Highlighted data reflects the most **Operator Name: OXY USA INCORPORATED** recent changes Well Name: RADIUS CC 6-7 FEDERAL COM Well Number: 52H Show Final Text Well Type: OIL WELL Well Work Type: Drill Section 1 - General APD ID: 10400045743 Tie to previous NOS? N Submission Date: 08/14/2019 **BLM Office: CARLSBAD User:** David Stewart Title: Sr. Regulatory Advisor Federal/Indian APD: FED Is the first lease penetrated for production Federal or Indian? FED Lease number: NMNM013996 Lease Acres: 199.71 Surface access agreement in place? Allotted? Reservation: Agreement in place? NO Federal or Indian agreement: Agreement number: Agreement name: Keep application confidential? N Permitting Agent? NO APD Operator: OXY USA INCORPORATED **Operator letter of designation: Operator Info Operator Organization Name: OXY USA INCORPORATED Operator Address:** 5 Greenway Plaza, Suite 110 Zip: 77046 **Operator PO Box: Operator City:** Houston State: TX Operator Phone: (713)366-5716 **Operator Internet Address:** Section 2 - Well Information Well in Master Development Plan? NO Master Development Plan name: Well in Master SUPO? NO Master SUPO name: Well in Master Drilling Plan? NO Master Drilling Plan name: Well Name: RADIUS CC 6-7 FEDERAL COM Well Number: 52H Well API Number: Field Name: PURPLE SAGE Field/Pool or Exploratory? Field and Pool Pool Name: PURPLE SAGE WOLFCAMP WOLFCAMP Is the proposed well in an area containing other mineral resources? USEABLE WATER,NATURAL GAS,OIL,POTASH

																			_
Ope	rator	Name	e: OX	(Y US	SA ING	CORP	PORA	TED											
Well	Nam	e: RA	DIUS	s cc	6-7 F	EDEF	RAL (СОМ		Well Nu	mber:	52H							
							• • •,··• ,·	··· . · · ·	<u> </u>										
Is the	e pro	posed	l wei	l in a	n are	a con	taini	na othe	r minera	l resources			WATE	R N		GAS		ΟΤΑS	н
												.,		.,		, .,	012,1	01/10	
ls the	e nro	noser	d wel	l in a	Heliı	ım pr	oduo	tion are	a7 N I	lse Fristin		Pad?	J	Ne	w surfa	ca dis	turba	nco?	
	ofW	lell Pa	ad: M		PLE \	NELL	Juut			Aultiple We	I Pad	Name:	Depth	N	mber: 4	.1H	unda	166 :	
Well	Clas	s: HO	RIZC		L .				C	CC 6-7 FED	ERAL	СОМ	Copin						
المW	Worl		a. Dri	11					r	vumber of L	.egs: 1	I							
Well			WEI	L															
Desc	ribe	Well 7	Гуре	:															
Well	sub-	Туре:	INFI	ԼԼ															
Desid	ribe	sub-t	ype:																
Dista	ance	to tov	vn: 8	Miles	6			Distanc	e to near	rest well: 35	5 FT		Distand	ce t	o lease l	ine: 2	0 FT		
Rese	ervoir	well	spac	ing a	ssigr	ned a	cres	Measur	ement: 6	640 Acres									
Well	plat:	R	adius	SCC6	_7Fd0	Com5	2H_5	SitePlan	_2019081	12125608.pc	if								
		R	adius	SCC6	_7Fd0	Com5	2Н_С	C102Am	ended10I	DayLetter_2	02002	071303	22.pdf						
Well	work	starl	Date	e: 07/	21/20	20			[Duration: 20	DAYS	5							
	Sa	otion	3	\\/o		oati	<u></u>	Tabla											
	Set		13-	vve		cau	<u>on</u>	Iable											
Surv	еу Ту	vpe: R	RECT	ANG	ULAR														
Desc	ribe	Surve	у Ту	pe:															
Datu	m: N	AD83							\ 	/ertical Dat	um: N/								
Surv	ey nı	Impei	r: I	r	1		1		F		atum:			VE	L 	r	I		m
																		ļ	oduce
		or		to				/Trac							nber				ell pro
ore	ot	dicat	oot	Idicat		0	Ē	ot/Lot	je j	nde	, K		an	ype	NUN	tion			lis we
Vellb	IS-Fc	in St	N-F	N N	wsp	kange	ectio	liquc	atituc	ongit	Sount	tate	1eridi	sase T	ease	leval	ē	9	Vill th
> SHL	∠ 170	∠ FNL	ш 135	FW	24S	29E	<i>б</i>	Lot	 32.2538	1-	EDD	NEW	≥ NEW	<u>ت</u> F	FEE	<u>ш</u> 295	<u>≥</u> 0	⊢ 0	N N
Leg			0	L				3	81	104.0279	Y	MEXI	MEXI			9		ļ	
#1 KOP	50	FNI	230	FW	245	29F	6	Lot	32 2541	2 -	FDD	NEW	NFW	F	FEE		103	102	N
Leg			0	L				3	17	104.0249	Y	MEXI	MEXI	ľ		725	40	18	
#1					1		1			081		co	ငဝ			9			

Operator Name: OXY USA INCORPORATED Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

												1							
Wellbore	NS-Foot	NS Indicator	EW-Foot	EW Indicator	Twsp	Range	Section	Aliquot/Lot/Tract	Latitude	Longitude	County	State	Meridian	Lease Type	Lease Number	Elevation	DM	TVD	Will this well produce from this lease?
PPP	1	FNL	230	FW	24S	29E	7	Aliquot	32.23962	-	EDD	NEW	NEW	F	NMNM	-	162	106	Y
Leg			0	L				NENW	6	104.0248	Y	MEXI	MEXI		077018	773	91	93	
#1-1										68		CO	co			4			
PPP	266	FSL	230	FW	24S	29E	6	Aliquot	32.24693	-	EDD	NEW	NEW	F	NMNM	-	136	106	Y
Leg	0		0	L				NESW	8	104.0248	Y	MEXI	MEXI		013996	772	51	82	
#1-2										89		ΟĢ	co			3	_		
PPP	100	FNL	230	FW	24S	29E	6	Lot	32.25398	-	EDD	NEW	NEW	F	FEE	-	111	106	Y
Leg			0	L		ļ		3	42	104.0249	Y	MEXI	MEXI			771	18	71	
#1-3										077		co	co			2		,	
EXIT	330	FSL	230	FW	24S	29E	7	Aliquot	32.22590	-	EDD	NEW	NEW	F	FEE	-	213	107	Y
Leg			0	L				SESW	4	104.0248	Y	MEXI	MEXI			775	34	14	
#1										301		CO	co			5			
BHL	20	FSL	230	FW	24S	29E	7	Aliquot	32.22505	-	EDD	NEW	NEW	F	FEE	-	216	107	N
Leg			0	L				SESW	18	104.0248	Y	MEXI	MEXI			775	44	15	
#1				}						277		co	co			6			

. ,



FMSS

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT



03/06/2020

APD ID: 10400045743

Operator Name: OXY USA INCORPORATED

Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

Highlighted data reflects the most recent changes

Show Final Text

Well Type: OIL WELL

Well Work Type: Drill

Submission Date: 08/14/2019

Section 1 - Geologic Formations

Formation	1997年1月1日,1997年1月1日,1997年1日。 1997年(1997年1月1日,1997年1日,1997年1日 1997年1月1日(1997年1月),1997年1日(1997年1日)。	8-8 6-8-8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	True Vertical	Measured	A state of the	in providence in a serie of the series of th	Producina
iD is a	Formation Name	Elevation	Depth	Depth	Lithologies	Mineral Resources	Formation
512914	RUSTLER	2959	98	98	ANHYDRITE, DOLOMITE, SHALE	USEABLE WATER	N
512915	SALADO	2423	536	536	ANHYDRITE, DOLOMITE, HALITE, SHALE	OTHER : Salt	N
512916	CASTILE	1659	1300	1300	ANHYDRITE	OTHER : Salt	N
512917	LAMAR	200	2759	2759	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL, OTHER : Brine	N
512918	BELL CANYON	154	2805	2805	SANDSTONE, SILTSTONE	NATURAL GAS, OIL, OTHER : Brine	N
512919	CHERRY CANYON	-707	3666	3666	SANDSTONE, SILTSTONE	NATURAL GAS, OIL, OTHER : Brine	N
512920	BRUSHY CANYON	-1946	4905	4921	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL, OTHER : Brine	N
512921	BONE SPRING	-3525	6484	6535	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL	Y
512922	BONE SPRING 1ST	-4512	7471	7544	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL	Y
512923	BONE SPRING 2ND	-5277	8236	8327	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL	Y
512924	BONE SPRING 3RD	-6382	9341	9456	LIMESTONE, SANDSTONE, SILTSTONE	NATURAL GAS, OIL	Y
512925	WOLFCAMP	-6745	9704	9822	SANDSTONE, SILTSTONE	NATURAL GAS, OIL	Y

Section 2 - Blowout Prevention

Pressure Rating (PSI): 10M

Rating Depth: 10715

Equipment: 13-5/8" 5M/10M Annular, Blind Ram, Double Ram

Requesting Variance? YES

Variance request: OXY requests a variance for the use of a flexible choke line from the BOP to Choke Manifold.

Testing Procedure: Oxy will utilize a 5M annular with a 10M BOPE stack. The BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded

Operator Name: OXY USA INCORPORATED

Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

all the components installed will be functional and tested. Pipe rams will be operationally checked each 24 hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment will include a Kelly cock and floor safety valve (inside BOP) and choke lines and choke manifold. A multibowl or a unionized multibowl wellhead system will be employed. The wellhead and connection to the BOPE will meet all API 6A requirements. The BOP will be tested per Onshore Order #2 after installation on the surface casing which will cover testing requirements for a maximum of 30 days. If any seal subject to test pressure is broken the system must be tested. We will test the flange connection of the wellhead with a test port that is directly in the flange. We are proposing that we will run the wellhead through the rotary prior to cementing surface casing as discussed with the BLM on October 8, 2015. BOP Break Testing Request Oxy requests permission to adjust the BOP break testing requirements as per the agreement reached in the OXY/BLM meeting on September 5, 2019. A separate sundry will be sent prior to spud that reflects the pad based break testing plan. BOP break test under the following conditions: After a full BOP test is conducted When skidding to drill an intermediate section where ICP is set into the third Bone Spring or shallower. When skidding to drill a production section that does not penetrate into the third Bone Spring or deeper. If the kill line is broken prior to skid, two tests will be performed. 1) Wellhead flange, co-flex hose, kill line connections and upper pipe rams 2) Wellhead flange, HCR valve, check valve, upper pipe rams If the kill line is not broken prior to skid, only one test will be performed. 1) Wellhead flange, co-flex hose, check valve, upper pipe rams

Choke Diagram Attachment:

RadiusCC6_7FdCom52H_ChkManifold_20190812132203.pdf

BOP Diagram Attachment:

RadiusCC6_7FdCom52H_BOP_20190812132215.pdf

RadiusCC6_7FdCom52H_FlexHoseCert_20190812132227.pdf

													1										
Casing ID	String Type	Hole Size	Csg Size	Condition	Standard	Tapered String	Top Set MD	Bottom Set MD	Top Set TVD	Bottom Set TVD	Top Set MSL	Bottom Set MSL	Calculated casing	length MD	Grade	Weight	Joint Type	Collapse SF	Burst SF	Joint SF Type	Joint SF	Body SF Type	Body SF
1	SURFACE	14.7 5	10.75	NEW	API	N	0	476	0	476	2959	2483	476		J-55	40.5	BUTT	1.12 5	1.2	BUOY	1.4	BUOY	1.4
2	INTERMED IATE	9.87 5	7.625	NEW	API	N	0	10240	0	10120	3101	-7161	1024	40	HCL -80	26.4	BUTT	1.12 5	1.2	BUOY	1.4	BUOY	1.4
3	PRODUCTI ON	6.75	5.5	NEW	API	N	0	21644	0	10715	3101	-7756	2164	44	P- 110	20	OTHER - DQX/SFTO RQ/DQWTO RO	1.12 5	1.2	BUOY	1.4	BUOY	1.4

Section 3 - Casing

Casing Attachments

Operator Name: OXY USA INCORPORATED Well Name: RADIUS CC 6-7 FEDERAL COM Well Nu	umber: 52H
Casing Attachments	
Casing ID: 1 String Type:SURFACE Inspection Document:	
Spec Document:	
Tapered String Spec:	
Casing Design Assumptions and Worksheet(s): RadiusCC6_7FdCom52H_CsgCriteria_20190812132325.pd	f
Casing ID: 2 String Type: INTERMEDIATE Inspection Document:	
Spec Document:	
Tapered String Spec:	
Casing Design Assumptions and Worksheet(s): RadiusCC6_7FdCom52H_CsgCriteria_20190812132358.pd	df
Casing ID: 3 String Type: PRODUCTION Inspection Document:	
Spec Document:	
Tapered String Spec:	
Casing Design Assumptions and Worksheet(s):	
RadiusCC6_7FdCom52H_CsgCriteria_20190812132427.pd	df
RadiusCC6_7FdCom52H_5.5_x_26_P110_CYHP_TMK_U	PTORQ_SFW_20200207133100.pdf
RadiusCC6_7FdCom52H_5_x_21.4_P110_CYHP_TMK_U	PTORQ_DQW_20200207133105.pdf

Operator Name: OXY USA INCORPORATED

Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

Section	4 - Ce	emen	t	-							
String Type	Lead/Tail	Stage Tool Depth	Top MD	Bottom MD	Quantity(sx)	Yield	Density	Cu Ft	Excess%	Cement type	Additives
SURFACE	Lead		0	476	385	1.33	14.8	512	100	CIC	Accelerator

INTERMEDIATE	Lead	0	5155	634	1.92	12.9	1278	10	CIC	Accelerator
INTERMEDIATE	Tail	5155	1024 0	702	1.65	13.2	1158	5	СІН	Retarder, Dispersant, Salt
PRODUCTION	Lead	9740	2164 4	1141	1.38	13.2	1575	20	СІН	Retarder, Dispersant, Salt

Section 5 - Circulating Medium

Mud System Type: Closed

Will an air or gas system be Used? NO

Description of the equipment for the circulating system in accordance with Onshore Order #2:

Diagram of the equipment for the circulating system in accordance with Onshore Order #2:

Describe what will be on location to control well or mitigate other conditions: Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times. The following is a general list of products: Barite, Bentonite, Gypsum, Lime, Soda Ash, Caustic Soda, Nut Plug, Cedar Fiber, Cotton Seed Hulls, Drilling Paper, Salt Water Clay, CACL2.

Describe the mud monitoring system utilized: PVT/MD Totco/Visual Monitoring

Circulating Medium Table

Top Depth	Bottom Depth	Mud Type	Min Weight (Ibs/gal)	Max Weight (Ibs/gal)	Density (lbs/cu ft)	Gel Strength (lbs/100 sqft)	Hd	Viscosity (CP)	Salinity (ppm)	Filtration (cc)	Additional Characteristics
0	476	WATER-BASED MUD	8.6	8.8							

Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

Top Depth	Bottom Depth	Mud Type	Min Weight (lbs/gal)	Max Weight (Ibs/gal)	Density (lbs/cu ft)	Gel Strength (lbs/100 sqft)	Hd	Viscosity (CP)	Salinity (ppm)	Filtration (cc)	Additional Characteristics
476	1024 0	OTHER : Saturated Brine Based Mud and/or Oil Based Mud	8	10							
1024 0	2164 4	OTHER : Water Based and/or oil Based Mud	9.5	13							

Section 6 - Test, Logging, Coring

List of production tests including testing procedures, equipment and safety measures:

GR from TD to surface (horizontal well - vertical portion of hole). Mud log from intermediate casing shoe to TD.

List of open and cased hole logs run in the well:

GAMMA RAY LOG, MUD LOG/GEOLOGICAL LITHOLOGY LOG,

Coring operation description for the well:

No coring is planned at this time.

Section 7 - Pressure

Anticipated Bottom Hole Pressure: 7244

Anticipated Surface Pressure: 4886

Anticipated Bottom Hole Temperature(F): 166

Anticipated abnormal pressures, temperatures, or potential geologic hazards? NO

Describe:

Contingency Plans geoharzards description:

Contingency Plans geohazards attachment:

Hydrogen Sulfide drilling operations plan required? YES

Hydrogen sulfide drilling operations plan:

RadiusCC6_7FdCom52H_H2S2_20190812132932.pdf RadiusCC6_7FdCom52H_H2S3ECL_20190812132932.pdf RadiusCC6_7FdCom52H_H2S1_20190812132932.pdf

Operator Name: OXY USA INCORPORATED

Well Name: RADIUS CC 6-7 FEDERAL COM

Well Number: 52H

Section 8 - Other Information

Proposed horizontal/directional/multi-lateral plan submission:

RadiusCC6_7FdCom52H_DirectPlan_20190812133003.pdf

RadiusCC6_7FdCom52H_DirectPlot_20190812133003.pdf

Other proposed operations facets description:

OXY requests the option to set casing shallower yet still below the salts if losses or hole conditions require this. Cement volumes may be adjusted if casing is set shallower and a DV tool may be run in case hole conditions merit pumping a second stage cement job to comply with permitted top of cement. If cement circulated to surface during first stage, we will drop a cancelation cone and not pump the second stage.

OXY requests the option to run production casing with DQX, SF TORQ, and/or DQW TORQ connections to accommodate hole conditions or drilling operations.

OXY requests to pump a two stage Intermediate casing cement job with the first stage being pumped conventionally with the calculated TOC @ the Brushy Canyon and the second stage performed as a bradenhead squeeze with planned cement from the top of the Brushy Canyon to Surface.

OXY requests a variance to cement the 7-5/8" intermediate casing string offline, see attached for additional information.

Annular Clearance Variance Request

As per the agreement reached in the OXY/BLM meeting on Feb 22, 2018, OXY requests permission to allow deviation from the 0.422 annular clearance requirement from Onshore Order #2 under the following conditions:

1. Annular clearance to meet or exceed 0.422 between intermediate casing ID and production casing coupling only on the first 500 overlap between both casings.

2. Annular clearance less than 0.422 is acceptable for the curve and lateral portions of the production open hole section.

Well will be drilled with a walking/skidding operation. Plan to drill the multiple well pad in batch by section: all surface sections, intermediate sections and production sections. The wellhead will be secured with a night cap whenever the rig is not over the well.

OXY requests the option to contract a Surface Rig to drill, set surface casing, and cement for this well. If the timing between rigs is such that OXY would not be able to preset surface, the Primary Rig will MIRU and drill the well in its entirety per the APD. See attached for additional spudder rig information.

Oxy requests permission to adjust the CBL requirement after bradenhead cement jobs, on 7-5/8 intermediate casings, as per the agreement reached in the OXY/BLM meeting on September 5, 2019. Three string wells:

CBL will be required on one well per pad

If the pumped volume of cement is less than permitted in the APD, BLM will be notified and a CBL may be run Echometer will be used after bradenhead cement job to determine TOC before pumping top-out cement

Other proposed operations facets attachment:

RadiusCC6_7FdCom52H_GasCapPlan_20190812133133.pdf

RadiusCC6_7FdCom52H_SpudRigData_20190812133143.pdf

RadiusCC6_7FdCom52H_DrillPlan10_DayLetter_20200207133820.pdf

Other Variance attachment:

RadiusCC6_7FdCom52H_OfflineCmtgDetail_20190812133156.pdf



Permian Drilling Hydrogen Sulfide Drilling Operations Plan New Mexico

<u>Scope</u>

This contingency plan establishes guidelines for the public, all company employees, and contract employees who's work activities may involve exposure to hydrogen sulfide (H2S) gas.

While drilling this well, it is possible to encounter H2S bearing formations. At all times, the first barrier to control H2S emissions will be the drilling fluid, which will have a density high enough to control influx.

Objective

- 1. Provide an immediate and predetermined response plan to any condition when H2S is detected. All H2S detections in excess of 10 parts per million (ppm) concentration are considered an Emergency.
- 2. Prevent any and all accidents, and prevent the uncontrolled release of hydrogen sulfide into the atmosphere.
- 3. Provide proper evacuation procedures to cope with emergencies.
- 4. Provide immediate and adequate medical attention should an injury occur.

- 1 -

Discussion

Implementation:

Emergency response Procedure:

Emergency equipment Procedure:

Training provisions:

Drilling emergency call lists:

Briefing:

Public safety:

Check lists:

General information:

This plan with all details is to be fully implemented before drilling to <u>commence</u>.

This section outlines the conditions and denotes steps to be taken in the event of an emergency.

This section outlines the safety and emergency equipment that will be required for the drilling of this well.

This section outlines the training provisions that must be adhered to prior to drilling.

Included are the telephone numbers of all persons to be contacted should an emergency exist.

This section deals with the briefing of all people involved in the drilling operation.

Public safety personnel will be made aware of any potential evacuation and any additional support needed.

Status check lists and procedural check lists have been included to insure adherence to the plan.

A general information section has been included to supply support information.

Hydrogen Sulfide Training

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing drilling operations on the well:

- 1. The hazards and characteristics of H2S.
- 2. Proper use and maintenance of personal protective equipment and life support systems.
- 3. H2S detection.
- 4. Proper use of H2S detectors, alarms, warning systems, briefing areas, evacuation procedures and prevailing winds.
- 5. Proper techniques for first aid and rescue procedures.
- 6. Physical effects of hydrogen sulfide on the human body.
- 7. Toxicity of hydrogen sulfide and sulfur dioxide.
- 8. Use of SCBA and supplied air equipment.
- 9. First aid and artificial respiration.
- 10. Emergency rescue.

In addition, supervisory personnel will be trained in the following areas:

- 1. The effects of H2S on metal components. If high tensile strength tubular is to be used, personnel will be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling a well, blowout prevention and well control procedures.
- 3. The contents and requirements of the H2S Drilling Operations Plan.

H2S training refresher must have been taken within one year prior to drilling the well. Specifics on the well to be drilled will be discussed during the pre-spud meeting. H2S and well control (choke) drills will be performed while drilling the well, at least on a weekly basis. This plan shall be available in the well site. All personnel will be required to carry the documentation proving that the H2S training has been taken.

Service company and visiting personnel

- A. Each service company that will be on this well will be notified if the zone contains H2S.
- B. Each service company must provide for the training and equipment of their employees before they arrive at the well site.
- C. Each service company will be expected to attend a well site briefing

Emergency Equipment Requirements

1. <u>Well control equipment</u>

Co. Sec

The well shall have hydraulic BOP equipment for the anticipated pressures. Equipment is to be tested on installation and follow Oxy Well Control standard, as well as BLM Onshore Order #2.

Special control equipment:

- A. Hydraulic BOP equipment with remote control on ground. Remotely operated choke.
- B. Rotating head
- C. Gas buster equipment shall be installed before drilling out of surface pipe.

2. Protective equipment for personnel

- A. Four (4) 30-minute positive pressure air packs (2 at each briefing area) on location.
- B. Adequate fire extinguishers shall be located at strategic locations.
- C. Radio / cell telephone communication will be available at the rig.
 - Rig floor and trailers.
 - Vehicle.

3. <u>Hydrogen sulfide sensors and alarms</u>

- A. H2S sensor with alarms will be located on the rig floor, at the bell nipple, and at the flow line. These monitors will be set to alarm at 10 ppm with strobe light, and audible alarm.
- B. Hand operated detectors with tubes.
- C. H2S monitor tester (to be provided by contract Safety Company.)
- D. There shall be one combustible gas detector on location at all times.

4. <u>Visual Warning Systems</u>

A. One sign located at each location entrance with the following language:

Caution – potential poison gas Hydrogen sulfide No admittance without authorization

- 4 -

Wind sock – wind streamers:

- A. One 36" (in length) wind sock located at protection center, at height visible from rig floor.
- B. One 36" (in length) wind sock located at height visible from pit areas.

Condition flags

A. One each condition flag to be displayed to denote conditions.

green – normal conditions yellow – potential danger red – danger, H2S present

B. Condition flag shall be posted at each location sign entrance.

5. <u>Mud Program</u>

The mud program is designed to minimize the risk of having H2S and other formation fluids at surface. Proper mud weight and safe drilling practices will be applied. H2S scavengers will be used to minimize the hazards while drilling. Below is a summary of the drilling program.

Mud inspection devices:

Garrett gas train or hatch tester for inspection of sulfide concentration in mud system.

- 6. <u>Metallurgy</u>
 - A. Drill string, casing, tubing, wellhead, blowout preventers, drilling spools or adapters, kill lines, choke manifold, lines and valves shall be suitable for the H2S service.
 - B. All the elastomers, packing, seals and ring gaskets shall be suitable for H2S service.
- 7. <u>Well Testing</u>

No drill stem test will be performed on this well.

8. <u>Evacuation plan</u>

Evacuation routes should be established prior to well spud for each well and discussed with all rig personnel.

- 9. <u>Designated area</u>
 - A. Parking and visitor area: all vehicles are to be parked at a predetermined safe distance from the wellhead.
 - B. There will be a designated smoking area.
 - C. Two briefing areas on either side of the location at the maximum allowable distance from the well bore so they offset prevailing winds perpendicularly, or at a 45-degree angle if wind direction tends to shift in the area.

Emergency procedures

- A. In the event of any evidence of H2S level above 10 ppm, take the following steps:
 - 1. The Driller will pick up off bottom, shut down the pumps, slow down the pipe rotation.
 - 2. Secure and don escape breathing equipment, report to the upwind designated safe briefing / muster area.
 - 3. All personnel on location will be accounted for and emergency search should begin for any missing, the Buddy System will be implemented.
 - 4. Order non-essential personnel to leave the well site, order all essential personnel out of the danger zone and upwind to the nearest designated safe briefing / muster area.
 - 5. Entrance to the location will be secured to a higher level than our usual "Meet and Greet" requirement, and the proper condition flag will be displayed at the entrance to the location.
 - 6. Take steps to determine if the H2S level can be corrected or suppressed and, if so, proceed as required.
- B. If uncontrollable conditions occur:
 - 1. Take steps to protect and/or remove any public in the down-wind area from the rig – partial evacuation and isolation. Notify necessary public safety personnel and appropriate regulatory entities (i.e. BLM) of the situation.

- 6 -

- 2. Remove all personnel to the nearest upwind designated safe briefing / muster area or off location.
- 3. Notify public safety personnel of safe briefing / muster area.
- 4. An assigned crew member will blockade the entrance to the location. No unauthorized personnel will be allowed entry to the location.
- 5. Proceed with best plan (at the time) to regain control of the well. Maintain tight security and safety procedures.
- C. Responsibility:
 - 1. Designated personnel.
 - a. Shall be responsible for the total implementation of this plan.
 - b. Shall be in complete command during any emergency.
 - c. Shall designate a back-up.

All personnel:

- 1. On alarm, don escape unit and report to the nearest upwind designated safe briefing / muster area upw
- 2. Check status of personnel (buddy system).
- 3. Secure breathing equipment.
- 4. Await orders from supervisor.

Drill site manager:

- 1. Don escape unit if necessary and report to nearest upwind designated safe briefing / muster area.
- 2. Coordinate preparations of individuals to return to point of release with tool pusher and driller (using the buddy system).
- 3. Determine H2S concentrations.
- 4. Assess situation and take control measures.

Tool pusher:

- 1. Don escape unit Report to up nearest upwind designated safe briefing / muster area.
- 2. Coordinate preparation of individuals to return to point of release with tool pusher drill site manager (using the buddy system).
- 3. Determine H2S concentration.
- 4. Assess situation and take control measures.

Driller:

1. Don escape unit, shut down pumps, continue

		rotating DP.
	2.	Check monitor for point of release.
	3.	Report to nearest upwind designated safe briefing / muster area.
	4.	Check status of personnel (in an attempt to rescue, use the buddy system).
	5.	Assigns least essential person to notify Drill Site
		Manager and tool pusher by quickest means in case of their absence.
	6.	Assumes the responsibilities of the Drill Site
		Manager and tool pusher until they arrive should they be absent.
Derrick man Floor man #1 Floor man #2	1.	Will remain in briefing / muster area until instructed by supervisor.
Mud engineer:	1.	Report to nearest upwind designated safe briefing / muster area.
	2.	When instructed, begin check of mud for ph and H2S level. (Garett gas train.)
Safety personnel:	1.	Mask up and check status of all personnel and secure operations as instructed by drill site manager.

<u>Taking a kick</u>

When taking a kick during an H2S emergency, all personnel will follow standard Well control procedures after reporting to briefing area and masking up.

Open-hole logging

All unnecessary personnel off floor. Drill Site Manager and safety personnel should monitor condition, advise status and determine need for use of air equipment.

Running casing or plugging

Following the same "tripping" procedure as above. Drill Site Manager and safety personnel should determine if all personnel have access to protective equipment.

Ignition procedures

The decision to ignite the well is the responsibility of the operator (Oxy Drilling Management). The decision should be made only as a last resort and in a situation where it is clear that:

- 1. Human life and property are endangered.
- 2. There is no hope controlling the blowout under the prevailing conditions at the well.

Instructions for igniting the well

- 1. Two people are required for the actual igniting operation. They must wear self-contained breathing units and have a safety rope attached. One man (tool pusher or safety engineer) will check the atmosphere for explosive gases with the gas monitor. The other man is responsible for igniting the well.
- 2. Primary method to ignite: 25 mm flare gun with range of approximately 500 feet.
- 3. Ignite upwind and do not approach any closer than is warranted.
- 4. Select the ignition site best for protection, and which offers an easy escape route.
- 5. Before firing, check for presence of combustible gas.
- 6. After lighting, continue emergency action and procedure as before.
- 7. All unassigned personnel will remain in briefing area until instructed by supervisor or directed by the Drill Site Manager.

<u>Remember</u>: After well is ignited, burning hydrogen sulfide will convert to sulfur dioxide, which is also highly toxic. **<u>Do not assume the area is safe after the well is</u> ignited.**

Status check list

Note: All items on this list must be completed before drilling to production casing point.

- 1. H2S sign at location entrance.
- 2. Two (2) wind socks located as required.
- 3. Four (4) 30-minute positive pressure air packs (2 at each Briefing area) on location for all rig personnel and mud loggers.
- 4. Air packs inspected and ready for use.
- 5. Cascade system and hose line hook-up as needed.
- 6. Cascade system for refilling air bottles as needed.
- 7. Condition flag on location and ready for use.
- 8. H2S detection system hooked up and tested.
- 9. H2S alarm system hooked up and tested.
- 10. Hand operated H2S detector with tubes on location.
- 11. 1-100' length of nylon rope on location.
- 12. All rig crew and supervisors trained as required.
- 13. All outside service contractors advised of potential H2S hazard on well.
- 14. No smoking sign posted and a designated smoking area identified.
- 15. Calibration of all H2S equipment shall be noted on the IADC report.

Checked by:	Date:	
	- 10 -	

Procedural check list during H2S events

Perform each tour:

- 1. Check fire extinguishers to see that they have the proper charge.
- 2. Check breathing equipment to ensure that it in proper working order.
- 3. Make sure all the H2S detection system is operative.

Perform each week:

- 1. Check each piece of breathing equipment to make sure that demand or forced air regulator is working. This requires that the bottle be opened and the mask assembly be put on tight enough so that when you inhale, you receive air or feel air flow.
- 2. BOP skills (well control drills).
- 3. Check supply pressure on BOP accumulator stand by source.
- 4. Check breathing equipment mask assembly to see that straps are loosened and turned back, ready to put on.
- 5. Check pressure on breathing equipment air bottles to make sure they are charged to full volume. (Air quality checked for proper air grade "D" before bringing to location)
- 6. Confirm pressure on all supply air bottles.
- 7. Perform breathing equipment drills with on-site personnel.
- 8. Check the following supplies for availability.
 - A. Emergency telephone list.
 - B. Hand operated H2S detectors and tubes.

General evacuation plan

- 1. When the company approved supervisor (Drill Site Manager, consultant, rig pusher, or driller) determines the H2S gas cannot be limited to the well location and the public will be involved, he will activate the evacuation plan.
- 2. Drill Site Manager or designee will notify local government agency that a hazardous condition exists and evacuation needs to be implemented.
- 3. Company or contractor safety personnel that have been trained in the use of H2S detection equipment and self-contained breathing equipment will monitor H2S concentrations, wind directions, and area of exposure. They will delineate the outer perimeter of the hazardous gas area. Extension to the evacuation area will be determined from information gathered.
- 4. Law enforcement personnel (state police, police dept., fire dept., and sheriff's dept.) Will be called to aid in setting up and maintaining road blocks. Also, they will aid in evacuation of the public if necessary.
- 5. After the discharge of gas has been controlled, company safety personnel will determine when the area is safe for re-entry.

<u>Important:</u> Law enforcement personnel will not be asked to come into a contaminated area. Their assistance will be limited to uncontaminated areas. Constant radio contact will be maintained with them.

Emergency actions

Well blowout – if emergency

- 1. Evacuate all personnel to "Safe Briefing / Muster Areas" or off location if needed.
- 2. If sour gas evacuate rig personnel.
- 3. If sour gas evacuate public within 3000 ft radius of exposure.
- 4. Don SCBA and shut well in if possible using the buddy system.
- 5. Notify Drilling Superintendent and call 911 for emergency help (fire dept and ambulance) if needed.
- 6. Implement the Blowout Contingency Plan, and Drilling Emergency Action Plan.
- 6. Give first aid as needed.

Person down location/facility

- 1. If immediately possible, contact 911. Give location and wait for confirmation.
- 2. Don SCBA and perform rescue operation using buddy system.

Toxic effects of hydrogen sulfide

Hydrogen sulfide is extremely toxic. The acceptable ceiling concentration for eight-hour exposure is 10 ppm, which is .001% by volume. Hydrogen sulfide is heavier than air (specific gravity -1.192) and colorless. It forms an explosive mixture with air between 4.3 and 46.0 percent by volume. Hydrogen sulfide is almost as toxic as hydrogen cyanide and is between five and six times more toxic than carbon monoxide. Toxicity data for hydrogen sulfide and various other gases are compared in table i. Physical effects at various hydrogen sulfide exposure levels are shown in table ii.

Table i Toxicity of various gases

Common	Chemical	Specific	Threshold	Hazardous	Lethal concentration
name	formula	gravity	limit	limit	(3)
		(sc=1)	(1)	(2)	
Hydrogen	Hcn	0.94	10 ppm	150 ppm/hr	300 ppm
Cyanide			11		
Hydrogen	H2S	1.18	10 ppm	250 ppm/hr	600 ppm
Sulfide					
Sulfur	So2	2.21	5 ppm	-	1000 ppm
Dioxide			11		11
Chlorine	C12	2.45	1 ppm	4 ppm/hr	1000 ppm
Carbon	Co	0.97	50 ppm	400 ppm/hr	1000 ppm
Monoxide					11
Carbon	Co2	1.52	5000 ppm	5%	10%
Dioxide					
Methane	Ch4	0.55	90,000 ppm	Combustibl	e above 5% in air

1) threshold limit – concentration at which it is believed that all workers may be repeatedly exposed day after day without adverse effects.

2) hazardous limit – concentration that will cause death with short-term exposure.

3) lethal concentration – concentration that will cause death with short-term exposure.

Toxic effects of hydrogen sulfide

Table ii Physical effects of hydrogen sulfide

		Concentration
Percent (%)	<u> </u>	Grains
	_	100 std. Ft3*
0.001	<10	00.65

Physical effects

Obvious and unpleasant odor.

- 14 -

0.002	10	01.30	Safe for 8 hours of exposure.
0.010	100	06.48	Kill smell in $3 - 15$ minutes. May sting eyes and throat.
0.020	200	12.96	Kills smell shortly; stings eyes and throat.
0.050	500	32.96	Dizziness; breathing ceases in a few minutes; needs prompt artificial respiration.
0.070	700	45.36	Unconscious quickly; death will result if not rescued promptly.
0.100	1000	64.30	Unconscious at once; followed by death within minutes.

*at 15.00 psia and 60'f.

Use of self-contained breathing equipment (SCBA)

- 1. Written procedures shall be prepared covering safe use of SCBA's in dangerous atmosphere, which might be encountered in normal operations or in emergencies. Personnel shall be familiar with these procedures and the available SCBA.
- 2 SCBA's shall be inspected frequently at random to insure that they are properly used, cleaned, and maintained.
- 3. Anyone who may use the SCBA's shall be trained in how to insure proper facepiece to face seal. They shall wear SCBA's in normal air and then wear them in a test atmosphere. (note: such items as facial hair {beard or sideburns} and eyeglasses will not allow proper seal.) Anyone that may be reasonably expected to wear SCBA's should have these items removed before entering a toxic atmosphere. A special mask must be obtained for anyone who must wear eyeglasses or contact lenses.
- 4. Maintenance and care of SCBA's:
 - a. A program for maintenance and care of SCBA's shall include the following:
 - 1. Inspection for defects, including leak checks.
 - 2. Cleaning and disinfecting.
 - 3. Repair.
 - 4. Storage.
 - b. Inspection, self-contained breathing apparatus for emergency use shall be inspected monthly.
 - 1. Fully charged cylinders.
 - 2. Regulator and warning device operation.
 - 3. Condition of face piece and connections.
 - 4. Rubber parts shall be maintained to keep them pliable and prevent deterioration.
 - c. Routinely used SCBA's shall be collected, cleaned and disinfected as frequently as necessary to insure proper protection is provided.
- 5. Persons assigned tasks that requires use of self-contained breathing equipment shall be certified physically fit (medically cleared) for breathing equipment usage at least annually.
- 6. SCBA's should be worn when:
 - A. Any employee works near the top or on top of any tank unless test reveals less than 10 ppm of H2S.

- B. When breaking out any line where H2S can reasonably be expected.
- C. When sampling air in areas to determine if toxic concentrations of H2S exists.
- D. When working in areas where over 10 ppm H2S has been detected.
- E. At any time there is a doubt as to the H2S level in the area to be entered.

<u>Rescue</u> <u>First aid for H2S poisoning</u>

Do not panic!

Remain calm – think!

- 1. Don SCBA breathing equipment.
- 2. Remove victim(s) utilizing buddy system to fresh air as quickly as possible. (go up-wind from source or at right angle to the wind. Not down wind.)
- 3. Briefly apply chest pressure arm lift method of artificial respiration to clean the victim's lungs and to avoid inhaling any toxic gas directly from the victim's lungs.
- 4. Provide for prompt transportation to the hospital, and continue giving artificial respiration if needed.
- 5. Hospital(s) or medical facilities need to be informed, before-hand, of the possibility of H2S gas poisoning no matter how remote the possibility is.
- 6. Notify emergency room personnel that the victim(s) has been exposed to H2S gas.

Besides basic first aid, everyone on location should have a good working knowledge of artificial respiration.

Revised CM 6/27/2012

and the second the second s	the second s
A A A A A A A A A A A A A A A A A A A	a set in the set of the
OXY Permian Delaware NM Basin Drilling & Comple	tions Incident Reporting
OVV Branching Catala Toons Hatting Notification	1. A BAR SALE AND THE CARE AND AND A COMPANY
UXI Ferman Crisis ream rounce nouncation	Remain and a second
the second se	Land and any state of the state
	·····································
Person	Office Phone Cell/Mobile Phone

Drilling & Completions Department	Contraction of the second s		and a first of the second s
Drilling & Completions Manager: John Willis	Houston	(713) 366-5556	(713) 259-1417
Drilling Superintendent: Simon Benavides	Houston	(713) 215-7403	(832) 528-3547
Completions Superintendent: Chris Winter	Houston	(713) 366-5212	(806) 239-8774
Drilling Eng. Supervisor: Diego Tellez	Houston	(713) 350-4602	(713) 303-4932
Drilling Eng. Supervisor: Randy Neel	Houston	(713) 215-7987	(713) 517-5544
Completions Eng. Supervisor: Evan Hinkel	Houston	(713) 366-5436	(281) 236-6153
Drilling & Completions HES Lead. Ryan Green	Houston	713-336-5753	281-520-5216
Drilling & Completions HES Advisor:Kenny Williams	Carlsbad	(432) 686-1434	(337) 208-0911
Drilling & Completions HES Advisor:Kyle Holden	Carlsbad	(432) 686-1435	(661) 369-5328
Drilling & Completions HES Advisor Sr:Dave Schmidt	Carlsbad		(559) 310-8572
Drilling & Completions HES Advisor. :Seth Doyle	Carlsbad		(337) 499-0756
HES / Enviromental & Regulatory Department	Location	Office	Cell Phone
[1] A. A. S. A.	and the second second	<u></u>	Carlos Proventing and the second
Jon Hamil-HES Manager	Houston	(713) 497-2494	(832) 537-9885
Mark Birk-HES Manager	Houston	(713) 350-4615	(949) 413-3127
Austin Tramell	Midland	(432) 699-4208	(575) 499-4919
Rico Munoz	Midland	(432) 699-8366	(432) 803-4116
Amber DuckWorth	Midland		(832) 966-1879
Kelley Montgomery- Regulatory Manager	Houston	(713) 366-5716	(832) 454-8137
Sandra Musallam -Regulatory Lead	Houston	+1 (713) 366-5106	+1 (713) 504-8577
Bishop, Steve-DOT Pipeline Coordinator	Midland	432-685-5614	
Wilson, Dusty-Safety Advisor	Midland	432-685-5771	(432) 254-2336
John W Dittrich Eniromental Advisor	Midland		(575) 390-2828
William (Jack) Calhoun-Environmental Lead	Houston	+713 (350) 4906	(281) 917-8571
Robert Barrow-Risk Engineer Manager	Houston	(713) 366-5611	(832) 867-5336
Sarah Holmes-HSE Cordinator	Midland	432-685-5758	
Administrative	Location	Office	·····································
Sarah Holmes	Midland	432-685-5830	
Robertson, Debbie	Midland	432-685-5812	
Laci Hollaway	Midland	(432) 685-5716	(432) 631-6341
Administrative	Location	Office	an a
Rosalinda Escajeda	Midland	432-685-5831	

Person	Location	i na seconda da	Office Phone	Cell/Mobile Phone
Moreno, Leslie (contract)	Hobbs		575-397-8247	
Sehon, Angela (contractor)	Levelland		806-894-8347	
Vasquez, Claudia (contractor)	North Cowden	Í	432-385-3120	
XstrémeMD	Locatio	n. Marina	Office	a Brite in the of the second second in the second
Medical Case Management	Orla, TX		(337) 205-9314	
Axiom Medical Consulting	Locatio	h . Se	Office	and the second
Medical Case Management			(877) 502-9466	
·				
Regulatory Agencies		· 金水市	ある 二部の 二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	and a state of the second s
Bureau of Land Management	Carlsbad, NM	*	(505) 887-6544	
Bureau of Land Management	Hobbs, NM		(505) 393-3612	
Bureau of Land Management	Roswell, NM) k	(505) 393-3612	
Bureau of Land Management	Santa Fe, NM	-	(505) 988-6030	
DOT Juisdictional Pipelines-Incident Reporting New			(505) 827-3549	
Mexico Public Regulaion Commission	Santa Fe, NM		(505) 490-2375	
DOT Juisdictional Pipelines-Incident Reporting Texas	Austin TX		(512) 463-6788	
EPA Hot Line	Dallas, Texas		(214) 665-6444	
Federal OSHA, Area Office	Lubbock, Texa	s	(806) 472-7681	· · · · · · · · · · · · · · · · · · ·
National Response Center	Washington, D	. C.	(800) 424-8802	
National Infrastructure Coordinator Center	,		(202) 282-9201	
New Mexico Air Ouality Bureau	Santa Fe. NM		(505) 827-1494	
New Merries Oil Concernation Division			(505) 748 1092	After Hours (505) 370-
New Mexico Oil Conservation Division	Artesia, NM		(505) 748-1283	/545
New Mexico Oil Conservation Division	Hobbs, NM		(505) 393-6161	
New Mexico Oil Conservation Division	Santa Fe, NM	-	(505) 471-1068	
New Mexico OCD Environmental Bureau	Santa Fe, NM		(505) 4/6-34/0	
New Mexico Environmental Department	HODDS, NM		(505) 827-9329	
NM State Emergency Response Center	Santa Fe, NM		(305) 827-9222	
Railroad Commission of TX	District 1 San A	Amonto	(210) 227-1313	
Pailwood Commission of TX	District 9 9A N	Angelo	(323) 637-7430	
Taxas Emarganay Despanse Center	Austin TV	viluiano	(432) 084-3381	
TOFO Air	Region 2 Lukh	ock TV	(312) 403-7727	
TCEO Water/Waste/Air	Region 3 Abile	ne TY	(325) 698-9674	
TCFO Water/Waste/Air	Region 7 Midle	and TV	(432) 570 1350	
TCEO Water/Waste/Air	Region 9 San A	ntonio	(512) 734-7981	
TCEO Water/Waste/Air	Region 9 San A	ngelo	(325) 655-0470	
	region o ball r		(323) (33-3473	
Medical Facilities			lang the Second Contraction of the second contract of the second contract of the second contract of the second	ال المراجع المراجع المراجع المراجع المراجع المراجع المراجع المراجع المراجع المراجع المراجع المراجع
Abernathy Medical Clinic	Abernathy, TX		(806) 298-2524	
Alliance Hospital	Odessa, TX		(432) 550-1000	
Artesia General Hospital	Artesia, NM		(505) 748-3333	
Brownfield Regional Medical Center	Brownfield, TX	K -	(806) 637-3551	
			1	•

.

Person	Location	Office Phone Cell/Mobile Phone
Cogdell Memorial Hospital	Snyder, TX	(325) 573-6374
Covenant Hospital Levelland	Levelland, TX	(806) 894-4963
Covenant Medical Center	Lubbock, TX 🔍	(806) 725-1011
Covenant Medical Center Lakeside	Lubbock, TX	(806) 725-6000
Covenant Family Health	Synder, TX	(325) 573-1300
Crockett County Hospital	Ozona, TX	(325) 392-2671
Guadalupe Medical Center	Carlsbad, NM	(505) 887-6633
Lea Regional Hospital	Hobbs, NM	(505) 492-5000
McCamey Hospital	McCamey, TX	(432) 652-8626
Medical Arts Hospital	Lamesa, TX	(806) 872-2183
Medical Center Hospital	Odessa, TX	(432) 640-4000
Medi Center Hospital	San Angelo, TX	(325) 653-6741
Memorial Hospital	Ft. Stockton	(432) 336-2241
Memorial Hospital	Seminole, TX	(432) 758-5811
Midland Memorial Hospital	Midland, TX	(432) 685-1111
Nor-Lea General Hospital	Lovington, NM	(505) 396-6611
Odessa Regional Hospital	Odessa, TX	(432) 334-8200
Permian General Hospital	Andrews, TX	(432) 523-2200
Reagan County Hospital	Big Lake, TX	(325) 884-2561
Reeves County Hospital	Pecos, TX	(432) 447-3551
Shannon Medical Center	San Angelo, TX	(325) 653-6741
Union County General Hospital	Clayton, NM	(505) 374-2585
University Medical Center	Lubbock, TX	(806) 725-8200
Val Verde Regional Medical Center	Del Rio, TX	(830) 775-8566
Ward Memorial Hospital	Monahans, TX	(432) 943-2511
Yoakum County Hospital	Denver City, TX	(806) 592-5484
Law Enforcement - Sheriff		
Andrews Cty Sheriff's Department	Andrews County(And	(432) 523-5545
Crane Cty Sheriff's Department	Crane, County (Crane)	(432) 558-3571
Crockett Cty Sheriff's Department	Crockett County (Ozo:	r (325) 392-2661
Dawson Cty Sheriff's Department	Dawson County (Lam	e (806) 872-7560
Ector Cty Sheriff's Department	Ector County (Odessa)) (432) 335-3050
Eddy Cty Sheriff's Department	Eddy County (Artesia)	(505) 746-2704
Eddy Cty Sheriff's Department	Eddy County (Carlsba	(505) 887-7551
Gaines Cty Sheriff's Department	Gaines County (Semir	(432) 758-9871
Hockley Cty Sheriff's Department	Hockley County(Leve	1 (806) 894-3126
Kent Cty (Jayton City Sheriff's Dept.)	Kent County(Jayton)	(806) 237-3801
Lea Cty Sheriff's Department	Lea County (Eunice)	(505) 384-2020
Lea Cty Sheriff's Department	Lea County (Hobbs)	(505) 393-2515
Lea Cty Sheriff's Department	Lea County (Lovingto	r (505) 396-3611
Lubbock Cty Sheriff's Department	Lubbock Cty (Abernat	t (806) 296-2724
Midland Cty Sheriff's Department	Midland County (Mid	1 (432) 688-1277

Person	Location 🦛	• Office Phone Cell/Mobile Phone
Pecos Cty Sheriff's Department	Pecos County (Iraan)	(432) 639-2251
Reeves Cty Sheriff's Department	Reeves County, (Pecos)	(432) 445-4901
Scurry Cty Sheriff's Department	Scurry County (Snyder	(325) 573-3551
Terry Cty Sheriff's Department	Terry County (Brownfi	(806) 637-2212
Union Cty Sheriff's Department	Union County (Claytor	(505) 374-2583
Upton Cty Sheriff's Department	Upton County (Rankin	(432) 693-2422
Ward Cty Sheriff's Department	Ward County (Monaha	(432) 943-3254
Yoakum City Sheriff's Department	Yoakum Co. (Denever	(806) 456-2377
Law Enforcement - Police	and the second second and the second s	and the second se
Abernathy City Police	Abernathy, TX	(806) 298-2545
Andrews City Police	Andrews, TX	(432) 523-5675
Artesia City Police	Artesia, NM	(505) 746-2704
Brownfield City Police	Brownfield, TX	(806) 637-2544
Carlsbad City Police	Carlsbad, NM	(505) 885-2111
Clayton City Police	Clayton, NM	(505) 374-2504
Denver City Police	Denver City, TX	(806) 592-3516
Eunice City Police	Eunice, NM	(505) 394-2112
Hobbs City Police	Hobbs, NM	393-2677
Jal City Police	Jal, NM	(505) 395-2501
Jayton City Police	Jayton, TX	(806) 237-3801
Lamesa City Police	Lamesa, TX	(806) 872-2121
Levelland City Police	Levelland, TX	(806) 894-6164
Lovington City Police	Lovington, NM	(505) 396-2811
Midland City Police	Midland, TX	(432) 685-7113
Monahans City Police	Monahans, TX	(432) 943-3254
Odessa City Police	Odessa, TX	(432) 335-3378
Seminole City Police	Seminole, TX	(432) 758-9871
Snyder City Police	Snyder, TX	(325) 573-2611
Sundown City Police	Sundown, TX	(806) 229-8241
	an aine a' chuire san air air an tartaire	n service ago na mís com a singuinago ago a como como como como como como como c
Law Enforcement - FBI		
FBI	Alburqueque, NM	(505) 224-2000
FBI	Midland, TX	(432) 570-0255
	and the second second second second	an an an an the second standing of the second and an
Law Enforcement - DPS		····································
NM State Police	Artesia, NM	(505) 746-2704
NM State Police	Carlsbad, NM	(505) 885-3137
NM State Police	Eunice, NM	(505) 392-5588
NM State Police	Hobbs, NM	(505) 392-5588
NM State Police	Clayton, NM	(505) 374-2473; 911
TX Dept of Public Safety	Andrews, TX	(432) 524-1443
TX Dept of Public Safety	Big Lake, TX	(325) 884-2301

TX Dept of Public Safety Brownfield, TX (806) 637-2312 TX Dept of Public Safety Iran, TX (432) 639-3232 TX Dept of Public Safety Lamesa, TX (806) 872-8675 TX Dept of Public Safety Levelland, TX (806) 872-8675 TX Dept of Public Safety Lebeock, TX (806) 872-8675 TX Dept of Public Safety Moldand, TX (432) 943-5857 TX Dept of Public Safety Moldand, TX (432) 943-5857 TX Dept of Public Safety Odessa, TX (432) 943-5837 TX Dept of Public Safety Orrona, TX (323) 932-621 TX Dept of Public Safety Pecca, TX (432) 943-5333 TX Dept of Public Safety Pecca, TX (432) 447-3533 TX Dept of Public Safety Sinder, TX (325) 372-0113 TX Dept of Public Safety Sinder, TX (325) 373-0113 TX Dept of Public Safety Yeakum County TX (806) 633-9113 TX Dept of Public Safety Yeakum County TX (806) 456-2377 TX Dept of Public Safety Yeakum County TX (806) 456-2377 TX Dept of Public Safety Ameraky, TX	Rerson	Location 🖉 🖉	Office Phone Cell/Mobile Phone
TX Dept of Public Safety Inane, TX (432) 659-3232 TX Dept of Public Safety Lamea, TX (806) 872-8675 TX Dept of Public Safety Lubbock, TX (806) 747-4491 TX Dept of Public Safety Mulland, TX (432) 697-2211 TX Dept of Public Safety Monahans, TX (432) 932-600 TX Dept of Public Safety Odesa, TX (432) 932-601 TX Dept of Public Safety Odesa, TX (432) 932-601 TX Dept of Public Safety Odesa, TX (432) 753-610 TX Dept of Public Safety Peces, TX (432) 758-601 TX Dept of Public Safety Seminole, TX (432) 758-4041 TX Dept of Public Safety Terry County TX (806) 637-8913 TX Dept of Public Safety Terry County TX (806) 456-2377 TX Dept of Public Safety Terry County TX (806) 456-2377 TX Dept of Public Safety Assicure, TX 523-3111 Anterasty Abernathy, TX (806) 289-2022 Abernathy Abernathy, TX (806) 289-2022 Anistad/Rosebud Amistad/Rosebud, TX (806) 573-3113 Anterasty Antereas, TX 523-3111	TX Dept of Public Safety	Brownfield, TX	(806) 637-2312
TX Dept of Public Safety Lanesa, TX (806) 872-8675 IX Dept of Public Safety Labbook, TX (806) 487-4491 TX Dept of Public Safety Midland, TX (432) 697-2211 TX Dept of Public Safety Monahans, TX (432) 697-2211 TX Dept of Public Safety Monahans, TX (432) 697-2211 TX Dept of Public Safety Odesa, TX (432) 493-5857 TX Dept of Public Safety Odesa, TX (432) 332-6100 TX Dept of Public Safety Ocons, TX (432) 352-621 TX Dept of Public Safety Seminole, TX (432) 357-6113 TX Dept of Public Safety Singler, TX (325) 357-6113 TX Dept of Public Safety Singler, TX (325) 357-6113 TX Dept of Public Safety Yoskum Coumy TX (806) 637-8913 TX Dept of Public Safety Yoskum Coumy TX (806) 456-2377 Fifefighting & Rescue Abernathy, TX (806) 378-9113 Anstad/Rosebud Amistad/Rosebud, NM (505) 465-2021 Amistad/Rosebud Amistad/Rosebud, NM (505) 465-5051 Big Lake Big Lake, TX (325) 883-3125 Brownfield Ardministrative & other calls Bro	TX Dept of Public Safety	Iraan, TX	(432) 639-3232
TX Dept of Public Safety Levelland, TX (806) 894-4385 TX Dept of Public Safety Midland, TX (806) 747-4491 TX Dept of Public Safety Monahans, TX (432) 943-5857 TX Dept of Public Safety Ozesa, TX (432) 332-6100 TX Dept of Public Safety Ozesa, TX (432) 332-6100 TX Dept of Public Safety Ozesa, TX (432) 332-6100 TX Dept of Public Safety Peccs, TX (432) 758-4041 TX Dept of Public Safety Seminole, TX (325) 573-0113 TX Dept of Public Safety Sayder, TX (325) 573-0113 TX Dept of Public Safety Yeakum County TX (806) 456-2377 TX Dept of Public Safety Yeakum County TX (806) 456-2377 TX Dept of Public Safety Yeakum County TX (806) 298-2022 Amistad/Rosebud Amistad/Rosebud, NM (505) 633-9113 Andrews Andrews, TX 523-3111 Antesia NIT (325) 884-3561 Big Lake Big Lake, TX (325) 885-3125 Clayton Clayton, NM (505) 385-3125 Clayton	TX Dept of Public Safety	Lamesa, TX	(806) 872-8675
TX Dept of Public Safety Lubbock, TX (806) 747-4491 TX Dept of Public Safety Midland, TX (432) 607-2211 TX Dept of Public Safety Odesa, TX (432) 332-6100 TX Dept of Public Safety Odesa, TX (432) 433-5857 TX Dept of Public Safety Odesa, TX (432) 437-5333 TX Dept of Public Safety Semiole, TX (432) 758-031 TX Dept of Public Safety Singler, TX (325) 573-0113 TX Dept of Public Safety Singler, TX (325) 573-0113 TX Dept of Public Safety Terry County, TX (806) 637-8913 TX Dept of Public Safety Yeakum County, TX (806) 456-2377 Firefighting & Rescue Amista/Rosebud, NM (505) 633-9113 Andrews Andrews, TX (806) 298-2022 Anista/Rosebud Amista/Rosebud, NM (505) 633-9113 Andrews Andrews, TX (323) 884-3650 Big Lake Big Lake, TX (323) 884-3650 Brownfield, TX (816) 637-4547 Brownfield, TX Brownfield Aministrative & other calls Brownfield, TX 911	TX Dept of Public Safety	Levelland, TX	(806) 894-4385
TX Dept of Public Safety Midland, TX (432) 697-2211 TX Dept of Public Safety Monahans, TX (432) 943-5857 TX Dept of Public Safety Ocosa, TX (325) 392-2621 TX Dept of Public Safety Pecos, TX (432) 432-5837 TX Dept of Public Safety Pecos, TX (432) 437-3533 TX Dept of Public Safety Seminole, TX (432) 758-4041 TX Dept of Public Safety Seminole, TX (806) 637-8913 TX Dept of Public Safety Terry County TX (806) 456-2377 TX Dept of Public Safety Yakum County TX (806) 456-2377 Firefighting & Rescue Sedenard Firefighting & Rescue Sedenard Abernathy Abernathy, TX (806) 298-2022 Annistad/Rosebud, NM (505) 633-9113 Andrews Andrews, TX 523-3111 Andrews Andrews Andrews, NM (505) 734-6501 Big Lake, TX (325) 874-3650 Big Lake Big Lake, TX 911 Carlabad, NM (505) 885-3125 Clayton Clayton, NM (505) 374-2435 Carlabad, NM (505) 374-2435 <td>TX Dept of Public Safety</td> <td>Lubbock, TX</td> <td>(806) 747-4491</td>	TX Dept of Public Safety	Lubbock, TX	(806) 747-4491
TX Dept of Public Safety Monahans, TX (432) 943-5857 TX Dept of Public Safety Ocesa, TX (432) 332-6100 TX Dept of Public Safety Pecos, TX (432) 322-621 TX Dept of Public Safety Pecos, TX (432) 758-4041 TX Dept of Public Safety Seminole, TX (432) 758-4041 TX Dept of Public Safety Snyder, TX (325) 757-0113 TX Dept of Public Safety Terry County TX (806) 637-8913 TX Dept of Public Safety Yoskum County TX (806) 456-2377 Firefightling & Rescue Yoskum County TX (806) 456-2377 Ademathy Abernathy, TX (806) 456-2377 Ademathy Abernathy, TX (806) 456-2377 Admarky, TX (806) 456-2377 (806) 458-2377 Amistad/Rosebud, Amistad/Rosebud, NM (505) 633-9113 (806) 456-2377 Amistad/Rosebud, NM (505) 637-547 (806) 572-557 <tr< td=""><td>TX Dept of Public Safety</td><td>Midland, TX</td><td>(432) 697-2211</td></tr<>	TX Dept of Public Safety	Midland, TX	(432) 697-2211
TX Dept of Public Safety Odessa, TX (432) 332-6100 TX Dept of Public Safety Pecos, TX (432) 473-5533 TX Dept of Public Safety Semiole, TX (432) 473-5533 TX Dept of Public Safety Semiole, TX (432) 473-5533 TX Dept of Public Safety Snyder, TX (325) 573-0113 TX Dept of Public Safety Terry County TX (806) 437-8913 TX Dept of Public Safety Terry County TX (806) 456-2377 Firefighting & Rescue Adversed 444 Abernathy Abernathy, TX (806) 456-2377 Andrews Amistad/Rosebud, NM (505) 633-9113 Andrews Andrews, TX 523-3111 Andrews Andrews, TX 523-3111 Andrews Andrews, TX (325) 884-3650 Big Lake Big Lake, TX (325) 884-3650 Brownfield Administrative & other calls Brownfield, TX -911 Carlsbad Carlsbad, NM (505) 374-2435 Coton Center Coton Center, TX (806) 879-2157 Crane Crane, TX (432) 582-361 <td>TX Dept of Public Safety</td> <td>Monahans, TX</td> <td>(432) 943-5857</td>	TX Dept of Public Safety	Monahans, TX	(432) 943-5857
TX Dept of Public Safety Ozona, TX (323) 392-2621 TX Dept of Public Safety Pecos, TX (432) 447-3533 TX Dept of Public Safety Snyder, TX (325) 573-0113 TX Dept of Public Safety Snyder, TX (325) 573-0113 TX Dept of Public Safety Terry County TX (806) 637-8913 TX Dept of Public Safety Yoakum County TX (806) 456-2377 Firefighting & Rescue Abernathy, TX (806) 298-2022 Amistad/Rosebud, NM (505) 633-9113 Andrews Andrews Andrews, TX 523-3111 Andrews Andrews, TX 523-3111 Andrews Andrews, TX 6305) 746-5051 Big Lake Big Lake, TX (325) 884-3650 Brownfield-Administrative & other calls Brownfield, TX (816) 637-4547 Brownfield emergency only Brownfield, TX -911 Carlsbad, NM (505) 885-3125 Clayton Clayton Clayton, NM (505) 882-3125 Clayton Clayton, NM (505) 882-3125 Clayton Clayton, NM (505) 342-2157 <td>TX Dept of Public Safety</td> <td>Odessa, TX</td> <td>(432) 332-6100</td>	TX Dept of Public Safety	Odessa, TX	(432) 332-6100
TX Dept of Public Safety Pecos, TX (432) 447-3533 TX Dept of Public Safety Seminole, TX (432) 758-4041 TX Dept of Public Safety Terry County TX (806) 637-8913 TX Dept of Public Safety Yoskum County TX (806) 637-8913 TX Dept of Public Safety Yoskum County TX (806) 637-8913 TX Dept of Public Safety Yoskum County TX (806) 637-8913 TX Dept of Public Safety Yoskum County TX (806) 637-8913 Abernathy Abernathy, TX (806) 298-2022 Amistad/Rosebud, AM K505) 633-9113 Andrews Andrews Andrews, TX 523-3111 Andrews Andrews, TX (325) 884-3650 Big Lake Big Lake, TX (325) 884-3650 Brownfield -Administrative & other calls Brownfield, TX (816) 637-4547 Brownfield emergency only Brownfield, TX 911 Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 374-2435 Cotton Center Cotton Center, TX (806) 872-3516 Del Rio Del	TX Dept of Public Safety	Ozona, TX	(325) 392-2621
TX Dept of Public SafetySeminole, TX(432) 758-4041TX Dept of Public SafetySnyder, TX(325) 573-0113TX Dept of Public SafetyTerry County TX(806) 637-8913TX Dept of Public SafetyYoakum County TX(806) 456-2377Firefighting & RescueAbernathy, TX(806) 298-2022Amitad/RosebudAmitad/Rosebud, NM(505) 633-9113AndrewsAndrews, TX523-3111AndrewsAndrews, TX523-3111AntesiaAndrews, TX(325) 884-3650Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX(816) 637-4547Brownfield emergency onlyBrownfield, TX911CarlsbadCarlsbad, NM(505) 374-2435Cotton CenterClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(432) 558-2361Del RioDel Rio, TX(830) 774-8650Denver CityDerwer City, TX(806) 592-3116EldoradoEldorado, TX(325) 833-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 253-2361Del RioDel Rio, TX(432) 253-2361Del RioGaldsmith, TX(432) 254-2404GoldsmithGoldsmith, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 257-3445Hale CenterHale Center, TX(806) 839-2111HalfwayHalfway, TXHalfwayHalfwayHalfway, TXHalfwayHalfway	TX Dept of Public Safety	Pecos, TX	(432) 447-3533
TX Dept of Public SafetySnyder, TX(325) 573-0113TX Dept of Public SafetyTerry County TX(806) 637-8913TX Dept of Public SafetyYoakum County TX(806) 645-2377Firefighting & RescueAbernathy, TX(806) 298-2022Amistad/RosebudAmistad/Rosebud, NM(505) 633-9113AndrewsAbernathy, TX(806) 298-2022Amistad/Rosebud, NM(505) 633-9113AndrewsAndrews, TX523-3111ArtesiaArtesia, NM(505) 746-5051Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX911CarlsbadCarlsbad, NM(505) 374-5477Brownfield emergency onlyBrownfield, TX911CarlsbadCarlsbad, NM(505) 385-3125ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(830) 774-8650Denver CityDenver City, TX(806) 879-2157CraneEldorado, TX(325) 853-2361EldoradoEldorado, TX(325) 853-2361EldoradoEldorado, TX(325) 853-2361EldoradoEldorado, TX(325) 853-2411Garden CityGarden City, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 827-3445Halc Center, TX(806) 839-2411Halfway, TXHalfwayHalfway, TXHalfway, TXHalc Center, TX(806) 837-321HalfwayHalfway, TX(806) 837-321<	TX Dept of Public Safety	Seminole, TX	(432) 758-4041
TX Dept of Public Safety Terry County TX (806) 637-8913 TX Dept of Public Safety Yoakum County TX (806) 456-2377 Firefighting & Rescue Image: Construction of the second of	TX Dept of Public Safety	Snyder, TX	(325) 573-0113
TX Dept of Public SafetyYoakum Counly TX(806) 456-2377Firrefighting & RescueAbernathyAbernathyAbernathy, TXRomathyAbernathy, TXAbernathyAbernathy, TXAbernathyAbernathy, TXAbernathyAbernathy, TXAmistad/RosebudAmistad/Rosebud, NMAndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AndrewsAndrews, TXS23-3111AntresiaArtesia, NM(505) 746-5051Big LakeBig Lake, TX(325) 858-5310Brownfield Administrative & other callsBrownfield, TXBrownfield emergency onlyBrownfield, TXCarlsbadCarlsbadCarlsbadCarlsbadCarlsbadCarlsbadCarlsbadCotton CenterCotton CenterCrane, TXCotton CenterCrane, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, Carlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXCarlsbad, TXC	TX Dept of Public Safety	Terry County TX	(806) 637-8913
Firefighting & RescueAbernathy, TX(806) 298-2022AbernathyAbernathy, TX(806) 298-2022Amistad/Rosebud, NM(505) 633-9113AndrewsAndrews, TX523-3111AndrewsAndrews, TX523-3111AntesiaArtesia, NM(505) 746-5051Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX911CarlsbadCarlsbad, NM(505) 885-3125ClaytonClayton, NM(505) 885-3125ClaytonClayton, NM(505) 747-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(806) 879-2157CraneCrane, TX(806) 879-2157CraneCrane, TX(806) 879-2157Denver CityDenver City, TX(806) 879-2157Del RioDel Rio, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 892-211HalrwayHalfway, TX(505) 397-9308JalJal, NM(505) 397-9308JalJal, NM(505) 397-9308JalJal, NM(505) 397-9308JalJayton, TX(430) 886-3468LamesaLamesa, TX(806) 872-4352Levelland, TX(806) 872-4352Levelland, TXLevellandLevelland,	TX Dept of Public Safety	Yoakum County TX	(806) 456-2377
Firefighting & Rescue Abernathy, TX (806) 298-2022 Amistad/Rosebud Amistad/Rosebud, NM (505) 639-013 Andrews Andrews, TX 523-3111 Antroxia Andrews, TX 523-3111 Antroxia Andrews, TX 523-3111 Antroxia Antesia, NM (505) 746-5051 Big Lake Big Lake, TX (325) 884-3650 Brownfield-Administrative & other calls Brownfield, TX 911 Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 885-3125 Cotton Center Cotton Center, TX (800) 879-2157 Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Bunice, NM (505) 394-2111 Garden City, TX (432) 827-3445 Hale Center Hale Center, TX (806) 872-4314 Hale Center Hale Center, TX (806) 892-4111			
Abernathy Abernathy, TX (806) 298-2022 Amistad/Rosebud, NM (505) 633-9113 Andrews Andrews Andrews, TX 523-3111 Artesia Artesia, NM (505) 746-5051 Big Lake Big Lake, TX (325) 884-3650 Brownfield-Administrative & other calls Brownfield, TX (816) 637-4547 Brownfield emergency only Brownfield, TX -911 Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 374-2435 Cotton Center Cotton Center, TX (806) 879-2157 Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 829-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 254-2404 Goldsmith Goldsmith, TX (432) 254-2404 Goldsmith Goldsmith, TX (432) 354-2404 Hale Center, TX (806) 839-24	Firefighting & Rescue	george en al grade	
Amistad/Rosebud Amistad/Rosebud, NM (505) 633-9113 Andrews Andrews, TX 523-3111 Antesia Artesia, NM (505) 746-5051 Big Lake Big Lake, TX (325) 884-3650 Brownfield-Administrative & other calls Brownfield, TX (816) 637-4547 Brownfield emergency only Brownfield, TX 911 Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 885-3125 Cotton Center Cotton Center, TX (806) 879-2157 Crane Crane, TX (830) 774-8650 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eanice Eunice, NM (505) 394-2111 Goldsmith Goldsmith, TX (432) 558-2361 Hale Center, TX (806) 839-2411 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX 1 Hobbs Jal, NM (505) 397-9308	Abernathy	Abernathy, TX	(806) 298-2022
AndrewsAndrews, TX523-3111ArtesiaArtesia, NM(505) 746-5051Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX(816) 637-4547Brownfield emergency onlyBrownfield, TX-911CarlsbadCarlsbad, NM(505) 885-3125ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(803) 774-8650Denver CityDenver City, TX(806) 592-3516EldoradoEldorado, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 839-2411Halfway, TXHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 397-9308JalJal, NM(505) 397-9301LamesaLamesa, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352LovingtonLovington, NM(505) 396-2359	Amistad/Rosebud	Amistad/Rosebud, NM	(505) 633-9113
ArtesiaArtesia, NM(505) 746-5051Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX(816) 637-4547Brownfield emergency onlyBrownfield, TX-911CarlsbadCarlsbad, NM(505) 885-3125ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(803) 774-8650Denver CityDenver City, TX(806) 592-3516EldoradoEldorado, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden City, TX(806) 839-2111Garden CityGarden City, TX(806) 839-2411Half WayHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 397-9308JaytonJayton, TX(806) 837-3801KermitKermit, TX(432) 586-3468LamesaLamesa, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352	Andrews	Andrews, TX	523-3111
Big LakeBig Lake, TX(325) 884-3650Brownfield-Administrative & other callsBrownfield, TX(816) 637-4547Brownfield emergency onlyBrownfield, TX-911CarlsbadCarlsbad, NM(505) 885-3125ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(830) 774-8650Denver CityDenver City, TX(806) 592-3516EldoradoEldorado, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 254-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 839-2411Halfway, TXHalfway, TXHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 397-9308JaytonJayton, TX(806) 837-3801KermitKermit, TX(432) 586-3468LamesaLamesa, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352LovingtonLovington, NM(505) 396-2359	Artesia	Artesia, NM	(505) 746-5051
Brownfield-Administrative & other callsBrownfield, TX(816) 637-4547Brownfield emergency onlyBrownfield, TX-911CarlsbadCarlsbad, NM(505) 885-3125ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(806) 592-3516EldoradoEldorado, TX(325) 853-2691EldoradoEldorado, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 254-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 839-2411HalfwayHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 397-9308JaltonJayton, TX(806) 6237-3801KermitKermit, TX(432) 586-3468LamesaLamesa, TX(806) 872-4352LevellandLevelland, TX(806) 872-4352LovingtonLovington, NM(505) 396-2359	Big Lake	Big Lake, TX	(325) 884-3650
Brownfield emergency only Brownfield, TX -911 Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 374-2435 Cotton Center Cotton Center, TX (806) 879-2157 Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 254-2404 Goldsmith Goldsmith, TX (432) 254-2404 Hale Center Hale Center, TX (806) 839-2411 Hafway Halfway, TX (806) 839-2411 Hafway Halfway, TX (505) 397-9308 Jal, NM (505) 397-9308 [31] Jal, NM (505) 397-9308 [31] Jal Jal, NM (505) 397-9308 [31] Jal, NM (505) 397-9308 [31] [32] Jayton Jayton, TX (806) 237-3801	Brownfield-Administrative & other calls	Brownfield, TX	(816) 637-4547
Carlsbad Carlsbad, NM (505) 885-3125 Clayton Clayton, NM (505) 374-2435 Cotton Center Cotton Center, TX (806) 879-2157 Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 854-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 827-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 894-3154 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359	Brownfield emergency only	Brownfield, TX	-911
ClaytonClayton, NM(505) 374-2435Cotton CenterCotton Center, TX(806) 879-2157CraneCrane, TX(432) 558-2361Del RioDel Rio, TX(830) 774-8650Denver CityDenver City, TX(806) 592-3516EldoradoEldorado, TX(325) 853-2691EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 839-2411HalfwayHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 395-2221JaytonJayton, TX(806) 237-3801KermitKermit, TX(432) 586-3468LamesaLamesa, TX(806) 894-3154LovingtonLovington, NM(505) 396-2359MaljamarMaljamar, NM(505) 676-4100	Carlsbad	Carlsbad, NM	(505) 885-3125
Cotton Center Cotton Center, TX (806) 879-2157 Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX (432) 827-3445 Hobbs Hobbs, NM (505) 397-9308 Jal, NM (505) 397-9308 Jal Jal, NM (505) 397-9308 Jal Jal, NM (505) 397-9308 Jal Jal, NM (505) 397-9308 Lamesa Lamesa, TX	Clayton	Clayton, NM	(505) 374-2435
Crane Crane, TX (432) 558-2361 Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 854-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 397-9308 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 892-3516 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Cotton Center	Cotton Center, TX	(806) 879-2157
Del Rio Del Rio, TX (830) 774-8650 Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 354-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX (806) 839-2411 Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 872-4352 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Crane	Crane, TX	(432) 558-2361
Denver City Denver City, TX (806) 592-3516 Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 354-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 8237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Del Rio	Del Rio, TX	(830) 774-8650
Eldorado Eldorado, TX (325) 853-2691 Eunice Eunice, NM (505) 394-2111 Garden City Garden City, TX (432) 354-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX (806) 839-2411 Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Denver City	Denver City, TX	(806) 592-3516
EuniceEunice, NM(505) 394-2111Garden CityGarden City, TX(432) 354-2404GoldsmithGoldsmith, TX(432) 827-3445Hale CenterHale Center, TX(806) 839-2411HalfwayHalfway, TXHobbsHobbs, NM(505) 397-9308JalJal, NM(505) 395-2221JaytonJayton, TX(806) 237-3801KermitKermit, TX(432) 586-3468LamesaLamesa, TX(806) 872-4352LevellandLevelland, TX(806) 894-3154LovingtonLovington, NM(505) 396-2359MaljamarMaljamar, NM(505) 676-4100	Eldorado	Eldorado, TX	(325) 853-2691
Garden City Garden City, TX (432) 354-2404 Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX (806) 839-2411 Hobbs Halfway, TX (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Eunice	Eunice, NM	(505) 394-2111
Goldsmith Goldsmith, TX (432) 827-3445 Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX	Garden City	Garden City, TX	(432) 354-2404
Hale Center Hale Center, TX (806) 839-2411 Halfway Halfway, TX Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Goldsmith	Goldsmith, TX	(432) 827-3445
Halfway Halfway, TX Halfway, TX Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Hale Center	Hale Center, TX	(806) 839-2411
Hobbs Hobbs, NM (505) 397-9308 Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Halfway	Halfway, TX	
Jal Jal, NM (505) 395-2221 Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Hobbs	Hobbs, NM	(505) 397-9308
Jayton Jayton, TX (806) 237-3801 Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Jal	Jal, NM	(505) 395-2221
Kermit Kermit, TX (432) 586-3468 Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Jayton	Jayton, TX	(806) 237-3801
Lamesa Lamesa, TX (806) 872-4352 Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Kermit	Kermit, TX	(432) 586-3468
Levelland Levelland, TX (806) 894-3154 Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Lamesa	Lamesa, TX	(806) 872-4352
Lovington Lovington, NM (505) 396-2359 Maljamar Maljamar, NM (505) 676-4100	Levelland	Levelland, TX	(806) 894-3154
Maljamar Maljamar, NM (505) 676-4100	Lovington	Lovington, NM	(505) 396-2359
	Maljamar	Maljamar, NM	(505) 676-4100

ł

Person	Location	Office Phone Cell/Mobile Phone
McCamey	McCamey, TX	(432) 652-8232
Midland	Midland, TX	(432) 685-7346
Monahans	Monahans, TX	(432) 943-4343
Nara Visa	Nara Visa, NM	(505) 461-3300
Notrees	Notress, TX	(432) 827-3445
Odessa	Odessa, TX	(432) 335-4659
Ozona	Ozona, TX	(325) 392-2626
Pecos	Pecos, TX	(432) 445-2421
Petersburg	Petersburg, TX	(806) 667-3461
Plains	Plains, TX	(806) 456-8067
Plainview	Plainview, TX	(806) 296-1170
Rankin	Rankin, TX	(432) 693-2252
San Angelo	San Angelo, TX	(325) 657-4355
Sanderson	Sanderson, TX	(432) 345-2525
Seminole	Seminole, TX	758-9871
Smyer	Smyer, TX	(806) 234-3861
Snyder	Snyder, TX	(325) 573-6215
Sundown	Sundown, TX	911
Tucumcari	Tucumcari, NM	911
West Odessa	Odessa, TX	(432) 381-3033
Ambulance	and a the second and the second	あるを かん あん ちょう ちょう かん しょう ひょう しょう ひょう
Abernathy Ambulance	Abernathy, TX	(806) 298-2241
Amistad/Rosebud	Amistad/Rosebud, N	M (505) 633-9113
Andrews Ambulance	Andrews, TX	(432) 523-5675
Artesia Ambulance	Artesia, NM	(505) 746-2701
Big Lake Ambulance	Big Lake, TX	(325) 884-2423
Big Spring Ambulance	Big Spring, TX	(432) 264-2550
Brownfield Ambulance	Brownfield, TX	(806) 637-2511
Carlsbad Ambulance	Carlsbad, NM	(505) 885-2111; 911
Clayton, NM	Clayton, NM	(505) 374-2501
Denver City Ambulance	Denver City, TX	(806) 592-3516
Eldorado Ambulance	Eldorado, TX	(325) 853-3456
Eunice Ambulance	Eunice, NM	(505) 394-3258
Goldsmith Ambulance	Goldsmith, TX	(432) 827-3445
Hobbs, NM	Hobbs, NM	(505) 397-9308
Jal, NM	Jal, NM	(505) 395-2501
Jayton Ambulance	Jayton, TX	(806) 237-3801
Lamesa Ambulance	Lamesa, TX	(806) 872-3464
Levelland Ambulance	Levelland, TX	(806) 894-8855
Lovington Ambulance	Lovington, NM	(505) 396-2811
McCamey Hospital	McCamey, TX	(432) 652-8626
Midland Ambulance	Midland, TX	(432) 685-7499

Person	Location	• Office Phone	Cell/Mobile Phone
Monahans Ambulance	Monahans, TX	3731	
Nara Visa, NM	Nara Visa, NM	(505) 461-3300	
Odessa Ambulance	Odessa, TX	(432) 335-3378	
Ozona Ambulance	Ozona, TX	(325) 392-2671	
Pecos Ambulance	Pecos, TX	(432) 445-4444	
Rankin Ambulance	Rankin, TX	(432) 693-2443	
San Angelo Ambulance	San Angelo, TX	(325) 657-4357	
Seminole Ambulance	Seminole, TX	758-9871	
Snyder Ambulance	Snyder, TX	(325) 573-1911	
Stanton Ambulance	Stanton, TX	(432) 756-2211	
Sundown Ambulance	Sundown, TX	911	
Tucumcari, NM	Tucumcari, NM	911	
Medical Air Ambulance Service			
AEROCARE - Methodist Hospital	Lubbock, TX	(800) 627-2376	
San Angelo Med-Vac Air Ambulance	San Angelo, TX	(800) 277-4354	
Southwest Air Ambulance Service	Stanford, TX	(800) 242-6199	
Southwest MediVac	Snyder, TX	(800) 242-6199	
Southwest MediVac	Hobbs, NM	(800) 242-6199	
Odessa Care Star	Odessa, TX	(888) 624-3571	
NWTH Medivac	Amarillo, TX	(800) 692-1331	

. . .

· · · ·


Permian Drilling Hydrogen Sulfide Drilling Operations Plan Radius CC 6-7 Federal Com 52H

Open drill site. No homes or buildings are near the proposed location.

1. Escape

Personnel shall escape upwind of wellbore in the event of an emergency gas release. Escape can take place through the lease road on the Southeast side of the location. Personnel need to move to a safe distance and block the entrance to location. If the primary route is not an option due to the wind direction, then a secondary egress route should be taken.

- 1 -



OXY

PRD NM DIRECTIONAL PLANS (NAD 1983) Radius CC 6_7 Radius CC 6_7 Federal Com 52H

Wellbore #1

Plan: Permitting Plan

Standard Planning Report

10 July, 2019

Database: Company: Project: Site: Well: Wellbore: Design: Project Map System:	HOPSPI ENGINE PRD NM Radius (Radius (Wellbore Permittir PRD NM US State F	ERING DES I DIRECTIO CC 6_7 CC 6_7 Fede #1 Ig Plan DIRECTION Plane 1983	SIGNS NAL PLANS Prai Com 52H IAL PLANS (I	(NAD 1983) VAD 1983)	Local Co-o TVD Refere MD Refere North Refe Survey Cal	ordinate Refere	ince: We RKI Gric od: Min Mean	II Radius CC (3=26.5' @ 29 3=26.5' @ 29 1 imum Curvati	6_7 Federal 85.40ft 85.40ft ure	Com 52H
Geo Datum: Map Zone:	North Ame New Mexic	rican Datum o Eastern Zo	1983 one				Using	geodetic sca	le factor	
अक्टर के समय का का के कुछ भ	16 - S. goldstanderstandersta		an a		Thesting of the second second second second	andreget, in high protocological and	tin a natural and the second secon	مى بېرىپو سېمىنىچېمىتى		ani in distanta anti na manifata ana manjari na siya jina ana siya jina ana sa
Site Site Position: From: Position Uncer	Map rtainty:	<u>C6_/</u> 2.	North Easti 00 ft Slot F	ning: ng: Radius:	456,20 • 635,60	07.02 usft La 66.76 usft Lo 13.200 in Gr	titude: ongitude: id Converger	nce:		32° 15' 13.751741 N 104° 1' 41.486528 W 0.16 °
Well	Radius C	C 6 <u>.</u> 7 Feder	al Com 52H				an the second			
Well Position	+N/-S +E/-W rtainty	-0 65 2	0.47 ft No 5.01 ft Ea 2.00 ft W	orthing: asting: ellhead Eleva	tion:	456,206.55 ust 635,731.76 ust 0.00 t	ft Latitud ft Longit ft Groun	de: ude: d Level:		32° 15' 13.745261 N 104° 1' 40.729594 W 2,958.90 ft
Wellbore Magnetics	Wellbore	#1 I Name	Sampl	e Date	Declinați (°)	ion is a	Dip Ang (°)	le	Field S (r	trength T)
Definition in density in the second		HDGM		7/10/2019		7.03		59.98		47,896
Design Audit Notes:	Permitting	g Plan	a and a star and a star	an a				999 - Hariya Sana ang		
Version:			Phas	e: P	ROTOTYPE	Tie O	n Depth:	C	0.00	
Vertical Sectio	on:	De	epth From (T (ft) 0.00	VD)	+N/-S (ft) 0.00	+E/-W (ft) 0.00		Diré (174	ction) 1.51	
Plan Sections Measured Depth	Inclination A	zimuth (?)	Verticăl Depth (ft)	+N/-S (ft) _{8.2}	+E/-W (ft)	Dogleg Rate (%100ft)	Bulld Rate (%/100ft) (Turn Rate ≌/100ft) ≸	Т ГО (?)	Tärgét
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	and the second state of the second states of the second states of the second states of the second states of the
3,750.00	0.00	0.00	3,750.00	0.00	0.00	0.00	0.00	0.00	0.00	
4,350.02	12.00	52.19 52.10	4,345.65	38.38	49.46 856.05	2.00	2.00	0.00	52.19	
9,200.01	12.00 12.00	52.19 170 70	9,103.80	621 17	076 86	2.00	0.00	0.00	0.00	
11 117 96	89.76	179.70	10,217.57 10,671 40	63.14	940.00 940 78	10.00	10.00	0.00	100.20	FTP (Radius CC
21,644.13	89.76	179.70	10,715.40	-10,462.80	1,004.76	0.00	. 0.00	0.00	0.00	PBHL (Radius CC

Oxy Planning Report

Database:	HOPSPP			Local Co	-ordinate Re	eference:	Well Radius CC	6_7 Federal C	om 52H
Company:		G DESIGNS	NS (NAD 1983		erence:	and the set	RKB=26.5' @ 2	985.40tt 985.40ft	
Site:	Radius CC 6	7		North Re	ferênce:		Grid	300.4UIL	
Well	Radius CC 6_	7 Federal Com	52H	Survey C	alculation N	lethod:	Minimum Curva	iture	
Wellbore:	Wellbore #1								
Design:	Permitting Pla	n	andre and a second second second second			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		second and its are president and	
Planned Survey	1. Second Property	an sana ana a	ing I. A.C.I	ARABER ARA	CERTIFICATION CONTRACT		Constitute Fille Filler	in Brief Connection and Anna Con	and the set of the set
ere accession	. M. M. Mar	the state of the second	A. A. A.	260 2 5 5 7 5 9 9		8 . C			ALL PROPERTY
Measured		E. C. Maria	Vertical	Sala Mar Shard	ac girt - Mag.	Vertical	Dogleg	Build.	Turn
Ueptn (ft)		'Azimuth	ູບeptn ີ້ (ft):	+N/-S	+E/-W	Section"	Rate (%100ft)	Rate */100ft)	Rate (°/100ft)
<u> enderstradersta</u> n	A Star	West of the second	Strates Pre	South States	<u>ç 19 (k. 184</u>			Y. Contraction	
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
200.00	0.00	0.00	200.00	0.00	0.00	0.00	0.00	0.00	0.00
300.00	0.00	0.00	300.00	0.00	0.00	0.00	0.00	0.00	0.00
400.00	0.00	0.00	400.00	0.00	0.00	0.00	0.00	0.00	0.00
500.00	0.00	0.00	500.00	0.00	0.00	0.00	0.00	0.00	0.00
600.00	0.00	0.00	600.00	0.00	0.00	0.00	0.00	0.00	0.00
700.00	0.00	0.00	700.00	0.00	0.00	0.00	0.00	0.00	0.00
900.00	0.00	0.00	900.00	0.00	0.00	0.00	0.00	0.00	0.00
1 000 00	0.00	0.00	1 000 00	0.00	0.00	0.00	0.00	0.00	0.00
1.100.00	0.00	0.00	1,100.00	0.00	0.00	0.00	0.00	0.00	0.00
1,200.00	0.00	0.00	1,200.00	0.00	0.00	0.00	0.00	0.00	0.00
1,300.00	0.00	0.00	1,300.00	0.00	0.00	0.00	0.00	0.00	0.00
1,400.00	0.00	0.00	1,400.00	0.00	0.00	0.00	0.00	0.00	0.00
1,500.00	0.00	0.00	1,500.00	0.00	0.00	0.00	0.00	0.00	0.00
1,600.00	0.00	0.00	1,600.00	0.00	0.00	0.00	0.00	0.00	0.00
1.800.00	0.00	0.00	1,700.00	0.00	0.00	0.00	0.00	0.00	0.00
1,900.00	0.00	0.00	1,900.00	0.00	0.00	0.00	0.00	0.00	0.00
2.000.00	0.00	0.00	2.000.00	0.00	0.00	0.00	0.00	0.00	0.00
2,100.00	0.00	0.00	2,100.00	0.00	0.00	0.00	0.00	0.00	0.00
2,200.00	0.00	0.00	2,200.00	0.00	0.00	0.00	0.00	0.00	0.00
2,300.00	0.00	0.00	2,300.00	0.00	0.00	0.00	0.00	0.00	0.00
2,400.00	0.00	0.00	2,400.00	0.00	0.00	0.00	0.00	0.00	0.00
2,500.00	0.00	0.00	2,500.00	0.00	· 0.00	0.00	0.00	0.00	0.00
2,700.00	0.00	0.00	2,700.00	0.00	0.00	0.00	0.00	0.00	0.00
2,800.00	0.00	0.00	2,800.00	0.00	0.00	0.00	0.00	0.00	0.00
2,900.00	0.00	0.00	2,900.00	0.00	0.00	0.00	0.00	0.00	0.00
3,000.00	0.00	0.00	3,000.00	0.00	0.00	0.00	0.00	0.00	0.00
3,100.00	0.00	0.00	3,100.00	0.00	0.00	0.00	0.00	0.00	0.00
3,200.00	0.00	0.00	3,200.00	0.00	0.00	0.00	0.00	0.00	0.00
3,400.00	0.00	0.00	3,400.00	0.00	0.00	0.00	0.00	0.00	0.00
3 500 00	0.00	0.00	3 500 00	0.00	0.00	0.00	0.00	0.00	0.00
3.600.00	0.00	0.00	3,600.00	0.00	0.00	0.00	0.00	0.00	0.00
3,700.00	0.00	0.00	3,700.00	0.00	0.00	0.00	0.00	0.00	0.00
3,750.00	0.00	0.00	3,750.00	0.00	0.00	0.00	0.00	0.00	0.00
3,800.00	1.00	52.19	3,800.00	0.27	0.34	-0.23	2.00	2.00	0.00
3,900.00	3.00	52.19	3,899.93	2.41	3.10	-2.10	2.00	2.00	0.00
4,000.00	5.00	52.19 52.19	3,999.68	0.08	16.87	-0.83 -11 42	2.00	2.00	0.00
4,200.00	9.00	52.19	4,198.15	21.62	27.87	-18.86	2.00	2.00	0.00
4,300.00	11.00	52.19	4,296.63	32.27	41.58	-28.14	2.00	2.00	0.00
4,350.02	12.00	52.19	4,345.65	38.38	49.46	-33.48	2.00	2.00	0.00
4,400.00	12.00	52.19	4,394.53	44.75	57.67	-39.03	0.00	0.00	0.00
4,500.00	12.00	52.19	4,492.35	57.50	74.10	-50.15	0.00	0.00	0.00
4,600.00	12.00	52.19	4,590.16	70.24	90.53	-61.27	0.00	0.00	0.00
4,700.00	12.00	52.19	4,087.97	82.99	100.95	-/ 2.38	0.00	0.00	0.00
4,800.00	12.00	52.19	4,785.79	95.73	123.38	-83.50	0.00	0.00	0.00
4,900.00	12.00	52.19 52.19	4,003.00	121 23	156 24	-94.02 -105.74	0.00	0.00	0.00
5,100.00	12.00	52.19	5,079.23	133.97	172.66	-116.85	0.00	0.00	0.00

Oxy Planning Report

CARSE AND AND	Ener hyperministration and any many	ath an injeran ar at a star	Latin and interimented	and the second	S. S. S. S. P. C. S. P. S.	File & Part She ! 4 "	مېر د مېر د د د ور	and the second second	the second s
Database:	HOPSPP			Local (Co-ordinate	Reference:	Well Radius CO	C 6_7 Federal C	Com 52H
Company:	ENGINEERING	DESIGNS		TVD R	eference	「ふっといれよう	RKB=26.5' @ 2	2985 40ft	아는 다양도 가까지 큰 씨인 웹
Project:	PRD NM DIREC		NS /NAD 1083)	ND D-		·····································		000E 408- 12	
				MD Ke	rerence:	e yeken Bakta akara bari ya	KNB=20.5 @ /	2965.401	at the set of a star star star
Site:	Radius CC 6_7			North I	Reference:	အရပ္ ေျပည္သြားေတြ ျမင့္ေန မ	Grid	المعاوري الأراب والأر	
Well:	Radius CC 6 7	Federal Com	52H	Survey	Calculation	n Method:	Minimum Curv	ature	in the grant of the
Mollhoro	. Wellbore #1					4			
Wendule.		(Bar Anna Barta	R. Carl Sol B	- Same	Sec. Share in a	19	and the second	الموقق المعالم مرقدت	요구는 영국 영국
Design:	Permitting Plan	પશુકુ જાણ તે કે તેમ ત			WAN OF STREET			la stat	1
हित्त स्विकृत सम्र विद्या स्वयन्त्र सम्बद्धाः स	ST LOCAL AND INCLUSION AND INCLUS	REALIZING, LAND, AN	er den an an andara and	MARTIN MART 12	an construction of the	1. 1	and a state of the second	AND ALL AND AND AND A	RANK AND AND A DESCRIPTION
Planned Survey		and a standard and a					a second and a second		1 × 1
Coloris Sector	assume the Cold	a series	Le varia de la	S. 1987 (1987 (19		1997 - Star 1997 - 1997 - 1997			
Measured	aria analis arigina digina di	1 . A . A . A	Vertical			Vertical	Donleg	Builde	Turn
Denth	经一辆 网络针缝 计	Alagha - Mine / Maria	Denth	6	State of the second	Soction -/2	Date	Data	Dato
(4)			- (4)	+N/-Ə	TE/-W	A CECUCII	1010 nn413 1152		1014 AA41
	(?) §₄ √♥??	%(°)%-:3en		(ft)) · · · · · · · · · · · · · · · · · ·	* (ft)	· · · · · · · · · · · · · · · · · · ·		(//////////////////////////////////////	ין אוטטונן איי איי איי
F 200 00	40.00	EQ 40	E 477 OF	AAC 70	100.00	407.07	0.00		
5,200.00	12.00	52.19	5,177.05	140.72	169.09	+127.97	0.00	0.00	0.00
5.300.00	12.00	52.19	5.274.86	159.46	205.52	-139.09	0.00	0.00	0.00
5 400 00	12 00	52 19	5 372 68	172 21	221 04	-150.20	0.00	0.00	0.00
5 500 00	12.00	52.10	5 470 40	194.05	229.27	161 22	0.00	0.00	0.00
5,500.00	12.00	52.13	5,470.45	104.33	200.97	470.44	0.00	0.00	0.00
5,800.00	12.00	52.19	5,500.51	197.70	254.60	-1/2.44	0.00	0.00	0.00
5,700.00	12.00	52.19	5,000.12	210.45	2/1.23	-183.56	0.00	0.00	0.00
5,800.00	12.00	52.19	5,763,93	223.19	287 65	-194 67	0.00	0.00	0.00
5 900 00	12 00	52 19	5,861,75	235 94	304 08	-205 79	0.00	0.00	0.00
6,000.00	12.00	52.10	5 959 56	248 69	320 51	200.70	0.00	0.00	0.00
£ 100.00	12.00	52.10	6 057 39	261 42	326 02	-210.91	0.00	0.00	0.00
6 200 00	12.00	JZ. 19	0,007.00	201.43	330.93	-220.02	0.00	0.00	0.00
0,200.00	12.00	52.19	0,100.19	274.18	353.36	-239.14	0.00	0.00	0.00
6.300.00	12.00	52.19	6,253.01	286.92	369.79	-250.26	0.00	0.00	0.00
6,400,00	12.00	52.19	6,350.82	299.67	386 21	-261.38	0.00	0.00	0.00
6 500 00	12.00	52.10	6 4 4 8 6 4	312 /1	402.64	-272 40	0.00	0.00	0.00
6,000.00	12.00	52.13	6 546 45	225 46	402.04	-272.43	0.00	0.00	0.00
0,000.00	12.00	52.19	0,540.45	325.10	419.07	-203.01	0.00	0.00	0.00
6,700.00	12.00	52.19	6,644.27	337.91	435.50	-294.73	0.00	0.00	0.00
6,800,00	12.00	52 19	6 742 08	350.65	451 92	-305 85	0.00	0.00	0.00
6 900 00	12.00	52 19	6 839 90	363.40	468 35	-316.96	0.00	0.00	0.00
7 000 00	12.00	52.10	6 037 71	376 14	400.55	328.08	0.00	0.00	0.00
7,000.00	12.00	52.19	7 025 52	200.04	404.70 501.20	-320.00	0.00	0.00	0.00
7,100.00	12.00	52.19	7,035.52	300.09	501.20	-339.20	0.00	0.00	0.00
7,200.00	12.00	52.19	7,133.34	401.64	517.63	-350.31	0.00	0.00	0.00
7,300,00	12 00	52 19	7 231 15	414 38	534.06	-361 43	0.00	0.00	0.00
7 400 00	12.00	52.10	7 328 97	427 13	550.48	-372 55	0.00	0.00	0.00
7,500.00	12.00	52.10	7,020.37	420.97	550.40	-072.00	0.00	0.00	0.00
7,500.00	12.00	52.19	7,420.70	453.07	500.91	-303.07	0.00	0.00	0.00
7,600.00	12.00	52.19	7,524.00	452.62	563.34	-394.78	0.00	0.00	0.00
7,700.00	12.00	52.19	7,622.41	465.36	599.77	-405.90	0.00	0.00	0.00
7.800.00	12.00	52.19	7.720.23	478.11	616.19	-417.02	0.00	0.00	0.00
7 900 00	12 00	52 19	7 818 04	490.86	632 62	-428 14	0.00	0.00	0.00
8 000 00	12.00	52 10	7 915 86	503.60	649.05	_/30.25	0.00	0.00	0.00
8 100 00	12.00	52.15	9.013.67	516 35	665 47	450.23	0.00	0.00	0.00
8,700.00	12.00	52.13	9 111 40	510.00	691.00	461.40	0.00	0.00	0.00
0,200.00	12.00	52.19	0,111.49	529.09	001.90	-401.49	0.00	0.00	0.00
8,300.00	12.00	52.19	8,209.30	541.84	698.33	-472.60	0.00	0.00	0.00
8,400.00	12.00	52.19	8,307.11	554.59	714.75	-483.72	0.00	0.00	0.00
8,500.00	12.00	52.19	8,404,93	567.33	731 18	-494 84	0.00	0.00	0.00
8.600.00	12.00	52.19	8.502.74	580.08	747.61	-505.96	0.00	0.00	0.00
8 700 00	12 00	52 19	8,600 56	592 82	764 04	-517 07	0.00	0.00	0.00
0,700.00	12.00	02.10	0,000.00	UVE.UE	, 04.04	011.01	0.00	0.00	0.00
8,800.00	12.00	52.19	8,698.37	605.57	780.46	-528.19	0.00	0.00	0.00
8,900.00	12.00	52.19	8,796.19	618.32	796.89	-539.31	0.00	0.00	0.00
9,000.00	12.00	52.19	8,894.00	631.06	813.3 ²	-550.43	0.00	0.00	0.00
9.100.00	12.00	52.19	8,991.82	643.81	829.74	-561.54	0.00	0.00	0.00
9,200,00	12.00	52.19	9.089.63	656.55	846 17	-572 66	0.00	0.00	0.00
0,200.00	12.00	02.10	0,000.00	000.00	5-10.11	072.00	5.00	0.00	0.00
9,265.61	12.00	52.19	9,153.80	664.92	856.95	-579.95	0.00	0.00	0.00
9,300.00	11.39	53.76	9,187.48	669.12	862.51	-583.60	2.00	-1.77	4.56
9,400.00	9.68	59.41	9,285.80	679.23	877.71	-592.22	2.00	-1.72	5.65
9.500.00	8.09	67.34	9.384.60	686.22	891.44	-597.86	2.00	-1.58	7.94
9 600 00	6 73	78 77	9 483 77	690.07	44 FUS	-600 53	2.00	-1.36	11 43
3,000.00	0.75	10.11	0,400.11	000.07	303.00	-000.00	2.00	- 1.00	11.40
9,700.00	5.75	94.92	9,583.18	690.78	914.42	-600.21	2.00	-0.98	16.15
9,800.00	5.37	115.31	9,682.72	688.35	923.64	-596.91	2.00	-0.38	20.38
9,900,00	5.71	135.85	9,782.26	, 682.78	931.34	-590.63	2.00	0.34	20.54
10,000,00	6 66	152 30	9 881 69	674.08	937 50	-581 38	2 00	0.95	16.45
10,000.00	8 00	163 08	9 980 87	662.26	042.11	-560 17	2.00	1 34	11 68
10,100.00	0.00	100.00	0,000.07	002.20	372.11	-000.17	2.00	1.04	11.00
10,200.00	9.58	172.09	10,079.70	647.33	945.18	-554.01	2.00	1.57	8.11
10,300.00	11.29	177.84	10,178.05	629.31	· 946.69	-535.93	2.00	1.71	5.76
10.340.36	12.00	179.70	10 217 57	621.17	946 86	-527.81	2.00	1.77	4.60

.

A. the straight and share wet the	Jona Make march & and the said	Pilice Rosenald in the	Land Lotte Little	And the ality or March .	88.7885 ale 73	a and a second	gar, particular and		1
Database:	HOPSPP	a i i i a a a a a a a a a a a a a a a a		Local C	o-ordinate R	Reference:	Well Radius C	C 6_7 Federa	I Com 52H
Company:	ENGINEERING	DESIGNS	S MAN MAR AND		foronco	高小家 通小机	BKB=26 5	2085 10#	and the state of the
Dreinet			NO INAD 400			و المراجع المراجع المراجع المحمد المحمد	THE 20.5 W	2000.401	i Rei de La Carla de Maria de
Project:		CTIONAL PLA	N2 (NAD 198	s) کې MD Ref	erence:		RKB=26.5 @	2985.40ft	승규는 것이 같아요. 같이 같아?
Site:	Radius CC 6_7			North F	leference:	್ಷೇಶ್ ಕ್ರಮ ಸಂಗ್ರೆ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ ಕಾಲ್ಗಳ ಗೋಪಿ ಸಿಲ್ಲಿ ಸಿಲ್ಲಿ	Grid	1	
Well	Radius CC 6 7	Federal Com	52H	Survey	Calculation	Method:	Minimum Cun	vature	· 영상 전 1 전 1 전 1 전 1 전 1 1 1 1 1 1 1 1 1 1
	Mollboro #1					and the star of a			
weildore:		and the second			an 1993 - 19	ana a sa sa sa a sa a a			
Design:	Permitting Plan	1				and the second secon			Sand and the
أنفنا غن عبر بين يد يو الم	a stand a marking a stand a stand	ويد باشتا متكند الج		and the second second second					- The marks was and the second states and
Planned Survey	and the second second	وأعيادها مرواري والتسوية ترتزي وأستسبدون	مېرونىمىرىۋەتسىرى مەربورىسىرى	وللابسور ويتعسره فبشيا مجو بريتومه تعاه	وببوسيا أسرك مسوحك	مربع تيجيعا ويتوقد خرافي السيركاني	and a start with the second start and the second st	المستحدث والمستحدث	ى مى ئې دىغەن مەردىقى بارلى ئىيىمىيىمە جىيەسىيەيىتىيەت ئېلىسىتىمىغ
in state i well i state state state st		میں موجود ایک میں				en el luis de la card	an a	an Sa Mar	All land the second
Measured		2 An Salar and	Vertical		한 것이 해 것	Vertical	Doalea	Build	Turn
Depth	Inclination	Azimuth	Depth	4N/-S	+F/W	Section	Rate	Rate	Rate 201
(ff)	(0)	(0)	(ft)	· · · · · · · · · · · · · · · · · · ·	(4)	(ff)	(°/100ft)	(°/100ff)	(°/100ft)
and the second	and the state of the states and	alsore iter 3	in all all and the	(II) 		าสาจ จารีสีสาราชสิลภัณาแล้	to a little part to the book	Martin In.	May more the way ways
10,400,00	17.96	179.70	10,275,16	605 76	946 94	-512 46	10.00	10.00	0.00
10,500,00	27.96	179.70	10 367 12	566 79	947 15	-473.66	10.00	10.00	0.00
10,000.00	27.50	175.70	10,007.12	500.75	347.10	-470.00	10.00	10.00	0.00
10,600.00	37.96	179.70	10,450.92	512.45	947.43	-419.54	10.00	10.00	0.00
10,700.00	47.96	179.70	10,524.00	444.38	947.79	-351.75	10.00	10.00	0.00
10,800.00	57.96	179.70	10.584.15	364.66	948.20	-272.35	10.00	10.00	0.00
10,900,00	67.96	179 70	10 629 55	275 70	948 67	-183 75	10.00	10.00	0.00
11 000 00	77 96	179 70	10 658 91	180.21	040 17	_88 65	10.00	10.00	0.00
11,000.00		113.10	10,000.01	100.21	3 -13 .17	-00.00	10.00	10.00	
11,100.00	87.96	179.70	10,671.04	81.09	949.68	10.06	10.00	10.00	0.00
11,117.96	89.76	179.70	10,671.40	63.14	949.78	27.95	10.00	10.00	0.00
11,200.00	89.76	179.70	10,671.74	-18.90	950.21	109.65	0.00	0.00	0.00
11.300.00	89.76	179.70	10.672.16	-118.90	950.73	209.24	0.00	0.00	0.00
11 400 00	89 76	179 70	10.672.58	-218 90	951 25	308 83	0.00	0.00	0.00
	00.70			210.00		000.00	0.00	0.00	0.00
11,500.00	89.76	179.70	10,673.00	-318.90	951.77	408.42	0.00	0.00	0.00
11,600.00	89.76	179.70	10,673.42	-418.89	952.30	508.01	0.00	0.00	0.00
11,700.00	89.76	179.70	10,673.83	-518.89	952.82	607.60	0.00	0.00	0.00
11.800.00	89.76	179.70	10.674.25	-618.89	953.34	707.19	0.00	0.00	0.00
11,900.00	89.76	179.70	10.674.67	-718.89	953,86	806.78	0.00	0.00	0.00
12,000.00	89.76	179.70	10,675.09	-818.88	954.39	906.37	0.00	0.00	0.00
12,100.00	89.76	179.70	10,675.51	-918.88	954,91	1,005.96	0.00	0.00	0.00
12,200.00	89.76	179.70	10,675.92	-1,018.88	955,43	1,105.55	0.00	0.00	0.00
12,300.00	89.76	179.70	10,676.34	-1,118.88	955 95	1,205.14	0.00	0.00	0.00
12,400.00	89.76	179.70	10.676.76	-1.218.88	956.48	1,304.73	0.00	0.00	0.00
				,					
12,500.00	89.76	179.70	10,677.18	-1,318.87	957,00	1,404.32	0.00	0.00	0.00
12,600.00	89.76	179.70	10,677.60	-1,418.87	957,52	1,503.90	0.00	0.00	0.00
12,700.00	89.76	179.70	10,678.01	-1,518.87	958 04	1,603.49	0.00	0.00	0.00
12,800.00	89.76	179.70	10,678.43	-1,618.87	958,56	1,703.08	0.00	0.00	0.00
12,900.00	89.76	179.70	10,678.85	-1,718.86	959,09	1,802.67	0.00	0.00	0.00
42,000,00	00.70	470 70	40.070.07	4 040 00	050 04	4 000 00	0.00	0.00	0.00
13,000.00	89.76	179.70	10,679.27	-1,818.86	959.61	1,902.26	0.00	0.00	0.00
13,100.00	89.76	1/9.70	10,679.69	-1,918.86	960.13	2,001.85	0.00	0.00	0.00
13,200.00	89.76	1/9./0	10,680.10	-2,018.86	960.65	2,101.44	0.00	0.00	0.00
13,300.00	89.76	179.70	10,680.52	-2,118.86	961,18	2,201.03	0.00	0.00	0.00
13,400.00	89.76	179.70	10,680.94	-2,218.85	961.70	2,300.62	0.00	0.00	0.00
13 500 00	89.76	179 70	10 681 36	-2 318 85	062 22	2 400 21	0.00	0.00	0.00
13 600 00	80.76	170 70	10,001.00	-2,010.00	062.22	2,400.21	0.00	0.00	0.00
13,000.00	90 7C	170 70	10,001.70	-2,410.00	062.74	2,733.00	0.00	0.00	0.00
13,700.00	03.70	170.70	10,002.18	2 610 04	062 20	2,033.03	0.00	0.00	0.00
13,800.00	09.70	179.70	10,002.01	-2,010.04	903.//9	2,090.90	0.00	0.00	0.00
13,900.00	89.76	179.70	10,683.03	-2,/18.84	964.31	2,198.51	0.00	0.00	0.00
14,000.00	89.76	179.70	10,683,45	-2.818.84	964.83	2,898.16	0.00	0.00	0.00
14,100.00	89.76	179.70	10,683,87	-2 918 84	965 36	2 997 75	0.00	0.00	0.00
14 200 00	89.76	179 70	10 684 28	-3 018 84	965 88	3 097 34	0.00	0.00	0.00
14 300 00	89.76	179 70	10 684 70	-3 118 83	966 40	3 106 03	0.00	0.00	0.00
14,00.00	80.76	170.70	10,004.70	2 210 02	066 02	3,130.55	0.00	0.00	0.00
4,400.00	09.70	179.70	10,000.12	-3,210.83	900.92	3,230.32	0.00	0.00	0.00
14,500.00	89.76	179.70	10,685.54	-3,318.83	967.45	3,396.11	0.00	0.00	0.00
14.600.00	89.76	179.70	10.685.96	-3.418.83	967.97	3,495,70	0.00	0.00	0.00
14,700,00	89 76	179.70	10,686.37	-3,518 82	968 49	3,595,29	0.00	0.00	0.00
14 800 00	80 76	179 70	10 686 79	-3 618 82	960 01	3 604 88	0.00	0.00	0.00
1/ 000.00	80.70	170 70	10,000.73	-3,010.02	0.60 53	3 704 47	0.00	0.00	0.00
14,900.00	09.70	1/9./0	10,007.21	-3,/10.82	909.53	3,194.41	0.00	0.00	0.00
15,000.00	89.76	179.70	10,687.63	-3,818.82	970.06	3,894.06	0.00	0.00	0.00
15.100.00	89.76	179.70	10,688.05	-3,918.82	970.58	3,993.65	0.00	0.00	0.00
15,200.00	89.76	179.70	10,688 46	-4.018 81	971 10	4,093 24	0.00	0.00	0.00
15 300 00	89.76	179 70	10.688.88	-4 118 81	971 62	4,192,83	0.00	0.00	0.00
15 400 00	89.76	179 70	10 689 30	_4 218 81	972 15	4 292 42	0.00	0.00	0.00
	00.70	110.10		1,210.01	572.15	, LUL. TL	0.00	0.00	0.00
15,500.00	89.76	179.70	10,689.72	-4,318.81	972.67	4,392.01	0.00	0.00	0.00
15,600.00	89.76	179.70	10.690.14	-4.418.80	973.19	4,491.60	0.00	0.00	0.00

,

Database:	HOPSPP	i gode s	an failing an	Local	Co-ordinate R	eference:	Well Radius CC	6_7 Federal	Com 52H
Company:		DESIGNS	ang ang san	TVD R	eference:		RKB=26.5' @ 2	985.40ft	the second second
Project:	PRD NM DIREC	TIONAL PLA	NS (NAD 1983) MD Re	ference:	Alex - Stars - Stars	RKB=26.5' @ 2	985.40ft	the second s
Site:	Radius CC 6_7			North	Reference	and the second	Grid		
Well:	Radius CC 6_7 F	-ederal Com	52H	Survey	y Calculation N	Aethod:	Minimum Curva	ature	
wendore: Desian:	Vveiloore #1 Permitting Plan	andra a star a star Angles a star a star Angles a star a star Angles a star	n an	- Bangar	and sign for	in the second		40 - Q - C	
			terret en est "terreter", e viertetetet En en el est en en el est e	ne son - 1º - qui escarat - esta -		anti constanta		ar and the second s	
Planned Survey	a ha an	ning and a start		inter all state		Set . Alt Call	AN STATION	a the second	
Measured		15 - 14 - A	Vertical	en e		Vertical	Dogleg	Build	Turn
Depth	Inclination A	zimuth	Depth	+N/-S	+E/-W	Section	Rate	Rate	Rate
(ft)	(°)	(°)	(ft)		(ft)	ू (ft) ू	(°/100ft)	(°/100ft)	}{(°/100ft)}, , , , , , , , , , , , , , , , , , ,
15,700.00	89.76	179.70	10,690.55	-4,518.80	973.71	4,591.19	0.00	0.00	0.00
15,800.00	89.76	179.70	10,690.97	-4,618.80	974.24	4,690.78	0.00	0.00	0.00
15,900.00	09.70	1/9./0	10,091.39	-4,718.80	9/4./6	4,790.37	0.00	0.00	0.00
16,000.00	89.76	179.70	10,691.81	-4,818.79	975.28	4,889.96	0.00	0.00	0.00
16,100.00	89.76 89.76	179.70	10,092.23	-4,918.79 -5 018 70	975.80	4,989.55 5 089 11	0.00	0.00	0.00
16,200.00	89.76	179.70	10,693.04	-5,118 79	976.33	5 188 73	0.00	0.00	0.00
16,400.00	89.76	179.70	10,693.48	-5,218.79	977.37	5,288.32	0.00	0.00	0.00
16 500 00	80 76	170 70	10 603 00	-5 319 79	077 20	5 397 01	0.00	0.00	0.00
16,500.00	09.70 89.76	179.70	10,093.90	-0,010.70	977.89 978.41	5 487 50	0.00	0.00	0.00
16,700.00	89.76	179.70	10.694.73	-5.518.78	978 94	5,587.09	0.00	0.00	0.00
16,800.00	89.76	179.70	10.695.15	-5.618.78	979.46	5.686.67	0.00	0.00	0.00
16,900.00	89.76	179.70	10,695.57	-5,718.77	979.98	5,786.26	0.00	0.00	0.00
17,000.00	89.76	179.70	10.695.99	-5.818.77	980 50	5,885,85	0.00	0.00	0.00
17,100.00	89.76	179.70	10.696.41	-5.918.77	981.03	5,985,44	0.00	0.00	0.00
17,200.00	89.76	179.70	10,696.82	-6,018.77	981.55	6,085.03	0.00	0.00	0.00
17,300.00	89.76	179.70	10,697.24	-6,118.77	982.07	6,184.62	0.00	0.00	0.00
17,400.00	89.76	179.70	10,697.66	-6,218.76	982 59	6,284.21	0.00	0.00	0.00
17,500.00	89.76	179.70	10,698.08	-6.318 76	983 12	6.383.80	0.00	0.00	0.00
17.600.00	89.76	179.70	10,698.50	-6,418.76	983 64	6,483.39	0.00	0.00	0.00
17,700.00	89.76	179.70	10,698.91	-6,518.76	984.16	6,582.98	0.00	0.00	0.00
17,800.00	89.76	179.70	10,699.33	-6,618.75	984 68	6,682.57	0.00	0.00	0.00
17,900.00	89.76	179.70	10,699.75	-6,718.75	985 21	6,782.16	0.00	0.00	0.00
18,000.00	89.76	179.70	10,700.17	-6,818.75	985 73	6,881.75	0.00	0.00	0.00
18,100.00	89.76	179.70	10,700.59	-6,918.75	986 25	6,981.34	0.00	0.00	0.00
18,200.00	89.76	179.70	10,701.00	-7,018.75	986 77	7,080.93	0.00	0.00	0.00
18,300.00	89.76	179.70	10,701.42	-7,118.74	987.29	7,180.52	0.00	0.00	0.00
18,400.00	89.76	179.70	10,701.84	-7,218.74	987.82	7,280.11	0.00	0.00	0.00
18,500.00	89.76	179.70	10,702.26	-7,318.74	988.34	7,379.70	0.00	0.00	0.00
18,600.00	89.76	179.70	10,702.68	-7,418.74	988.86	7,479.29	0.00	0.00	0.00
18,700.00	89.76	1/9.70	10,703.09	-7,518.73	989.38	7,578.88	0.00	0.00	0.00
18,800.00 18 QAA AA	89.76 RQ 76	179.70	10,703.51	-7,010./3 -7,718,79	989.91 990 42	1,0/0.4/ 7778.06	0.00	0.00	0.00
10,000.00	09.70	4	10,703.93	-1,110.73	550.45	7,770.00	0.00	0.00	0.00
19,000.00	89.76	1/9.70	10,704.35	-7,818.73	990.95	1,877.65	0.00	0.00	0.00
19,100.00	09.70 20.76	170.70	10,704.77	-1,310./3	331.41 002 hn	1,911.24 8 076 93	0.00	0.00	0.00
19,200.00	89.70	179.70	10,705.10	-0,010.72	992.00	8 176 42	0.00	0.00	0.00
19,400.00	89.76	179.70	10,706.02	-8,218.72	993.04	8,276.01	0.00	0.00	0.00
10 500 00	PO 76	170 70	10 706 44	9 219 70	002 56	9 375 60	0.00	0.00	0.00
19,000.00	09.70 80.76	179.70	10,700.44	-0,310.72	993.00 001 00	0,3/3.6U 8 475 10	0.00	0.00	0.00
19,000.00	89.76	179 70	10,707.27	-0, +10.71	994.09 994.61	8 574 78	0.00	0.00	0.00
19,800.00	89.76	179 70	10,707 69	-8.618 71	995 13	8.674.37	0.00	0.00	0.00
19,900.00	89.76	179.70	10,708.11	-8,718.71	995.65	8,773.96	0.00	0.00	0.00
20,000,00	80 76	170 70	10 708 53	_8 818 71	006 17	8 873 55	0.00	0.00	0.00
20,000.00	89.70	179.70	10,700.00	-0,010.71	990.17 996.70	0,073.00 8 973 1 <i>1</i>	. 0.00	3 0.00 0.00	0.00
20,100.00	89.76	179 70	10,709.36	-0,310.70	997 22	9 072 73	0.00	0.00	0.00
20,200.00	89.76	179.70	10,709 78	-9,118.70	997 74	9,172.32	0.00	0.00	0.00
20,400.00	89.76	179.70	10,710.20	-9,218.70	998.26	9,271.91	0.00	0.00	0.00
20 500 00	00.76	170 70	10,710,60	0.249.60	000 70	0.274 50	0.00	0.00	0.00
20,000.00 20 600 00	09./0 80.76	170 70	10,710.62	-9,318.69	998.79	9,371.50 0,471.00	0.00	0.00	0.00
20,000.00	03.10 80.76	179.70	10,711.04	-9,410.09	000 83	9,471.09	0.00	0.00	0.00
20,700.00	89 76	179 70	10,711 87	-9,618.69	1,000,35	9,670.27	0.00	0.00	0.00
20,900.00	89.76	179.70	10,712.29	-9,718.69	1,000.88	9,769,86	0.00	0.00	0.00
24,000,00	00.70	470 70	40 740 74	0.040.00	1 001	0.000.45	0.00	0.00	0.00
21,000.00	89.76	1/9.70	10,/12.71	-9,818.68	1,001.40	9,869.45	0.00	0.00	0.00

i.

,

Database: Company: Project:	HOPSPP ENGINEERING PRD NM DIREC	DESIGNS TIONAL PLA	.NS (NAD 198	3)	Co-ordinate R eference: ference:	Reference:	Well Radius C RKB=26.5' @ RKB=26.5' @	C 6_7 Federal C 2985 40ft 2985 40ft	om 52H
Vell: Wellbore: Design:	Radius CC 6_7 Radius CC 6_7 I Wellbore #1 Permitting Plan	Federal Com	52H	Surve	Reference: / Calculation	Méthod:	Grid Minimum Curv	ature	
Planned Survey									
Measured ***	Cyr Martines		Vertical	le inferentita alla	168 - S - 155	Vertical	Dogleg	Build	Turn
Depth. (ft)	Inclination . A (°)	Azimuth (°)	Depth (ft)	+N/-S (ft)	+E/-W	Section (ft)	Rate (°/100ft)	Rate (°/100ft)	Rate (°/100ft)
21,100.00 21,200.00	89.76 89.76	179.70 179.70	10,713.13 10,713.54	-9,918.68 -10.018.68	1,001.92 1.002.44	9,969.03 10.068.62	0.00 0.00	0.00 0.00	0.00 0.00
21,300.00	89.76	179.70	10,713.96	-10,118.68	1,002.97	10,168.21	0.00	0.00	0.00
21,400.00	09.70 80.76	179.70	10,714.30	-10,218.67	1,003.49	10,267.80	0.00	0.00	0.00
21,600.00	89.76	179.70	10,715.22	-10,418.67	1,004.01	10,367.39	0.00	0.00	0.00
21,644.13	89.76	179.70	10,715.40	-10,462.80	1,004.76	10,510.93	0.00	0.00	0.00
Design Targets	and a market a market and a second	an a she							a de participa de la companya de la La companya de la comp
Target Name - hit/miss target - Shape	Dip Angle D	ip Dir. T (°)	VD +N/ ft) (ft	-S +E/-W (ft)	Northi	ng Ea	sting. usft)	se ann fi sti Rig den de 14	an de ser an de ser de ser La ser de ser
FTP (Radius CC 6_7 - plan hits target c - Point	0.00 enter	0.00 10,6	71.40 (63.14 949.	78 456,2	269.68 6	36,681.46 32° 15	5' 14.343123 N	104° 1' 29.667867
PBHL (Radius CC 6_7 - plan hits target c - Point	0.00 0.00	0.00 10,7	15.40 -10,40	52.80 1,004.	76 445,7	744.62 6	36,736.44 32° 13	3' 30.186652 N	104° 1' 29.379670
Plan Annotations Measu Dep (ft 3,7 4,3 9,2 10,3 11,1 21,6	ured Vertica th Depth 50.00 3,750 50.02 4,345 55.61 9,153 40.36 10,217 17.96 10,671 44.13 10,715	1 0.00 0.65 0.80 0.57 0.40 0.40 -1	Local Coor N/S (ft) 0.00 38.38 664.92 621.17 63.14 0,462.80	dinates +E/-W (ft) 0.00 49.46 856.95 946.86 949.78 1,004.76	Commen Build 2.00 Hold 12.0 Turn 2.00 KOP, Bui Landing F TD at 216	it)°/100' 0° Tangent)°/100' Id 10.00°/100 Point S44.13' MD			
				•.					



OXY USA Inc APD ATTACHMENT: SPUDDER RIG DATA

OPERATOR NAME / NUMBER: <u>OXY USA Inc</u>

1. SUMMARY OF REQUEST:

Oxy USA respectfully requests approval for the following operations for the surface hole in the drill plan:

1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
 - **a.** After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
 - **b.** The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has been reached.
- 3. A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.
 - **a.** A means for intervention will be maintained while the drilling rig is not over the well.
- 4. Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- 6. Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
 - **a.** The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
 - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. Oxy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- 8. Once the rig is removed, Oxy will secure the wellhead area by placing a guard rail around the cellar area.



Oxy USA Inc. - Radius CC 6_7 Federal Com 52H

1. Geologic Formations

TVD of target	10715'	Pilot Hole Depth	N/A
MD at TD:	21644'	Deepest Expected fresh	397'
		water:	

Delaware Basin

Formation	TVD - RKB	Expected Fluids
Rustler	98	
Salado	536	Salt
Castile	1,300	Salt
Lamar/Delaware	2,759	Oil/Gas/Brine
Bell Canyon	2,805	Oil/Gas/Brine
Cherry Canyon	3,666	Oil/Gas/Brine
Brushy Canyon	4,905	Losses
Bone Spring	6,484	Oil/Gas
1st Bone Spring	7,471	Oil/Gas
2nd Bone Spring	8,236	Oil/Gas
3rd Bone Spring	9,341	Oil/Gas
Wolfcamp	9,704	Oil/Gas

*H2S, water flows, loss of circulation, abnormal pressures, etc.

2. Casing Program

										Buoyant	Buoyant
Tiole Size (in)	Casing	Interval 👘 🔬 🛫	Csg. Size	Weight		1	* A	SF	SE D	Body SF	Joint SF
size (in)	From (ft)	To (ft)	(in)	(lbs)	Grade	÷.	Conn.	Collapse	SF DUISU	Tension	Tension
14.75	0	476	10.75	40.5	J-55		BTC	1.125	1.2	1.4	1.4
9.875	0	10240	7.625	26.4	L-80 HC		BTC	1.125	1.2	1.4	1.4
6.75	0	10790	5.5	26	P-110 CYHP		TORQ SFW	1.125	1.2	1.4	1.4
6.75	10790	21644	5	21.4	P-110 CYHP		TORQ DQW	1.125	1.2	1.4	1.4
									SF Values will r	neet or Exceed	

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h *Oxy requests the option to set casing shallower yet still below the salts if losses or hole conditions require this. Cement volumes may be adjusted if casing is set shallower and a DV tool may be run in case hole conditions merit pumping a second stage cement job to comply with permitted top of cement. If cement circulated to surface during first stage, we will drop a cancelation cone and not pump the second stage.

*Oxy requests the option to run production casing with DQX, SF TORQ, and/or DQW TORQ connections to accommodate hole conditions or drilling operations.

Annular Clearance Variance Request

As per the agreement reached in the Oxy/BLM meeting on Feb 22, 2018, Oxy requests permission to allow deviation from the 0.422" annular clearance requirement from Onshore Order #2 under the following conditions:

- 1. Annular clearance to meet or exceed 0.422" between intermediate casing ID and production casing coupling only on the first 500' overlap between both casings.
- 2. Annular clearance less than 0.422" is acceptable for the curve and lateral portions of the production open hole section.

	Y or N
Is casing new? If used, attach certification as required in Onshore Order #1	Y
Does casing meet API specifications? If no, attach casing specification sheet.	Y

Oxy USA Inc Radius CC 6_7 Federal Com 52H	
Is premium or uncommon casing planned? If yes attach casing specification sheet.	Y
Does the above casing design meet or exceed BLM's minimum standards? If not provide justification (loading assumptions, casing design criteria).	Y
Will the intermediate pipe be kept at a minimum 1/3 fluid filled to avoid approaching the collapse pressure rating of the casing?	Y
Is well located within Conitan Reef?	N
IS well located within Capital Reel?	1
If yes, does production casing cement tie back a minimum of 50' above the Reef?	
Is well within the designated 4 string boundary.	
	interior and the state
Is well located in SOPA but not in R-111-P?	N
If yes, are the first 2 strings cemented to surface and 3 rd string cement tied back 500' into previous casing?	
Is well located in R-111-P and SOPA?	N
If yes, are the first three strings cemented to surface?	
Is 2 nd string set 100' to 600' below the base of salt?	
いたかべいないとなる。1989年にあると、1989年に発展したなどの特徴であるから、1977年にあるでは、1987年にある。1987年にある。1987年になったので、1979年になった。1977年になった	1979年の1997日 1997
Is well located in high Cave/Karst?	Ν
If yes, are there two strings cemented to surface?	
(For 2 string wells) If yes, is there a contingency casing if lost circulation occurs?	
Constant of the State of the St	
Is well located in critical Cave/Karst?	Ν
If yes, are there three strings cemented to surface?	

3. Cementing Program

ichting i rogra									
Casing Strip	a V	# Sks	Wt. (lb/gal)	Yld (ft3/sack)	H20 (gal/sk		500# Comp. Strength (hours)	Slurry D	escription
Surface (Lead	d)	N/A	N/A	N/A	N/A		N/A	N/A	
Surface (Tail	l)	385	14.8	1.33	6.365		5:26	Class C Cement, Acc	elerator
Intermediate 1st Stag	ge (Lead)	N/A	N/A	N/A	N/A		N/A	N/A	
Intermediate 1st Sta	ge (Tail)	702	13.2	1.65	8.640		11:54	Class H Cement, Reta	arder, Dispersant, Salt
Intermedia	te 2nd Sta	ge (Tail Shırry) to be pumpe	d as Bradenho	ead Squee	ze f	rom surface, d	own the Intermedia	te annulus
Intermediate 2nd Stag	ge (Lead)	N/A	N/A	N/A	N/A		N/A	N/A	
Intermediate 2nd Sta	.ge (Tail)	634	12.9	1.92	10.41		23:10	Class C Cement, Acc	elerator
Production (Le	ad)	N/A	N/A	N/A	N/A	N/A		N/A	
Production (Ta	uil)	1141	13.2	1.38	6.686		3:39	Class H Cement, Reta	arder, Dispersant, Salt
		Casing S	tring	Top	o (ft)	B	ottom (ft)	% Excess	
		Surface (I	Lead)	N	/A	N/A		N/A	
		Surface (Tail)		0		476	100%	
	Intermediate 1st		Stage (Lea	ad) N	/A		N/A	N/A	
Intermediate 1st		Stage (Ta	il) 51	55		10240	5%		
Intermediate 2nd S		Stage (Lea	tage (Lead) N			N/A	N/A		
· [Interm	ediate 2nd	Stage (Ta	uil)	0		5155	10%	
	F	roduction	(Lead)	N	I/A		N/A	N/A	

Production (Tail)

9740

21644

;

20%

Oxy USA Inc. - Radius CC 6_7 Federal Com 52H

Offline Cementing

Oxy requests a variance to cement the 9.625" and/or 7.625" intermediate casing strings offline in accordance to the approved variance, EC Tran 461365.

The summarized operational sequence will be as follows:

- 1. Run casing as per normal operations. While running casing, conduct negative pressure test and confirm integrity of the float equipment (float collar and shoe).
- 2. Land casing.
- 3. Fill pipe with kill weight fluid, and confirm well is static.
 - a. If well is not static notify BLM and kill well.
 - b. Once well is static notify BLM with intent to proceed with nipple down and offline cementing.
- 4. Set and pressure test annular packoff.
- 5. After confirmation of both annular barriers and internal barriers, nipple down BOP and install cap flange. If any barrier fails to test, the BOP stack will not be nippled down until after the cement job is completed.
- 6. Skid rig to next well on pad.
- 7. Confirm well is static before removing cap flange.
- 8. If well is not static notify BLM and kill well prior to cementing or nippling up for further remediation.
- 9. Install offline cement tool.
- 10. Rig up cement equipment.
 - a. Notify BLM prior to cement job.
- 11. Perform cement job.
- 12. Confirm well is static and floats are holding after cement job.
- 13. Remove cement equipment, offline cement tools and install night cap with pressure gauge for monitoring.

Oxy requests permission to adjust the CBL requirement after bradenhead cement jobs, on 7-5/8" intermediate casings, as per the agreement reached in the OXY/BLM meeting on September 5, 2019.

Three string wells:

- CBL will be required on one well per pad
- If the pumped volume of cement is less than permitted in the APD, BLM will be notified and a CBL may be run
- Echometer will be used after bradenhead cement job to determine TOC before pumping top-out cement

4. Pressure Control Equipment

BOP installed and		Min.		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
tested before drilling which hole?	Size?	Required WP	Туре			Tested to:	
9.875" Hole	13-5/8"	5M	Annula		✓	70% of working	
		5M	Blind Ra	m	✓	pressure	
			Pipe Rar	n			
			Double Ram		✓	250 psi / 5000 psi	
			Other*	-			
6.75" Hole	13-5/8"	5M	Annula			100% of working pressure	
		10M	Blind Ra	m	1		
			Pipe Ram			250 mai / 5000 mai	
			Double R	am	· 🗸	250 psi / 5000 psi	
			Other*				

3

*Specify if additional ram is utilized.

Per BLM's Memorandum No. NM-2017-008: Decision and Rationale for a Variance Allowing the Use of a 5M Annular Preventer with a 10M BOP Stack, Oxy requests to employ a 5M annular with a 10M BOPE stack in the pilot and lateral sections of the well and will ensure that two barriers to flow are maintained at all times. Please see attached Well Control Plan.

Oxy will utilize a 5M annular with a 10M BOPE stack. The BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded all the components installed will be functional and tested.

Pipe rams will be operationally checked each 24 hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment will include a Kelly cock and floor safety valve (inside BOP) and choke lines and choke manifold. See attached schematics.

	Formation integrity test will be performed per Onshore Order #2.				
	On Exploratory wells or on that portion of any well approved for a 5M BOPE system or				
	greater, a pressure integrity test of each casing shoe shall be performed. Will be tested in				
	accord	lance with Onshore Oil and Gas Order #2 III.B.1.i.			
	A variance is requested for the use of a flexible choke line from the BOP to Choke				
	Manifold. See attached for specs and hydrostatic test chart.				
	Y	Are anchors required by manufacturer?			
	A mul	tibowl or a unionized multibowl wellhead system will be employed. The wellhead			
	and co	onnection to the BOPE will meet all API 6A requirements. The BOP will be tested			
	per Onshore Order #2 after installation on the surface casing which will cover testing				
	requirements for a maximum of 30 days. If any seal subject to test pressure is broken the				
system must be tested. We will test the flange connection of the wellhead with a test					
	that is	directly in the flange. We are proposing that we will run the wellhead through the			
	rotary	prior to cementing surface casing as discussed with the BLM on October 8, 2015.			
	See at	tached schematics.			

BOP Break Testing Request

Oxy requests permission to adjust the BOP break testing requirements as per the agreement reached in the OXY/BLM meeting on September 5, 2019. A separate sundry will be sent prior to spud that reflects the pad based break testing plan.

BOP break test under the following conditions:

- After a full BOP test is conducted
- When skidding to drill an intermediate section where ICP is set into the third Bone Spring or shallower.

• When skidding to drill a production section that does not penetrate into the third Bone Spring or deeper. If the kill line is broken prior to skid, two tests will be performed.

- 1) Wellhead flange, co-flex hose, kill line connections and upper pipe rams
- 2) Wellhead flange, HCR valve, check valve, upper pipe rams

If the kill line is not broken prior to skid, only one test will be performed.

1) Wellhead flange, co-flex hose, check valve, upper pipe rams

Oxy USA Inc. - Radius CC 6_7 Federal Com 52H

5. Mud Program

De	pth		Weight		Weter Looo
From (ft)		ı ype	(ppg).	viscosity	vvale f Loss
0	476	Water-Based Mud	8.6-8.8	40-60	N/C
		Saturated Brine-			
476	10240	Based or Oil-Based	8.0-10.0	35-45	N/C
		Mud			
10240	21644	Water-Based or Oil-	0 5 12 0		N/C
10240	21044	Based Mud	9.3-13.0	38-30	IN/C

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times. The following is a general list of products: Barite, Bentonite, Gypsum, Lime, Soda Ash, Caustic Soda, Nut Plug, Cedar Fiber, Cotton Seed Hulls, Drilling Paper, Salt Water Clay, CACL2. Oxy will use a closed mud system.

What will be used to monitor the loss or gain of fluid? PVT/MD Totco/Visual Monitoring

6. Logging and Testing Procedures

Logg	ing, Coring and Testing	· An she was the state of the second	
Yes	Will run GR from TD to	surface (horizontal well – vertic	al portion of hole). Stated logs
	run will be in the Comp	letion Report and submitted to th	e BLM.
No	Logs are planned based	on well control or offset log info	rmation.
No	Drill stem test? If yes, e	explain	
No	Coring? If yes, explain		
Addi	tional logs planned	Interval	
No	Resistivity		,
No	Density		2
No	CBL		
Yes	Mud log	ICP - TD	
No	PEX		

7. Drilling Conditions

Condition	Specify	what type and where?
BH Pressure at deepest TVD		7244 psi
Abnormal Temperature		No
BH Temperature at deepest TVD		166°F

Pump high viscosity sweeps as needed for hole cleaning. The mud system will be monitored visually/manually as well as with an electronic PVT. The necessary mud products for additional weight and fluid loss control will be on location at all times. Appropriately weighted mud will be used to isolate potential gas, oil, and water zones until such time as casing can be cemented into place for zonal isolation.

Hydrogen Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered, measured values and formations will be provided to the BLM.

H2S is present N Y H2S Plan attached Yes/No 8. Other facets of operation Will the well be drilled with a walking/skidding operation? If yes, describe. Yes We plan to drill the four well pad in batch by section: all surface sections, • intermediate sections and production sections. The wellhead will be secured with a night cap whenever the rig is not over the well. Will more than one drilling rig be used for drilling operations? If yes, describe. Yes Oxy requests the option to contract a Surface Rig to drill, set surface casing, and cement for this well. If the timing between rigs is such that Oxy would not be able to preset surface, the Primary Rig will MIRU and drill the well in

its entirety per the APD. Please see the attached document for information

Oxy USA Inc. - Radius CC 6 7 Federal Com 52H

Total estimated cuttings volume: 1530.3 bbls.

on the spudder rig.

9. Company Personnel

Name	<u>Title</u>	Office Phone	<u>Mobile Phone</u>
Garrett Granier	Drilling Engineer	713-513-6633	832-265-0581
William Turner	Drilling Engineer Supervisor	713-350-4951	661-817-4586
Simon Benavides	Drilling Superintendent	713-522-8652	281-684-6897
Diego Tellez	Drilling Manager	713-350-4602	713-303-4932

Drilling Plan

6