Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR OF SUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Evniree: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS OF ARTESIA

NMNM18613A 6. If Indian, Allottee or Tribe Name

abandoned wei	,					
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreen	ment, Name and/or No.	
Type of Well Oil Well			8. Well Name and No. NOEL HENSLEY FED COM 202H			
Name of Operator MATADOR PRODUCTION CO	R LINK `ces.com		9. API Well No. 30-015-46294-00-X1			
3a. Address ONE LINCOLN CENTER 5400 DALLAS, TX 75240	e No. (include area code) 5-627-2465		10. Field and Pool or E WILDCAT	xploratory Area		
4. Location of Well (Footage, Sec., T.			11. County or Parish, S	tate		
Sec 19 T24S R28E NENW 25 32.209740 N Lat, 104.130676			EDDY COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION						
☐ Notice of Intent	ce of Intent Deepen Pro		☐ Product	ction (Start/Resume)		
_ (☐ Alter Casing ☐	Hydraulic Fracturing	□ Reclam	ation	☐ Well Integrity	
Subsequent Report	☐ Casing Repair ☐	New Construction	☐ Recomp	olete	Other	
☐ Final Abandonment Notice	☐ Change Plans ☐	Plug and Abandon	□ Tempor	arily Abandon	Drilling Operations	
	☐ Convert to Injection ☐	Plug Back	☐ Water I	Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BLM Bond No. NMB0001079 Surety Bond No. RLB0015172 10/23/2019 Well spud. Rotate f/148'-410'. Run total of 8 jts, 13 3/8", 54.5#, J-55, BTC casing t/400'. Pressure test to 2200 psi and cement 13 3/8" casing. Pump 30 bbls fresh water, 127 bbls Class C tail cement (530 sx) @ 14.8 ppg, 1.35 yield. No cement to surface. Called BLM and received permission to tag hard cement with 1" tubing and perform top out job. Tag hard cement at 35', pump 20 bbls and had 5 bbls cement returns to surface. 11/4/2019 BOPE tests held for 10 minutes remove check valve and test BOPS, 8000 psi, test casing to 1500 psi, Rotate f/410'-2,570'. 11/5/2019 Run 9 5/8", 40#, J-55 BTC casing to 2560', test cement lines 3000 psi, pump 30 bbls 8.4 ppg spacer. Pump 223 bbls (735 sxs) Class C lead slurry @ 13.5 ppg, 1.70 yield. Mix and pump 50.0						
Electronic Submission #501574 verified by the BLM Well Information System For MATADOR PRODUCTION COMPANY, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 01/31/2020 (20PP1064SE)						
Traine (1 time at type a) 1 AIVINIT R	LINIX	Title PRODU	CTION AN	AL 101		
Signature (Electronic Submission) Date 01/30/2020						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By ACCEPT	JONATHO TitlePETROLE	N SHEPAR UM ENGINI		Date 02/13/2020		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	office Carlsbac	Office Carlsbad				
Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						
(Instructions on page 2)						

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #501574 that would not fit on the form

32. Additional remarks, continued

bbls (210 sxs) Class C tail slurry @ 14.8 ppg. Had 72 bbls cement back @ surface. Increased pressure to 500 psi over to 1350 psi. Held pressure 5 minutes. 11/6/2019 Test casing 1500 psi for 30 minutes. Drill f/2,580'-8,400'.

11/10/2019 M/U shoe track and test float equipment; Good Test. Run 60 joints, 7 5/8", 29.7#, P-110

casing to 2,700'.

11/11/2019 Test lines t/6500 psi, pump 20 bbls of 8.4 ppg. Pump lead cement w/470 sxs (195 bbls) yield 2.33, mix water 13.54 @ 11.5 ppg. Mix and pump tail cement w/135 sxs (32.9 bbls) yield 1.37, mix water 6.49 @ 13.5 ppg. Held 5 minutes, bleed pressure and 3.0 bbls back, 1 bbls of cement to

surface.

11/12/2019 Finish final cut on 7 5/8" casing set BOP's, RU 4 1/2" dp, test lower seals to 4,200 psi, middle and upper seals to 10,000 psi, good test.

11/14/2019 Drill curve f/9,465'-14,164'.

11/17/2019 Run 4 1/2" x 5 1/2" production casing 13.5#, P-110. Test lines to/8000 psi. Pump 40 bbls of 8.4 ppg. Pump lead cement w/250 sxs (90 bbls) yield 2.018, mix water 11.24 @ 12.0 ppg. Pump tail cement w/690 sxs (168 bbls) yield 1.375, displace w/273 bbls fresh water, bump plug w/3500 psi and press up 500 psi to 4000 psi. Shut in for 5 minutes.

11/18/2019 Test seals and void t/8500 psi, walk catwalk forward. Release rig @ 06:00.

See attached Casing and Cement Actuals

Revisions to Operator-Submitted EC Data for Sundry Notice:#501574

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

DRG NOI

DRG SR

Lease:

NMNM18613A

NMNM18613A

Agreement:

Operator:

MATADOR PRODUCTION COMPANY 5400 LBJ FREEWAY, SUITE 1500 DALLAS, TX 75240 Ph: 575-623-6601

Admin Contact:

TAMMY R LINK

PRODUCTION ANALYST

E-Mail: tlink@matadorresources.com

Ph: 575-627-2465

Tech Contact:

TAMMY R LINK PRODUCTION ANALYST E-Mail: tlink@matadorresources.com

Ph: 575-627-2465

Location:

State: County: NM **EDDY**

Field/Pool:

WILDCAT; WOLFCAMP

Well/Facility:

NOEL HENSLEY FED COM 202H Sec 19 T24S R28E Mer NMP NENW 250FNL 1491FWL

MATADOR PRODUCTION COMPANY ONE LINCOLN CENTER 5400 LBJ FREEWAY SUITE 1500 DALLAS, TX 75240 Ph: 972.371.5200

TAMMY R LINK

PRODUCTION ANALYST

E-Mail: tlink@matadorresources.com

Ph: 575-627-2465

TAMMY R LINK PRODUCTION ANALYST E-Mail: tlink@matadorresources.com

Ph: 575-627-2465

NM EDDY

WILDCAT

NOEL HENSLEY FED COM 202H Sec 19 T24S R28E NENW 250FNL 1491FWL 32.209740 N Lat, 104.130676 W Lon