Form 3160-5 (Tune 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137

NMLC028784C

Expires:	January	31,	201
Lease Serial No.			

Do not use th	is form for proposals to a	drill or to re-	anton ball la L	() E.S	<u></u>			
Do not use this form for proposals to drill or to re-enter(an) is 102.5 abandoned well. Use form 3160-3 (APD) for such proposals.					If Indian, Allottee	or Tribe Name		
SUBMIT IN TRIPLICATE - Other instruction			7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well					8. Well Name and N			
☑ Oil Well ☐ Gas Well ☐ Other			GRAYBURG DE	EP 25 FED 5				
Name of Operator CONOCOPHILLIPS COMPAN	Contact: (VY E-Mail: GREG.BRY	GREG BRYAI ANT@BASICE	NT NERGYSERVIC	ES.COM	9. API Well No. 30-015-03083	-00-S1		
3a. Address 3b. Phone 925 N ELDRIDGE PARKWAY Ph: 432 HOUSTON, TX 77079 Fx: 432-					10. Field and Pool or Exploratory Area UNDESIGNATED			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State				
Sec 25 T17S R29E NENE 330FNL 660FEL					EDDY COUNTY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE,	REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				~			
☐ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Producti	ion (Start/Resume)	□ Water S	Shut-Off	
. —	☐ Alter Casing	☐ Hydr	aulic Fracturing	☐ Reclama	ation	- □ Well In	itegrity	
Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp		☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	🛭 Plug	and Abandon	☐ Tempora	arily Abandon		1	
	☐ Convert to Injection	Plug]	Back	☐ Water D	Disposal			
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit 11/21/19 - MIRU, LD Rods 11/25/19 - Set 5-1/2 CIBP @ 612/2/19 - Tag BP @ 6555' - Ci 12/3/19 - Spot 25sx cmt @ 55:cmt 12/4/19 - Tag @ 2620', Perf @ 1928', Perf @ 1454', pressure 12/5/19 - Tag @ 335', Perf @ 12/6/19 Tag @ 335', Perf @ 12/6/19	andonment Notices must be filed nal inspection. 8555' rc. hole w/ MLE. Cap. BP w 56'-5302'. Spot 40sx cmt (0) 2102', pressure up. BLM up. BLM ok'd spot. Spot 20925'- Spz. 40sx cmt - Tac	/ 25sx_cmt.to. ① 4228' - Tag OK'd_spot_S 5sx_cmt @ 15 1 @ 800' Per	6301' @ 3910'_Perf oot 25 <u>sx cmt @</u> 520' f @ 475' - Sqz op off well. RD	@ 2868' - Soo 2172' - Tag	n, have been completed RECI QZ 55sx RE DU	AMATION P ATTACHI CCLAM JE 6 - 6	ROCEDUF ED ATIO	
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) GREG BR	Electronic Submission #49 For CONOCOPH itted to AFMSS for process	IILLIPS COMP ing by DEBOR	ANY, sent to the	e Carlsbad on 12/12/201	9 (19PP1729SE)			
•	,	ņ,		AC	CCEPTED FO	R RFCO	RN	
Signature (Electronic S	ubmission)		Date 12/11/20					
	THIS SPACE FOI	R FEDERAL	OR STATE (OFFICE US	SE DEC 13	2019		
Approved By			Title		DMCKinne	1 16		
onditions of approval, if any, are attached ertify that the applicant holds legal or equi thich would entitle the applicant to conduc	itable title to those rights in the s	ot warrant or ubject lease	Office		BUREAU OF LAND N CARLSBAD FIEL	ANAGEMENT D OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crune for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/mm

IN M. RID

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filling the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filling the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612