Form 3160-5 (April 2004)

N.M. Oil Cons. DIV-Dist. 2

UNITED TRAFES W. Grand Avenue DEPARTMENT OF THE INTERFERENTIAM 88210

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007


٧.	Licase scriai No.
	LC-067858
	If Indian Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE- Other instructions on reverge side IVED	7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well	Empire Abo Unit / 70945					
	8. Well Name and No. Empire Abo Unit "M" #151					
2. Name of Operator BP America Production Company	9. API Well No. 30-015-22658					
3a. Address 3b. Phone No. (include area code) P. O. Box 1089 Eunice, New Mexico 88231 505-394-1600	10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Empire Abo 11. County or Parish, State					
400' FNL & 1450' FEL (Unit Letter "B") Section 11 - T18S - R27E	Eddy, New Mexico					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA					
TYPE OF SUBMISSION TYPE OF ACTION						
✓ Notice of Intent ✓ Acidize ✓ Deepen ✓ Production (Star Practure Treat ✓ Notice of Intent ✓ Reclamation	rt/Resume) Water Shut-Off Well Integrity					
Subsequent Report Casing Repair New Construction Recomplete	Other					
Change Plans Plug and Abandon Temporarily Aba	andon					
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of an						
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) This P&A plan replaces the one submitted by operator on 8/25/03. This revised procedure corrects errors in the previous sequence of operations and modifies specific methods of plugging this well: (please see attached wellbore diagrams for well data and proposed placement of plugs) 1. MIRU PU. Install BOP and test BOP and casing w/ 500 psi. 2. Spot 25 sx cement on top of existing CIBP set @ 6050'. 3. Circulate hole with 9.5 ppg mud-laden fluid. 4. Spot 25 sx cement plug (minimum of 100' in length) from 3950' - 4050' across DV Tool @ 3999'. 5. Spot 25 sx cement plug (minimum of 100' in length) from 3354' - 3454' across Glorieta. WOC and tag plug to confirm proper placement. 6. Spot 25 sx cement plug (minimum of 100' in length) from 950' - 1050' across 8 5/8" surface casing shoe. WOC & tag to confirm placement. 7. Spot 50 sk cement plug from 460' back to ground level to cover Yates and provide top plug; 5 1/2" casing left full of cement from 0' - 460'. 8. RD PU. Cut-off WH's and casings @ 3' below GL and install regulation Dry Hole Marker. 9. Clean location and prepare it for BLM and NMOCD inspections. Operations will commence after approval of this "Notice of Intent" and will be dependent on availability of equipment and services. Operations should require approximately 4 days and intent is to complete this P&A by June 28, 2006.						
D. C. Dodd / Sierra Engineering (432 / 683-8000) Title Agent for BP America	Production Company					
Signature Lanchall Date 6-01-06						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE APPROVED						
Approved by Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	JUN - 6 2006					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully states any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	to make to any department of the United PETROLEUM FNOINER					

Empire Abo Unit "M" #151 Empire Abo Field

API No. 30-015-22568

400' FNL & 1450' FEL Sec 11 - T18S - R27E Eddy County, New Mexico BLM has approved continued TA status only until 6/28/06.



Empire Abo Unit "M" #151 Empire Abo Field

API No. 30-015-22568

400' FNL & 1450' FEL Sec 11 - T18S - R27E Eddy County, New Mexico BLM has approved continued TA status only until 6/28/06.

	P&A Plan		Event
	RKB = 11' GL = 3604'		Date
Top Plug & Yates Plug 0' - 460' Approx 50 sx		Wellhead 6" - 900 Spud TD	8/1/1978 8/19/1978
Surface Shoe Plug 950' - 1050' 25 sx TAG		85/8" 24# K-55 @ 1000' Cmt'd w/ 250 sx "C" w/ 4% gel, 6# salt / sk & 1/4# celloflake / sk & 2% CaCl ₂ followed by 100 sx "C" w/ 6# salt / sk & 2% CaCl ₂ . Circ 60 sx.	8/4/1978
Glorieta Plug 3354' - 3454' 25 sx TAG			,
Across DV Tool 25 sx		DV Tool @ 3999'. Cmt'd Stage 2: 900 sx HLW w/ 8# salt / sk followed by 100 sx Class "C" w/ 8# salt / sk. Circ 105 sx to surface.	8/23/1978
<u>Cap CIBP @ 6050'</u> 25 sx		Set CIBP @ 6050'	6/24/1998
This CIBP was found to		6084' - 6100' w/ 2 SPF = 32 holes Acidize w/ 1000 gals 15%. TA'd as failed WO.	
be leaking during WO of June, 1998.		CIBP @ 6122' & TA'd Wellbore 6150 - 6165' 2 SPF Original Completion	1/22/1993 August, 1978
DCD 5/30/06	6239' PB 6310' TD	51/2" 15.5# K-55 @ 6310' TD w/ PENGO selective CA set (2 ECP's) 6143' - 6178'. Cmt'd Stage 1: 260 sx HLW w/ 10# 20/40 5# 100 mesh sand / sk followed by 200 sx Class "C" Thik-Set cmt. Circ 35 bbls cmt from above DV Tool @ 3999'.	8/23/1978