Form 3160-5 (August 1999)

its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

SUNDAT NOTICES AND REFORTS ON WELLS				D. Lease Seliai No	'·
Do not use this form for proposals to drill or to re-enter an				NMNM025528 6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals				6. If Indian, Allottee	e or Tribe Name
SUBMIT IN TRIPLICATE					
		TI, (J. William	7. Unit or CA Agre	ement Name and No.
1a. Type of Well 🔽 Oil Well 🔲 Ga:	s Well	JIIN .		8 Well Name and	No
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP				Eagle 33 P Federal 15	
DEVON ENERGY PRODUCTION COMPANY, LP				9. API Well No.	
3. Address and Telephone No.				30-015-33829	
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198				10. Field and Pool	
4. Location of Well (Report location clearly and in accordance with Federal requirements)*				Red Lake Glorieta-Yeso, NE	
330 FSL 890 FEL				12. County or Parish 13. State	
SEC 33 T17S R27E, UNIT P				Eddy	NM
<u> </u>	·	NOATE NATURE OF NOT	ICE DEDODI	<u> </u>	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION					
	☐ Acidina			n (Start/Bassima)	Water Shut-Off
✓ Notice of Intent	Acidize Alter Casing	☐ Deepen☐ Fracture Treat	Reclamat	n (Start/Resume) ion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomple		Other
Final Abandonment Notice	Change Plans	Plug and Abandon		rily Abandon	
	Convert to Injection	Plug Back	Water Dis		
 Describe Proposed or Completed Operations (Cl deepen directionally or recomplete horizontally, give su 					
the Bond No. on file with BLM/BIA. Required subseque	ent reports shall be filed within 30 days fo	llowing completion of the involved	perations. If the o	peration results in a multip	le completion or recompletion in a new
interval, a Form 3160-4 shall be filed once testing has t determined that the site is ready for final inspection)	seen completed. Final Abandonment No	tices shall be filed only after all requ	uirement, including	reclamation, have been c	ompleted, and the operator has
determined that the site is ready for final inspection,					
•					
Devon Energy Production Company, LI	P hereby requests approval to	n recomplete to the Quee	n-Gravhurg-S	an Andres ner the	following procedure:
l	norosy roquests approvant	o recomplete to the que	oluybulg c	an marco por the	ionouning procedure.
1. MIRU PU. TOH with rods and pump. ND tree, NU BOP. TOH with tubing.					
2. Pick up RBP and RIH on tubing. Set RBP at +/- 100' above top of Yeso perf. TOH with tubing.					
3. MIRU pump truck. Pressure test casing to 3000 psi. Dump 10 sand on top of RBP. RDMO pump truck.					
4. RIH with 4" casing gun and perforate the San Andres w/ 44 holes from 1769'-2592'. TOH with					
wireline, RDMO same.					
5. RIH with packer and set at +/- 50' above top of San Andres perf. MIRU BJ. Acidize & frac San Andres perfs.					
6. Open well up and flow back frac load until well dies.					
7. RIH with 8' perforated sub w/pi	n in bottom, SN, and tub	ing. Set SN +/-15' be	low bottom	perf.	
8. RIH with pump and rods. Hang well on and put well to test to battery.					
14. Thereby certify that the Jeregoing is In	the and correct				
	8				
Signed / kall	Name Title	Norvella Ada Sr. Staff Engineering		- Date	6/16/2006
(This space for Federal or State Office us	e)				
Approved by	Title			Date	
Conditions of approval, if any:					
Title 10 0.5.C. Section 1001, makes it a crime for any p	erson knowingly and willfully to make an	y department or agency of the office	o states any raise	, neutrous or traudulent sta	nements or representations to any matter with

*See Instruction on Reverse Side

APPROVED

JUN 2 2 2006

(ORIG. SGD.) ALEXIS C. SWOBODA

ALEXIS C. SWOBODA

PETROLEUM ENGINEER