Form 3160-5 (April 2004)

## UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

NM-84851				
:	If Indian	Allottee or Tribe Name		

5. Lease Serial No.

Do not use th abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. 26494						
1. Type of Well  ✓ Oil Well  2. Name of Operator  Chi Operation	8. Well Name and No. Carbon Valley "15" Fed #1  9. API Well No.						
3a Address P.O. Box 179	30-015-31281  10. Field and Pool, or Exploratory Area						
4. Location of Well (Footage, Sec.,	Maljamar Grayburg-San Andres						
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter A, 660 FNL & 660 FEL, Section 15, T-16-S, R-27-E  OCD - ARTESIA  Maljamar Grayburg-San Andres  11. County or Parish, State  Eddy, New Mexico							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent  ✓ Subsequent Report  ☐ Final Abandonment Notice	Casing Repair New (	re Treat Reclamation Construction Recomplete and Abandon Temporarily					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  8-5/8" csg @ 1,578' w/ 600 sx, circ.; 5½" 17# csg @ 8,900' w/ 600 sx on 1st stage, TOC @ 6,025' CBL, 400 sx on 2nd stage, TOC 2,120' by CBL. DV tool 3,397'; Open perfs 8,622 – 8,640'. 2-7/8" tubing & packer @ 8,541'  07/07/06 MIRU Triple N rig #22 & plugging equipment. Set steel pit. SDFN. 07/10/06 Notified BLM, Paul Swartz. Killed well and NU BOP. POOH w/ production tubing. RIH w/ CIBP. SDFN. 07/11/06 BLM Paul Swartz, on location. Set CIBP @ 8,553'. Circulated hole w/ mud, pumped 50 sx C cmt on CIBP 8,553 – 8,027'. Pumped 25 sx C cmt 6,346 – 6,094'. Perforated casing @ 4,800'. RIH w/ packer, unable to establish rate @ 1,800 psi. Pumped 25 sx C cmt @ 4,849'. POOH w/ tbg, SDFN. 07/12/06 Notified BLM, Paul Swartz, on location. Tagged cmt @ 4,692'. Pumped 25 sx C cmt 3,400 – 3,148' across DV tool. Cut and pulled 1,952' 5½" casing. RIH w/ tubing, pumped 45 sx C cmt @ 2,015'. WOC and tagged cmt @ 1,850'. Pumped 50 sx C cmt @ 1,637'. POOH w/ tubing to 409' and SDFN. 07/13/06 Tagged cmt @ 1,490'. Pumped 35 sx C cmt 409 – 273'. Pumped 15 sx C cmt 60' to surface; RDMO. Cut off wellhead & anchors, install dry hole marker							
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct		7				
James F. Newma	n, P.E.	Title Engineer, Triple N S	Services, Inc. 432-687-1994				
Signature Su		Date	07/24/2006				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
certify that the applicant holds legal which would entitle the applicant to		ct lease Office	Date  y to make to any department or agency of the United				
States any false, fictitious or fraudul	ent statements or representations as to any m	atter within its jurisdiction.	y to make to any department of agency of the officer				