## UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

Lease	Sena	No.	

Do not use this form for presents to drill on to us order or	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No. NMNM111789X
1. Type of Well Gas Well Other	8. Well Name and No.
2. Name of Operator Marbob Energy Corporation	Dodd Federal Unit #46  9. API Well No.
3a. Address 3b. Phope No (highyde area code)	30-015-26220
PO Box 227, Artesia, NM 88211-0227 505-748-3393 505-748-3395 505-748-55-75-75-75-75-75-75-75-75-75-75-75-75-	10. Field and Pool, or Exploratory Area  Grbg Jackson SR Q Grbg SA
1870 FSL 2615 FEL, Sec. 14-T17S-R29E, Unit J	11. County or Parish, State  Eddy Co., NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent  Alter Casing  Fracture Treat  Reclamation	Start/Resume) Water Shut-Off Well Integrity
Subsequent Report  Casing Repair  New Construction  Recomplete  Plug and Abandon  Temporarily	Other Perforate  Abandon
Final Abandonment Notice Convert to Injection Plug Back Water Dispos	
determined that the site is ready for final inspection.)  Perforated as follows:	amation, have been completed, and the operator has
determined that the site is ready for final inspection.)	
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well o	
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well o	
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well o	
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well o  14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Diana J. Briggs  Title Production Analyst	ut w/ acid. Returned to pump.  11/01/2006
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well of the state of	ut w/ acid. Returned to pump.  11/01/2006  E USE  ACCEPTED FOR RECOF
determined that the site is ready for final inspection.)  Perforated as follows:  POOH w/ rods & tbg. Made scraper run. Perforated @ 4095' - 4402' (30 shots). Cleaned well o  14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Diana J. Briggs  Title Production Analyst  Signature  Date	ut w/ acid. Returned to pump.  11/01/2006