OCD-ARTESIA

Form 3160 -3 1 2004) Month - Year OCD - ARTES

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

5. Lease Se
LC-02934

FORM APPROVED OMB No. 1004-0137 Expires March 31, 2007

rial No. l2A

6. If Indian, Allotee or Tribe Name

APPLICATION FOR PERMIT TO DR	6. If Indian, Anotee C)1 1110C 1	Name			
Jarypeofwork-: DRILL REENTER			· :	7 If Unit or CA Agree	ment, Na	me and No.
Ib. Type of Well: Oil Well Gas Well Other	Sing	le ZoneMultip	le Zone	8, Lease Name and W Woolley Federal		3025
2. Name of Operator		_		9. API Well No.		
COG Operating LLC 29/	131			<u> 30 - 0</u>	15-	3547
		(include area code)		10. Field and Pool, or E	-	•
550 W. Texas, Suite 1300 Midland, TX 79701 (4:	Loco Hills; Glori	etta Ye	eso			
4. Location of Well (Report location clearly andinaccorounce with any State	te requiremen	ts*)		I 1. Sec., T. R. M. or Bl	k, and Su	rvey or Area
At surface 990 FSL & 1650 FWL						
At proposed prod. zone ROSWELL CONTROLLE	ED WAT	ER BASIN		Sec. 21 T17S R30	0E	
14. Distance in miles and direction from nearest town or post office*				12. County or Parish		13. State
1/2 mile south of Loco Hills, NM				Eddy		NM
15. Distance from proposed* location to nearest property or lease line, ft.	16. No. of acres in lease 17. Spacin		17. Spacin	cing Unit dedicated to this well		
(Also to nearest drlg. unit line, if any) 330	120 40		40			
18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft.	19. Proposed Depth 20. Bl		20. BLM/I	M/BIA Bond No. on file		
applied for, on this lease, it. 660	6000 NMB(NMB00	000215		
	22 Approximate date work will start*		t*	2.3. Estimated duration		
3636' GR 2/	2/6/07			12 days		
	24. Attach	iments				
The following, completed in accordance with the requirements of Onshore O	il and Gas Oi	rder No. 1, shall be at	tached to th	is form:		
Well plat certified by a registered surveyor.	ĺ	A Rond to cover th	e operation	us unless covered by an e	ovictina k	and on file (ree
2. A Drilling Plan.		Item 20 above),	c operation	is diffess covered by an e	Misning C	oona on the (see
A Surface Use Plan (if the location is on National Forest System Lar SUPO shall be filed with the appropriate Forest Service Office).	nds, the	5. Operator certific6. Such other site sauthorized office	pecific info	ormation and/or plans as	may be r	equired by the
25. Signature	Name (Printed'/Typed)			Date	
June V. Senoll	Jerry V	W. Sherrell			1/8/07	
Title /						

FIELD MANAGER CARLSBAD FIELD OFFICE Application approval does not warrantor certify that the applicant holds lega or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Conditions of approval, if any, are attached.

/s/ James Stovall

APPROVAL FOR 1 YEAR

MAR <u>0 6 2007</u>

Title 18 U.S.C. Section 1001 and Tide 43 U.S.C. Section 1212, make it a crime for any person knowirilly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its juris iction.

Office

Name (Printedl/Typed)
S James Stovall

*(Instructions on page 2)

Production Clerk

Approved by (Signature)

SEE ATTACHED FOR CONDITIONS OF APPROVAL APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS ATTACHED

If earthen pits are used in association with the drilling of this well, an OCD pit permit must be obtained prior to pit construction.

State of New Mexico

DISTRICT I 1625 N. FRENCH DR., HOBBS, NM 88240

Energy, Minerals and Natural Resources Department

DISTRICT II

1301 W. GRAND AVENUE, ARTESIA, NM 88210

OIL CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505 Form C-102 Revised October 12, 2005 Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

WELL LOCATION AND ACREAGE DEDICATION PLAT

□ AMENDED REPORT

API Number	API Number Pool Code Pool Loco Hills; G1		me
			orieta-Yeso
Property Code	Property Name		Well Number
302589	WOOLLEY	11	
OGRID No.	Operate	or Name	Elevation
229137	MACK ENERGY	CORPORATION	3636'

Surface Location


1	UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
	N	21	17-S	30-E		990	SOUTH	1650	WEST	EDDY

Bottom Hole Location If Different From Surface

UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acres	Dedicated Acres Joint or Infill Consolidation Code Order No.								
40									


NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OPERATOR CERTIFICATION
	I hereby certify that the information berein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
GEODETIC COORDINATES NAD 27 NME	Signature Date
Y=660525.1 N X=608650.0 E	Jerry W. Sherrell Printed Name
LAT.=32.815372* N LONG.=103.979679* W	SURVEYOR CERTIFICATION
	I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
	NOVEMEBER 29, 2006
3636.9'3638.5'	Date Surveyed Signature & Seal of Professional Surveyor
3635.87 - 7639.4'	06.11.1841 Certificate No. GARY EIDSON 12641
	CHAD HARCROW 177777



DIRECTIONS TO LOCATION

FROM THE INTERSECTION OF U.S. HWY. #82 AND CO. RD. #217 (HAGERMAN CUT-OFF RD.), GO SOUTH ON CO. RD. #217 APPROX. 0.3 MILES. VEER LEFT AND GO EAST—SOUTHEAST APPROX. 0.2 MILES. VEER LEFT AND GO NORTHEAST APPROX. 0.2 MILES. THIS LOCATION IS APPROX. 80 FEET EAST.



100	0	100	200 Feet
	Scale: 1	"=100°	

MACK ENERGY CORPORATION

WOOLLEY FEDERAL #11 WELL LOCATED 990 FEET FROM THE SOUTH LINE AND 1650 FEET FROM THE WEST LINE OF SECTION 21, TOWNSHIP 17 SOUTH, RANGE 30 EAST, N.M.P.M., EDDY COUNTY, NEW MEXICO.

Survey Date: 1	1/29/06		Sheet	1	of	1	Sheets
W.O. Number: 06	11.1841	Dr .	By: J.R.		R	ev 1.	·N/A
Date: 12/07/06	Disk: CD#	<i>¥5</i>	0611	184	1	Scal	le:1"=100'

DRILLING PROGRAM

1. Geologic Name of Surface Formation

Quaternary

2. Estimated Tops of Important Geologic Markers:

Quaternary	Surface
Top of Salt	500'
Base of Salt	1025'
Yates	1600'
Queen	2130'
San Andres	3050°
Glorietta	4320'

3. Estimated Depths of Anticipated Fresh Water, Oil and Gas:

Water Sand	150'	Fresh Water
Grayburg	2580'	Oil/Gas
San Andres	3050'	Oil/Gas
Paddock	3950'	Oil/Gas

No other formations are expected to give up oil, gas or fresh water in measurable quantities. Setting 13 3/8" casing to 425' and circulating cement back to surface will protect the surface fresh water sand. Salt Section will be protected by setting 8 5/8" casing to 1300' and circulating cement back to surface. Any shallower zones above TD, which contain commercial quantities of oil and/or gas, will have cement circulated across them by cementing 5 1/2" production casing, which will be run at TD.

4. Casing Program:

Hole Size	Interval	OD Casing	Weight, Grade, Jt, Cond., Type
17 ½"	0-425°	13 3/8"	48#, H-40, ST&C, New, R-3
12 ¼"	0-1300°	8 5/8"	24#, J-55, ST&C, New, R-3
7 7/8"	0-TD	5 1/2"	17#, J-55, LT&C, New, R-3

Drilling Program Page 1

5. Cement Program:

- 13 3/8" Surface Casing: Circulate to Surface with Class C w/2% CaCl2.
- 8 5/8 Intermiate Casing: Circulate to Surface with Class C W/2% CaCl2.
- 5 1/2" Production Casing: Cement Casing with Class C w/6# Salt & 2/10 of 1% CFR-3 per sack. We will run a hole caliper and run sufficient cement to circulate to surface.

6. Minimum Specifications for Pressure Control:

The blowout preventer equipment (BOP) shown in Exhibit #9 will consist of a double ram-type (2000 psi WP) preventer. This unit will be hydraulically operated and the ram type preventer will be equipped with blind rams on top of 4 1/2" drill pipe rams on bottom. The BOP will be nippled up on the 13 3/8" surface casing and tested to 1500 psi by a 3rd party. The BOP will then be nippled up on the 8 5/8" intermediate casing and tested by a 3rd party to 2000 psi and used continuously until TD is reached. All BOP's and accessory equipment will be tested to 2000 psi before drilling out of intermediate casing. Pipe rams will be operationally checked each 24-hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment (Exhibit #10) will include a Kelly cock and floor safety valve and choke lines and choke manifold (Exhibit #11) with 2000 psi WP rating.

7. Types and Characteristics of the Proposed Mud System:

The well will be drilled to TD with a combination of brine, cut brine and polymer mud system. The applicable depths and properties of this system are as follows:

DEPTH	TYPE	WEIGHT	VISCOSITY	WATERLOSS
0-425'	Fresh Water	8.5	28	N.C.
425-1300'	Brine	10	30	N.C.
1300'-TD	Cut Brine	9.1	29	N.C.

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept at the well site at all times.

8. Auxiliary Well Control and Monitoring Equipment:

- A. Kelly cock will be kept in the drill string at all times.
- B. A full opening drill pipe-stabbing valve with proper drill pipe connections will be on the rig floor at all times.

9. Logging, Testing and Coring Program:

Drilling Program Page 2

- A. The electric logging program will consist of GR-Dual Laterolog, Spectral Density, Dual Spaced Neutron, CSNG Log and will be ran from T.D. to 8 5/8 casing shoe.
- B. Drill Stem test is not anticipated.
- C. No conventional coring is anticipated.
- D. Further testing procedures will be determined after the 5 1/2" production casing has been cemented at TD based on drill shows and log evaluation.

10. Abnormal Conditions, Pressures, Temperatures and Potential Hazards:

No abnormal pressures or temperatures are anticipated. The estimated bottom hole at TD is 110 degrees and estimated maximum bottom hole pressure is 2400 psig. Low levels of Hydrogen sulfide have been monitors in producing wells in the area, so H2S may be present while drilling of the well a plan is attached to the Drilling program. No major loss of circulation zones has been reported in offsetting wells.

11. Anticipated Starting Date and Duration of Operations:


Road and location work will not begin until approval has been received from the BLM. The anticipated spud date is February 6, 2007. Once commenced, the drilling operation should be finished in approximately 10 days. If the well is productive, an additional 30 days will be required for completion and testing before a decision is made to install permanent facilities.

Surface Use Plan Page 3

SURFACE USE AND OPERATING PLAN

1. Existing & Proposed Access Roads

- A. The well site and elevation plat for the proposed well is shown in Exhibit #1. It was staked by John West Engineering, Hobbs, NM.
- B. All roads to the location are shown in Exhibit below. The existing lease roads are illustrated in Blue and are adequate for travel during drilling and production operations. Upgrading existing roads prior to drilling well will be done where necessary.
- C. Directions to Location: From Loco Hills, go south .3 mile on CR 217, turn left/E-SE .2 mile, turn left/NE .2 mile this location is 80' east.
- D. Routine grading and maintenance of existing roads will be conducted as necessary to maintain their condition as long as any operations continue on this lease.



Surface Use Plan Page 4

Hydrogen Sulfide Drilling Operation Plan

I. HYDROGEN SULFIDE TRAINING

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing drilling operations on this well:

- 1. The hazards an characteristics of hydrogen sulfide (H2S)
- 2. The proper use and maintenance of personal protective equipment and life support systems.
- 3. The proper use of H2S detectors alarms warning systems, briefing areas, evacuation procedures, and prevailing winds.
- 4. The proper techniques for first aid and rescue procedures.

In addition, supervisory personnel will be trained in the following areas:

- 1. The effects of H2S on metal components. If high tensile tubular are to be used, personnel well be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling or reworking a well and blowout prevention and well control procedures.
- 3. The contents and requirements of the H2S Drilling Operations Plan and Public Protection Plan.

There will be an initial training session just prior to encountering a known or probable H2S zone (within 3 days or 500 feet) and weekly H2S and well control drills for all personnel in each crew. The initial training session shall include a review of the site specific H2S Drilling Operations Plan and the Public Protection Plan. The concentrations of H2S of wells in this area from surface to TD are low enough that a contingency plan is not required.

H2S Plan Page 11

II. H2S SAFETY EQUIPMENT AND SYSTEMS

Note: All H2S safety equipment and systems will be installed, tested, and operational when drilling reaches a depth of 500 feet above, or three days prior to penetrating the first zone containing or reasonable expected to contain H2S.

1. Well Control Equipment:

- A. Flare line.
- B. Choke manifold.
- C. Blind rams and pipe rams to accommodate all pipe sizes with properly sized closing unit.
- D. Auxiliary equipment may include if applicable: annular preventer & rotating head.

2. Protective equipment for essential personnel:

A. Mark II Survive air 30-minute units located in the doghouse and at briefing areas, as indicated on well site diagram.

3. H2S detection and monitoring equipment:

A. 1 portable H2S monitors positioned on location for best coverage and response. These units have warning lights and audible sirens when H2S levels of 20 PPM are reached.

4. Visual warning systems:

- A. Wind direction indicators as shown on well site diagram (Exhibit #8).
- B. Caution/Danger signs (Exhibit #7) shall be posted on roads providing direct access to location. Signs will be painted a high visibility yellow with black lettering of sufficient size to be readable at a reasonable distance from the immediate location. Bilingual signs will be used, when appropriate. See example attached.

5. Mud program:

A. The mud program has been designed to minimize the volume of H2S circulated to surface. Proper mud weight, safe drilling practices, and the use of H2S scavengers will minimize hazards when penetrating H2S bearing zones.

H2S Plan Page 12

6. Metallurgy:

- A. All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.
- B. All elastomers used for packing and seals shall be H2S trim.

7. Communication:

- A. Radio communications in company vehicles including cellular telephone and 2-way radio.
- B. Land line (telephone) communication at Office.

8. Well testing:

- A. Drill stem testing will be performed with a minimum number of personnel in the immediate vicinity, which are necessary to safely and adequately conduct the test. The drill stem testing will be conducted during daylight hours and formation fluids will not be flowed to the surface. All drill-stem-testing operations conducted in an H2S environment will use the closed chamber method of testing.
- B. There will be no drill stem testing.


EXHIBIT #7

WARNING YOU ARE ENTERING AN H2S AUTHORIZED PERSONNEL ONLY

- 1. BEARDS OR CONTACT LENSES NOT ALLOWED
- 2. HARD HATS REQUIRED
- 3. SMOKING IN DESIGNATED AREAS ONLY
- 4. BE WIND CONSCIOUS AT ALL TIMES
- 5. CHECK WITH MACK ENERGY FOREMAN AT OFFICE

MACK ENERGY CORPORATION 1-505-748-1288

DRILLING LOCATION H2S SAFTY EQUIPMENT Exhibit # 8




- H2S Monitors with alarms at the bell nipple
- ☐ Wind Direction Indicators

Attachment to Exhibit #9 NOTES REGARDING THE BLOWOUT PREVENTERS Woolley Federal #11 Eddy County, New Mexico


- 1. Drilling nipple to be so constructed that it can be removed without use of a welder through rotary table opening, with minimum I.D. equal to preventer bore.
- 2. Wear ring to be properly installed in head.
- 3. Blow out preventer and all fittings must be in good condition, 2000 psi WP minimum.
- 4. All fittings to be flanged.
- 5. Safety valve must be available on rig floor at all times with proper connections, valve to be full 2000 psi WP minimum.
- 6. All choke and fill lines to be securely anchored especially ends of choke lines.
- 7. Equipment through which bit must pass shall be at least as large as the diameter of the casing being drilled through.
- 8. Kelly cock on Kelly.
- 9. Extension wrenches and hands wheels to be properly installed.
- 10. Blow out preventer control to be located as close to driller's position as feasible.
- 11. Blow out preventer closing equipment to include minimum 40-gallon accumulator, two independent sources of pump power on each closing unit installation all API specifications.

H2S Plan Page 15

Exhibit #9 BOPE Schematic



Choke Manifold Requirement (2000 psi WP) No Annular Required



Adjustable Choke (or Positive)

Page 16


Blowout Preventers

Minimum Blowout Preventer Requirements

2000 psi Working Pressure 2 MWP EXHIBIT #10

Stack Requirements

	Stack Requirements									
NO.	Items	Min.	Min.							
	_	I.D.	Nominal							
1	Flowline		2"							
2	Fill up line		2"							
3	Drilling nipple									
4	Annular preventer									
5	Two single or one dual hydraulically operated rams									
6a	Drilling spool with 2" min. kill line and 3"		2"							
	min choke line outlets		Choke							
6b	2" min. kill line and 3" min. choke line]							
	outlets in ram. (Alternate to 6a above)									
7	Valve Gate	3 1/8								
	Plug									
8	Gate valve-power operated	3 1/8								
9	Line to choke manifold		3"							
10	Valve Gate	2 1/16								
	Plug									
11	Check valve	2 1/16								
12	Casing head									
13	Valve Gate	1 13/16								
	Plug									
14	Pressure gauge with needle valve									
15	Kill line to rig mud pump manifold		2"							
										



OPTIONAL

|--|

CONTRACTOR'S OPTION TO FURNISH:

- All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 2000 psi minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
- BOP controls, to be located near drillers' position.
- 4. Kelly equipped with Kelly cock.
- Inside blowout preventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6. Kelly saver-sub equipped with rubber easing protector at all times.
- 7. Plug type blowout preventer tester.
- 8. Extra set pipe rams to fit drill pipe in use on location at all times.
- Type RX ring gaskets in place of Type R.

COG TO FURNISH:


- 1. Bradenhead or casing head and side valves.
- 2. Wear bushing. If required.

GENERAL NOTES:

- Deviations from this drawing may be made only with the express permission of COG's Drilling Manager.
- All connections, valves, fittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through choke valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position
- Chokes will be positioned so as not to hamper or delay changing of choke beans.
 Replaceable parts for adjustable choke, or bean

- sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- All valves to be equipped with hand-wheels or handles ready for immediate use.
- Choke lines must be suitably anchored.
- Handwheels and extensions to be connected and ready for use.
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- All seamless steel control piping (2000 psi working pressure) to have flexible joints to avoid stress. Hoses will be permitted.
- Casinghead connections shall not be used except in case of emergency.
- 11. Do not use kill line for routine fill up operations.

Exhibit #11
MIMIMUM CHOKE MANIFOLD
3,000, 5,000, and 10,000 PSI Working Pressure
2 M will be used or greater
3 MWP - 5 MWP - 10 MWP



Mud Pit

Reserve Pit

* Location of separator optional

Below Substructure

Mimimum requirements

		3,000 MWP				5,000 MWP			10,000 MWP	
No.		I.D.	NOMINAL	Rating	I.D.	Nominal	Rating	I.D.	Nominal	Rating
1	Line from drilling Spool		3"	3,000		3"	5,000		3"	10,000
2	Cross 3" x 3" x 3" x 2"			3,000			5,000			
2	Cross 3" x 3" x 3" x 2"									10,000
3	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
4	Valve Gate Plug	1 13/16		3,000	1 13/16		5,000	1 13/16		10,000
4a	Valves (1)	2 1/16		3,000	2 1/16		5,000	2 1/16		10,000
5	Pressure Gauge			3,000			5,000			10,000
6	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
7	Adjustable Choke (3)	2"		3,000	2"		5,000	2"		10,000
8	Adjustable Choke	1"		3,000	1"		5,000	2"		10,000
9	Line		3"	3,000		3"	5,000		3"	10,000
10	Line		2"	3,000		2"	5,000		2"	10,000
11	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000
12	Line		3"	1,000		3"	1,000		3"	2,000
13	Line		3"	1,000		3"	1,000		3"	2,000
14	Remote reading compound Standpipe pressure quage			3,000			5,000			10,000
15	Gas Separator		2' x5'			2' x5'			2' x5'	
16	Line		4"	1,000		4"	1,000		4"	2,000
17	Valve Gate Plug	3 1/8		3,000	3 1/8		5,000	3 1/8		10,000

- (1) Only one required in Class 3M
- (2) Gate valves only shall be used for Class 10 M
- (3) Remote operated hydraulic choke required on 5,000 psi and 10,000 psi for drilling.

EQUIPMENT SPECIFICATIONS AND INSTALLATION INSTRUCTION

- 1. All connections in choke manifold shall be welded, studded, flanged or Cameron clamp of comparable rating.
- 2. All flanges shall be API 6B or 6BX and ring gaskets shall be API RX or BX. Use only BX for 10 MWP.
- 3. All lines shall be securely anchored.
- 4. Chokes shall be equipped with tungsten carbide seats and needles, and replacements shall be available.
- 5. Choke manifold pressure and standpipe pressure gauges shall be available at the choke manifold to assist in regulating chokes. As an alternate with automatic chokes, a choke manifold pressure gauge shall be located on the rig floor in conjunction with the standpipe pressure gauge.
- 6. Line from drilling spool to choke manifold should bee as straight as possible. Lines downstream from chokes shall make turns by large bends or 90 degree bends using bull plugged tees.

CONDITIONS OF APPROVAL - DRILLING

Well Name & No. Operator's Name: 11-Woolley Federal COG Operating LLC

Location:

0990FSL, 1650FWL, Section 21, T-17-S, R-30-E

Lease:

LC-029342A

I. DRILLING OPERATIONS REQUIREMENTS:

1. The Bureau of Land Management (BLM) is to be notified at the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822 - for wells in Eddy County, in sufficient time for a representative to witness:

- A. Spudding
- B. Cementing casing: 13-3/8 inch 8-5/8 inch 5-1/2 inch
- C. BOP tests
- 2. A Hydrogen Sulfide (H2S) Drilling Plan should be activated prior to drilling into the <u>Grayburg</u> Formation. A copy of the plan shall be posted at the drilling site. H2S has been reported in this section measuring 1900 ppm in gas streams from a well completed in the Seven Rivers and Grayburg Jackson. It has also been reported in Sec. 17-17S-30E measuring 1600 ppm in gas streams and 1500 ppm in STVs from the Queen, Grayburg Jackson and San Andres, and in Sec 20-17S-30E measuring 10,000 ppm in gas streams and 4000 ppm in STVs from the Grayburg Jackson and Morrow.
- 3 Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 4. Submit a Sundry Notice (Form 3160-5, one original and five copies) for each casing string, describing the casing and cementing operations. Include pertinent information such as; spud date, hole size, casing (size, weight, grade and thread type), cement (type, quantity and top), water zones and problems or hazards encountered. The Sundry shall be submitted within 15 days of completion of each casing string. The reports may be combined into the same Sundry if they fall within the same 15 day time frame.
- 5. The API No. assigned to the well by NMOCD shall be included on the subsequent report of setting the first casing string.
- 6. A Communitization Agreement covering the acreage dedicated to this well must be filed for approval with the BLM. The effective date of the agreement shall be prior to any sales.
- 7. Gamma-Ray/Neutron logs shall be run from the base of the Salado Formation to the surface; cable speed not to exceed 30 feet per minute.

II. CASING:

1. The 13-3/8 inch surface casing shall be set at a minimum of 25 feet into the Rustler Anhydrite at approximately 425 feet or in the case that salt occurs at a shallower depth above the top of the salt, below usable water and cement circulated to the surface. If cement does not circulate, contact the BLM for further instructions. Remedial cementing shall be completed prior to drilling out that string.

Possible loss of circulation in the Grayburg and San Andres formations.

Possible water flows in the Salado and Artesia Groups.

- 2. The minimum required fill of cement behind the <u>8-5/8</u> inch salt protection casing is <u>circulate cement to</u> <u>the surface</u>.
- 3. The minimum required fill of cement behind the <u>5-1/2</u> inch production casing is <u>cement shall circulate</u> to surface.

III. PRESSURE CONTROL:

- 1. All BOP systems and related equipment shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2. The BOP and related equipment shall be installed and operational before drilling below the 13-3/8 inch casing shoe and shall be tested as described in Onshore Order No. 2. Any equipment failing to test satisfactorily shall be repaired or replaced. BOP and BOPE when nippled up on the 13-3/8" casing will be tested to 1500 psi by independent service company. BOP and BOPE when nippled up on 8-5/8" casing will be tested to 2000 psi by independent service company.
- 2. Minimum working pressure of the blowout preventer and related equipment (BOPE) is 2M psi.
- 3. The appropriate BLM office shall be notified in sufficient time for a representative to witness the tests.
- The tests shall be done by an independent service company.
- The results of the test shall be reported to the appropriate BLM office.
- Testing fluid must be water or an appropriate clear liquid suitable for sub-freezing temperatures. Use of drilling mud for testing is not permitted since it can mask small leaks.
- Testing must be done in a safe workman-like manner. Hard line connections shall be required.

Engineer on call phone: 505-706-2779

WWI 021207