Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-22124 District II OIL CONSERVATION DIV 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis I **District III** STATE 🖂 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. **District IV** 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Washington 33 State PROPOSALS.) 8. Well Number 028 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number **BP** America Production Company 00778 3. Address of Operator 10. Pool name or Wildcat OCD-ARTESIA P. O. Box 1089 Eunice, New Mexico 88231 Artesia, Glorieta-Yeso 4. Well Location Unit Letter O: 313 feet from the South line and 2490 feet from the East line Township 17S Range 28E **NMPM** County Eddy Section 33 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661' GR Pit or Below-grade Tank Application ☐ or Closure ☐ Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ \Box COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON CHANGE PLANS** P AND A \Box **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB OTHER: Abandon Yeso perfs, add Queen perfs & frac OTHER: П 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. BP America proposes to abandon the Yeso, add perfs in the Queen and frac as outlined below. This work is being performed in preparation for waterflood operations on the Washington 33 State Lease (Artesia, Queen-Grayburg-San Andres pool). Please see attached schematics for wellbore details. Anticipated start date 6/25/07. 1. MIRU PU. Pull rods and pump. 2. Install BOP. POH with tubing. 3. RU wireline unit. Set CIBP at 3730' (Yeso perfs 3782-3966') and dump 35' cement on top. Perforate Oueen-Grayburg 1547-1575', 1642-1666', 1914-1930', 2126-2170', 2245-2263', RD WL. 4. Frac Q-GB 1547-2263' with approximately 80,000 gal gelled water and 50,000# sand. 5. Run production tubing. Remove BOP. Run pump and rods. 6. RDPU. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines _, a general permit _ or an (attached) alternative OCD-approved plan _. **SIGNATURE** TITLE agent for BP America production Company DATE 6/11/07 W. C. Heard BRYAN G. ARRANT E-mail address: bill.heard@bp.com Type or print name Telephone No. 432 / 688-5257

TITLE

JUN 1 5 2007

Conditions of Approval (if any):

DISTRICT II GEOLOGIST

For State Use Only

APPROVED BY:

Washington 33 State #28 Artesia Field

API No. 30-015-22124

313' FSL & 2490' FEL Sec 33 - T17S - R28E Eddy County, New Mexico

