

Submit 5 Copies To Appropriate District Office
 District I
 1025 N. French Drive., Hobbs, NM 88240
 District II
 1201 W. Grand, Artesia, NM 88210
 District III
 1000 Rio Grande Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State Of New Mexico
 Energy, Minerals, and Natural Resources

Form C-103
 Revised March 25, 1989

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

Well API No. 50-015-25126
 5056772361

6. Indicate Type Of Lease
 State For

8. State Oil and Gas Lease No.
 L-9945

7. Lessee Name Of Unit Agreement
 Name:
 Myrde Myra

9. Well No.
 400- W

6. Pool Name Or Wildcat
 LeVerna Bolivar

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type Of Well
 Oil Well Gas Well Other

Name Of Operator
 Ray Westall Operating

Address Of Operator
 P.O. Box 4 - Leon Hills, New Mexico 88255

Well Location

Unit Letter K : 1980 Feet From The South Line And 1980 Feet From The West Line

Section 09 Township 23S Range 27E NMPM County Sidky

10. Elevation (Show whether OR, AMSL, RT, GR, etc.)
 2188 OR

11. Check The Appropriate Box To Indicate Nature Of Notice, Report Or Other Act

NOTICE OF INTERVENTION TYPE		SUBSEQUENT REPORT OF:	
Remedial Work	<input type="checkbox"/> Plug And Abandon <input checked="" type="checkbox"/>	Remedial Work	<input type="checkbox"/> Alter Casing <input type="checkbox"/>
Temporary Abandon	<input type="checkbox"/> Change Plans <input type="checkbox"/>	Conductance Drilling OPER.	<input type="checkbox"/> Plug and Abandonment <input type="checkbox"/>
Plug Or Alter Casing	<input type="checkbox"/> Multiple Completion <input type="checkbox"/>	Casing Tool and Cement Job	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1102. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Set CIBP @ 4900', cap with 35' cement. Pull 5 1/2" casing from 2446'. Set 75 sec (300') @ 2700'. --- TAG must tag @ 2450' or Above
 Est. top 2400'. 5 1/2" cut off - 100' above 8 3/8" casing shoe. Set 12 cas (100') 9 1/8" - 8 1/8" across
 caplain roof. Set 12 sec (100') 8 3/8" - 4 3/8" in and out 13 3/8" casing shoe. Set 20 sec surface plug. - WOODY HRS - TAG

TAG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
 Signature [Signature] Title Production Secretary Date 07/10/03

Type Or First Name Rene Martinez Telephone No. (505) 677-2370
 (THIS SPACE FOR STATE USE)

APPROVED BY [Signature] Date 10 July 2003
 Conditions Of Approval If Any: