

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

WELL API NO.

30-015-32925

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

32673

7. Lease Name or Unit Agreement Name

Dulce Amor

8. Well Number

1

9. OGRID Number

155615

10. Pool name or Wildcat

Undesignated Morrow

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Nadel and Gussman Permian, L.L.C.

3. Address of Operator

601 N. Marienfeld, Suite 508

4. Well Location

Unit Letter 2 : 990 feet from the North line and 1980 feet from the East line

Section 4 Township 18S Range 26E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/21/03 - Circ & RU Schlumberger, cmt 5 1/2" csg w/stage of 100 sx, 35/65 poz and 700 sx 50/50 poz, circ 60 sx off DV tool. Circ. between stages, pump second stage 660 sx 35/65 poz and 50 sx Class H Neat, plug down at 2:00pm & circ. 50 sx to pit. RD BOPS, set slips, cut off csg & nipple up wellhead, test to 3000 psi, ok. Jet pits & release rig at 8:00pm - 9/21/03.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Martin TITLE Engineering Manager DATE 9/22/03

Type or print name Joel Martin E-mail address: Telephone No. 432/682-4429

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE OCT 02 2003

Conditions of approval, if any: