

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210-2118
TELEPHONE (505) 748-1471

S P YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

September 9, 2003

Mr. Bryan Arrant
Oil Conservation Division, District II Office
1301 W. Grand Ave.
Artesia, NM 88210

Re: Sacra SA Com. #20
1980' FSL and 1980' FEL
Section 35, T6S-R25E
Chaves County, New Mexico
H2S Contingency Plan



Sources at Yates Petroleum Corporation have relayed information to me that they believe there will not be enough H2S found in the Cottonwood Ranch Penn Formation to even meet the OCD's minimum requirements for the submission of a contingency plan per Rule 118.

Thank you,

YATES PETROLEUM CORPORATION

Debbie L. Caffall
Regulatory Technician