Subtifft 3 Copies To Appropriate District	State of New Me	vico		Form C-103
Office			'	May 27, 2004
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	ral Resources	WELL API NO.	114 27, 2001
District 11	OIL CONSERVATION	DIVISION	30-015-03166	
1301 W. Grand Ave , Artesia, NM 88210 District III			5. Indicate Type of Lease	e
1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Fran			FEE
District IV	Santa Fe, NM 87	(505	6. State Oil & Gas Lease	No.
1220 S St Francis Dr , Santa Fe, NM 87505	B-10714			
	S AND REPORTS ON WELLS		7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOSALS				
DIFFERENT RESERVOIR USE "APPLICATION PROPOSALS)	ON FOR PERMIT (FORM C-101) FC	JK SUCH	GJ West Coop Unit	
1. Type of Well: Oil Well 🛛 Gas	8. Well Number 6			
2. Name of Operator			9. OGRID Number 229137	
COG Operating LLC 3. Address of Operator	· · · ·		I 0. Pool name or Wildca	
-	X 70701			
550 W Texas, Suite 1300, Midland, T. 4. Well Location	X /9/01		Grayburg Jackson, 7RVS-QN-G-SA	VEmpire; Yeso, East
	310 feet from the Sout	h v v	990 feet from the	West line
<u></u>		mic unu		
Section	Township <u>17S</u> Ra		NMPM Coun	ty <u>Eddy</u>
· I	1. Elevation (Show whether DR, 3534'			
Pit or Below-grade Tank Application or Clo		UK		
Pit typeDepth Groundwater_		entor well Dis	tanaa fuam naanast suufaas wata	_
				r
Pit Liner Thickness: mil	Below-Grade Tank: Volume			
12. Check App	ropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INTE			SEQUENT REPORT	
		REMEDIAL WOR		
		COMMENCE DRI	=	
		CASING/CEMEN	_	
PULL OR ALTER CASING		CASING/CEIVIEN	I JOB LI '	
OTHER [.]	🛛	OTHER: Re-com	pletion	X
13. Describe proposed or completed		ertinent details, and	l give pertinent dates, inclu	
		ertinent details, and	l give pertinent dates, inclu	
13. Describe proposed or completed		ertinent details, and	l give pertinent dates, inclu	
 Describe proposed or completed of starting any proposed work) or recompletion. 	. SEE RULE 1103. For Multipl	ertinent details, and e Completions: Att	l give pertinent dates, inclu ach wellbore diagram of p	
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 	. SEE RULE 1103. For Multipl 5. Drilled out cmt plug from 2	ertinent details, and e Completions: Att 875-2997', cont'd	l give pertinent dates, inclu ach wellbore diagram of p drlg formation.	roposed completior
 Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 	SEE RULE 1103. For Multipl Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5	l give pertinent dates, inclu ach wellbore diagram of p drlg formation. 0 C POZ, bump plug, circ	roposed completion
 Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC	I give pertinent dates, inclu ach wellbore diagram of p drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad	roposed completion
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC	I give pertinent dates, inclu ach wellbore diagram of p drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad	roposed completion
 Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes.	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated fron	I give pertinent dates, inclu ach wellbore diagram of p drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad	roposed completion
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2	ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid.	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad n 3560-3690', 18 holes.	roposed completior c 35sx,
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2	ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes.	roposed completior c 35sx,
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL.	ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes.	roposed completion
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL.	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'.	roposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hole 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. so gals 20% HCL, 30,240 gals	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho ls 40# gel, 2500 ga	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL.	roposed completior c 35sx,
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. so gals 20% HCL, 30,240 gals	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho ls 40# gel, 2500 ga	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL.	roposed completior c 35sx,
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hole 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. so gals 20% HCL, 30,240 gals	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho ls 40# gel, 2500 ga	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL.	roposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hole 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. so gals 20% HCL, 30,240 gals	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho ls 40# gel, 2500 ga	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL.	roposed completior c 35sx,
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hole 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. so gals 20% HCL, 30,240 gals	ertinent details, and e Completions: Att 875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCl Moved RBP upho ls 40# gel, 2500 ga	l give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL.	roposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	. SEE RULE 1103. For Multipl g. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE . 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. 380 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing \$	ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH v	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad n 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. sls 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completior c 35sx, l-9, circ 0sx.
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. 380 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5	ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH w	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad n 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. ole & reset @ 3190'. ols 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completior c 35sx, l-9, circ 0sx.
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	SEE RULE 1103. For Multipl Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. 80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 e is true and complete to the be according to /MOCD guidelines [ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCI Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH v st of my knowledge	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ 0Z w/2.5# salt, 4/10 Halad n 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. ole & reset @ 3190'. ols 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completion 2 35sx, I-9, circ 0sx.
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized a 106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID I hereby certify that the information above grade tank has been/will be constructed or close 	SEE RULE 1103. For Multipl Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 hol es. 5 holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. 80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 e is true and complete to the be according to /MOCD guidelines [ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCI Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH v st of my knowledge	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad a 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. als 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completion 2 35sx, I-9, circ 0sx. that any pit or below- D-approved plan
 13. Describe proposed or completed of starting any proposed work). or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RIP 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. i80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 c is true and complete to the be according to MOCD guidelines [Constant of MOCD guidelines [ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH w st of my knowledge a general permit	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad a 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. ole & reset @ 3190'. uls 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completion 2 35sx, 1-9, circ 0sx. 2 hat any pit or below- 2 D-approved plan 3 8/31/06
 13. Describe proposed or completed of starting any proposed work), or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hole 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RI 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes 5 holes w/1500 gals 15% NE 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. i80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 c is true and complete to the be according to MOCD guidelines [Constant of MOCD guidelines [ertinent details, and e Completions: Att 2875-2997', cont'd ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. 500 gals 15% HCI Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH v st of my knowledge	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ bZ w/2.5# salt, 4/10 Halad a 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. ble & reset @ 3190'. sls 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completion 2 35sx, 1-9, circ 0sx. 2 hat any pit or below- 2 D-approved plan 3 8/31/06
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in ated from 3106-3132', 26 holes b holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. i80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 according to MOCD guidelines according to MOCD guidelines E-mail addr	ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH w st of my knowledge a general permit	I give pertinent dates, inclu ach wellbore diagram of pr drlg formation. 0 C POZ, bump plug, circ VZ w/2.5# salt, 4/10 Halad a 3560-3690', 18 holes. L. Set RBP @ 3709'. ole & reset @ 3190'. ole & reset @ 3190'. uls 15% HCL. w/2 1/2 x 2 x 22' pump.	roposed completion 2 35sx, 1-9, circ 0sx. 2 hat any pit or below- 2 D-approved plan 3 8/31/06
 13. Describe proposed or completed of starting any proposed work), or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in rated from 3106-3132', 26 holes boles w/1500 gals 15% NE . 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. 80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing s c is true and complete to the be according to MOCD guidelines [Caraca TITLE Pro- E-mail addressed]	ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH w st of my knowledge a general permit	I give pertinent dates, incluach wellbore diagram of production. 0 C POZ, bump plug, circle 0 Z W/2.5# salt, 4/10 Halade 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL. w/2 1/2 x 2 x 22' pump. e and belief. I further certify to or an (attached) alternative OC	roposed completion 2 35 sx, 1-9, circ 0 sx. that any pit or below- 2 - approved plan $3 - \frac{8/31/06}{2}$ the No. (432) 683-74
 13. Describe proposed or completed of starting any proposed work) or recompletion. 2-18-95 RIH w/6 1/8" bit, start drilling 3-10-95 TD @ 5205, RIH w/120 joints 2nd. stage 180sx Howco Lite 3-20-95 Ran CBL TOC @ 500'. Perfor Perforated 4152-4229' 15 hold 3-21-95 Acidized perfs 4152'-4229', 15 3-22-95 Reacidized w/15,580 gals 20% 3-23-95 Acidized perfs 3560-3690' 18 3-24-95 Acidized perfs 3106-3132' 26 3-25-95 Reacidized 3106-3132' w/15,5 3-27-95 POH wRBP @ 3190', then RID 	SEE RULE 1103. For Multiples. Drilled out cmt plug from 2 s 4 1/2 8rd LTC @ 4525' Cem w/6#salt, 1/4# flocele, tail in ated from 3106-3132', 26 holes b holes w/1500 gals 15% NE 2 6 HCL, 30,240 gals 40# gel, 2 holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. holes w/1500 gals 15% HCL. i80 gals 20% HCL, 30,240 ga H w/131 joints 2 7/8" tubing 5 according to MOCD guidelines according to MOCD guidelines E-mail addr	ertinent details, and e Completions: Att (875-2997', cont'd) ented w/90sx 50/5 130sx. 50/50 C PC es. Perforated from Acid. (500 gals 15% HCl Moved RBP upho Is 40# gel, 2500 ga SN @ 4239', RIH w st of my knowledge a general permit	I give pertinent dates, incluach wellbore diagram of production. 0 C POZ, bump plug, circle 0 Z W/2.5# salt, 4/10 Halade 1 3560-3690', 18 holes. L. Set RBP @ 3709'. ble & reset @ 3190'. sls 15% HCL. w/2 1/2 x 2 x 22' pump. e and belief. I further certify to or an (attached) alternative OC	roposed completion 2 35sx, 1-9, circ 0sx. 2 hat any pit or below- 2 D-approved plan 3 8/31/06

•

.

Submit to Appropriate District Office	e	State of New Mexico							Form C-105 Revised I-I-89				
State Lease - 6 copies Fee Lease - 5 copies	State Lease - 6 copies Energy, Minerals and Natural Resources Department											<u>`</u> _	
DISTRICT V									WELL API NO				
2040 South Pacheco							30	0-015-03166 5 Indicate Typ					
DISTRICT II 811 South First, Artesia, NM 88210 Santa Fe, New Mexico 87505								5 State Oil & Ga	STAT	ге 🛛	FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410								-10714		_			
WELL COMPLETION OR RECOMPLETION REPORT AND LOG													
1. Type of Well: OIL WELL GAS WELL DRY OTHER									7 Lease Name	or Unit Agree	ment N	ame	
b. Type of Completion NEW WORK WELL OVER		pen 🕅	PLUG BACK		DIFF RESVR 0	THER					.		
2. Name of Operator										- GJ West Coop Unit 8. Well No.			
COG Operating LLO									1 -	6			
3. Address of Operato	r								Ģ	9. Pool name o	r Wildcat		
550 W Texas, Suite 4. Well Location	1300, Mid	land, T	X 797(01					G	rayburg Jackson;	7RVS-QN-G-SA	VEmpire	; Yeso, East
Unit Letter	<u> </u>	2310	Feet	From The	Sou	uth	Li:	ne and	990	Feet Fr	om The	W	Est Line
Section	27	ı 		nship	17S	Range	: 	29E	NM		Eddy		County
10. Date Spudded	11. Date T	D Reache 10/95	ed	12 Date C	ompl <i>(Ready</i> 3/27/95	,		13. Elevat		& RKB, RT, GF	R, etc.)	. Elev.	Casinghead 3534'
2/18/95 15. Total Depth		10/95 Plug Bac	k TD	<u> </u>	3/2//95 17 If Multiple Co			18 1	ntervals	0' RKB Rotary Tools		Cable 7	
5205		-	4505		Many Zones?				Drilled By				t.
19 Producing Interval(s 3106-3690', GB/SA		-	-	ottom, Name					•	2	0. Was Directi	onal Su NO	rvey Made
21. Type Electric and Other Logs Run SDL-DSN-CSNG-DLL-MSFL							22. Was Well Cored No						
23	<u>, 1, 1, - 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, </u>									L			
CASING SIZE	WEI	HT LB			C <mark>CORD (1</mark> th set		<u>t all s</u> dle si	0		Y ell) 1enting ri		Tax	OUNT PULLED
8 5/8, J-55	wEit	24	./1'1.		21		$\frac{512}{11}\frac{31}{1/2}$			50sx		AW	OUNT FOLLED
7"		20		2	713		8		•	100sx			
4 1/2		11.6		4	525		6 1/8			400sx		1	
					· · · ·					· ·		<u> </u>	<u> </u>
24.	/			ER RECO	RD				25	·	SING RECO		
SIZE	ТОР	T		TTOM	SACKS CE	MENT	S(25 TUBING RECORD SCREEN SIZE DEPTH SET					PACKER SET
										2 7/8	4239		
							-r						<u></u>
26 Perforation reco				umber)				ACID, S		1		<u> </u>	EEZE, ETC.
		106-31 560-36						-3132'		L AMOUNT AND KIND MATERIAL USED See C-103 for detail			
		152-42						-3690'					<u></u>
							4152	-4229'		See C-103	for detail		·····
28					PRODU						1		
Date First Production 3/27/95		P	roductio	on Method (Flowing, gas l 2 1/2 s	ift, pumpi x 2 x 22	~	•••	pump)			s (Produ Produ	or Shut-in)
Date of Test	Hours Te	sted	C	hoke Size	Prod'n Fc		Dil - Bb		Gas - MC	CF W	/ater- Bbl.		Gas - Oil Ratio
Initial Test Unknow	n 24	hours			Test Peri	bd							
Flow Tubing Press.	Casing P	ressure		alculated 24- our Rate	- Oıl - Bbl.		Gas 	s - MCF	Wa	ter- Bbl.	Oıl Gravi	ty - AP	I - (Corr)
29. Disposition of Gas (Sold, used fo	r fuel, ver	nted, etc.,)	_L	. <u> </u>	_ ,			Test Wi	tnessed By		
30. List Attachments													
31. I hereby certify that the information shown on both sides of this form is true and complete to the best of my knowledge and belief													
Signature		50	ènd		rinted	Diane	Kuyke	endall,	Title	Producti	on Analyst	_ Date	8/31/2006

٤.

1

INSTRUCTIONS

This form is to be filed with the appropriate District Office of the Division not later than 20 days after the completion of any newly-drilled or deepened well. It shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also be reported. For multiple completions, Items 25 through 29 shall be reported for each zone. The form is to be filed in quintuplicate except on state land, where six copies are required. See Rule 1105.

INDICATE FORMATION TOPS IN CONFORMANCE W1TH GEOGRAPHICAL SECTION OF STATE

2

Southeastern New Mexico Northwestern New Mexico

T. Anhy	- T. Canyon	T. Ojo Alamo	_ T. Penn. "B"
	_ T. Strawn		_ T. Penn. "C"
	- T. Atoka		_ T. Penn. "D"
	_ T. Miss		_ T. Leadville
T. 7 Rivers	_ T. Devonian	T. Menefee	_ T. Madison
	_ T. Silurian		_ T. Elbert
T. Grayburg	T. Montoya	T. Mancos	_ T. McCracken
2526	_ T. Simpson	T. Gallup	_ T. Ignacio Otzte
T. Glorieta 4056	_ T. McKee	Base Greenhorn	_ T. Granite
T. Paddock	_ T. Ellenburger	T. Dakota	_ T
	_ T. Gr. Wash		_ T
T. Tubb	T. Delaware Sand	T. Todilto	_ T
T. Drinkard	_ T. Bone Springs		_ T
T. Abo	T. <u>Yeso</u> 4150	T. Wingate	_ T
T. Wolfcamp		T. Chinle	_ T
T. Penn		T. Permain	T
T. Cisco (Bough C)		T. Penn "A"	T
	OIL OR GAS S.	ANDS OR ZONES	
No. 1, from	to	No.3,from	to
No. 2, from	···· to	No. 4, from WATER SANDS	to
Include data on rate of water inflo	ow and elevation to which water rose	e in hole.	
No. 1, from	to	feet	
	to		
	to		
	THOLOGY RECORD (Atta	ach additional sheet if necess	san/)
			···· · · · · · · · · · · · · · · · · ·

From	То	Thickness in Feet	Lithology	From	То	Thickness in Feet	Lithology
•	4						