

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA



FORM APPROVED  
OMB No. 1004-0137  
Expires July 31, 2010

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5 Lease Serial No

NM 10190

6 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

MAR 25 2008

2 Name of Operator  
AmeriCo Energy Resources, LLC

OCD-ARTESIA

3a Address  
7575 San Felipe, Ste 200  
Houston, TX 77063

3b Phone No (include area code)

713-984-9700

7 If Unit of CA/Agreement, Name and/or No  
East Shugart Unit

NM 70943X

8 Well Name and No  
18

9 API Well No  
30-015-05679

10 Field and Pool or Exploratory Area  
Shugart Yates - 7Rs-Qn-Grayburg

4 Location of Well (Footage, Sec., T. R. M. or Survey Description)

1650' FSL & 1650' FEL - Section 34, Township 18S, Range 31E

11 Country or Parish, State  
Eddy, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION                                   | TYPE OF ACTION                                |                                           |                                                               |                                         |
|------------------------------------------------------|-----------------------------------------------|-------------------------------------------|---------------------------------------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input checked="" type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report           | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation                          | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice    | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                           | <input type="checkbox"/> Other          |
|                                                      | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon                  |                                         |
|                                                      | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal                       |                                         |

13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1. Re-check pump action to check for parted rod or hole in tubing
2. MIRU Service Rig and tie to permanent anchors
3. POOH with rods. If rods are parted pull with the tubing.
4. POOH with the tubing. If parted use overshot to fish
5. Tag well for PBTD
6. GIH with tubing, run insert pump on rods and space out.
7. Put well on pumping and check for pump action.
8. Report on tubing and rods details.
9. Rig down and move rig off location. Put well on production.

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Cathy A. Duffield

Title Regulatory Analyst

Signature

Date 03/17/2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

APPROVED

Approved by

Title

Date MAR 23 2008

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

JAMES A. AMOS

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

Accepted for record - NMOCD