## OCT 06 2008

(August 2007)

Form 3160-5 OCD-ARTESIA UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT **OCD-ARTESIA** 

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010 5. Lease Serial No.

ACCEPTED FOR RECORD



## SUNDRY NOTICES AND REPORTS ON WELLS

NMLC-029388C 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/A	greement, Name and/or No.	
Type of Well					
Other Gas Well Other			8. Well Name and JOHNSON A	No. FEDERAL #3	
2. Name of Operator LEGACY RESERVES OPERATING LP			9. API Well No. 30-015-05517		
3a Address P.O. BOX 10848 MIDLAND, TX 79702		3b. Phone No. (include area co	code) 10. Field and Pool or Exploratory Area		
		(432)689-5200	SHUGART-Y	SHUGART-YATES-7 RVRS-QUEEN-GRAYBURG	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Par	rish, State	
1980 FSL & 1980 FEL, UNIT LETTER J,	SEC 10, T-18-S, R-31-E		EDDY COUN	EDDY COUNTY, NM	
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATUR	E OF NOTICE, REPORT OR C	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume	e) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	✓ Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/11/08 MIRU plugging equipment and rig.

9/12/08 Rig up. ND wellhead, NU BOP. POH w/ 108 its tbg. SDFN.

9/15/08 RIH w/ tbg tag CIBP @ 3244'. Circulate hole w/ mud laiden fluid. POH w/ tbg.

9/16/08 Dig out cellar. ND BOP and wellhead. RU wireline, cut csg @ 2235'. Work csg 2 hrs. Came free. POH w/ 3 jts csg. SDFN.

9/1708 Layed down 52 jts csg. RIH w/ tbg to 2297'. Circulated hole. Spot 40 sx cement. Pull out of cement. SDFN.

9/18/08 Tagged plug @ 2142'. Spot 25 sx cement @ 2142'-1917'. POH w/ tbg. Spot 80 sx cement @ 962'-750'. WOC 4 hrs. Tag cement plug @ 745'. POH w/ tbg to 60. Pumped 15 sx cement from 60'-surface. Cut off wellhead and weld on Dry Hole Marker. Rig down move off.

## ACCEPTED FOR RECORD

not 7 2008 14 I hereby certify that the foregoing is true and correct Name of the Name of NMOCD-District II ARTESIA D. Patrick Darden, R.E. Title Senior Engineer BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE Date 09/19/2008

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

THIS SPACE TON EDERAL ON STATE OF THE USE					
Approved by					
	Title	Date			
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon	Office				

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction