

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.	NM-100558
6. If Indian, Allottee or Tribe Name	-----

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	NOV - 1 2008	7. If Unit of CA/Agreement, Name and/or No. -----
2. Name of Operator RKI Exploration & Production	OCD-ARTESIA	8. Well Name and No. RDX "17" # 1
3a. Address 3817 NW Expressway, Suite 950 Oklahoma City, OK. 73112	3b. Phone No. (include area code) 405-949-2221	9. API Well No. 30-015-36504
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2310' FSL 990' FEL Sec. 17-26S-30E		10. Field and Pool or Exploratory Area Brushy Draw - Delaware
		11. Country or Parish, State Eddy Co. New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Due to being unable to get below 1,065'. The following has been completed:
TRIP IN HOLE W/ DRILL PIPE & LAY DOWN SAME. TRIP IN HOLE W/ DRILL PIPE TO 1,000' LOST 65' OF HOLE (TERRY WILSON W/ BLM ON LOCATION APPROVED TO CEMENT @ 1,000'.

RIG UP SCHLUMBERGER & PUMP 1ST CEMENT PLUG, 450 SX "C" + 2% S1 DENSITY: 14.8, YIELD: 1.34, H2O 6.32 PULL OUT OF HOLE & WAIT ON CEMENT. TRIP IN HOLE TO 1,000', PUMP 2ND CEMENT PLUG, 200 SX "C" + 2% S1 DENSITY: 14.8, YIELD: 1.34, H2O 6.32 PULL OUT OF HOLE & WAIT ON CEMENT.

TRIP IN HOLE, TAGGED @ 985' PUMP 3RD CEMENT PLUG, 200 SX "C" + 2% S1, DENSITY: 14>8, YIELD 1.34 PULL OUT OF HOLE, WAIT ON CEMENT. TRIP IN HOLE, TAGGED @ 985' # 4 PUMP 150 SX "C" + 2% S1, DENSITY: 14>8, YIELD 1.34, H2O 6.32 PULL OUT OF HOLE, WAIT ON CEMENT. TRIP IN HOLE, TAGGED @ 983' # 5 PUMP 200 SX "C" + 2% S1, DENSITY: 14>8, YIELD 1.34, H2O 6.32 PULL OUT OF HOLE AND WAIT ON CEMENT.

TRIP IN HOLE, TAGGED @ 915' # 6 PUMP 200 SX "C" + 2% S1, DENSITY: 14>8, YIELD 1.34, H2O 6.32 PULL OUT OF HOLE, WAIT ON CEMENT. TRIP IN HOLE, TAGGED @ 800' # 7 PUMP 200 SX "C" + 2% S1, DENSITY: 14>8, YIELD 1.34, H2O 6.32 PULL OUT OF HOLE, WAIT ON CEMENT. TRIP IN HOLE TAGGED @ 200' # 8 CEMENT W/ 75 SX TO SURFACE. ACCEPTED FOR RECORD NOV 3 2008
WELD ON DRY HOLE MARKER. RIG DOWN.

14. I hereby certify that the foregoing is true and correct.
Name (Printed/Typed)

Gene Simer

NOV 3 - 2008
Gerry Guyer Deputy Field Inspector Production Superintendent
NMOCD-District II ARTESIA

Signature

Gene Simer

Date

10/20/08

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

NOV 1 2008

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

ACCEPTED FOR RECORD

NOV 1 2008

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE