



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

RECEIVED

NOV 3 9 2003

OCD-ARTESIA

Lori Wrotenberg

Director

Oil Conservation Division

11-19-03

PIA - Compliance closed

to

28 October 2003

BP America Production
P.O. Box 1089
Eunice, New Mexico 88231



Form C-103 Report of Plugging for your Empire Abo Unit 'F' # 363 H-34-17-28 API 30-015-22820
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

M. Kent Whitmore
Name
Production Lead
Title

[Signature]
Van Barton
Field Rep. II

Oil Conservation Division * 1301 West Grand Ave. * Artesia, New Mexico 88210
Phone: (505) 748-1283 * Fax (505) 748-9720 * <http://www.enmrd.state.nm.us>

No "F" on Well Marker -

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

DUPLICATE

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-22820

Indicate Type of Lease

STATE ☒

FEE ☐

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name
Empire Abo Unit "F"

Well No.

363

Pool name or Wildcat

ABO

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
Bp America Production Company

Address of Operator
PO Box 1089 Eunice, NM 88231

Well Location

Unit Letter H : 2250 Feet From The North Line and 1250 Feet From The East Line

Section 34 Township 17S Range 28E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ANBANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6348' PB:6308' Csg. 5 1/2 Perfs @ 6220'-6230' TOC Surface

8/28/03 MIRU Plugging unit.

8/29/03 Spot 25 sks of cement on top of existing CIBP @ 6190'. Circ well w/ plugging mud. Spot 25 sks of cement @ 3940'. Tagged @ 3685'

9/2/03 Spot 25 sks of cement @ 900'. Tagged @ 695'. Spot 25 sks of cement @ 695'. Tagged @ 418'.

9/3/03 Spot 10 sk surface plug 60'-surface.

Cut off wellhead and anchors 3' BGL. Capped well w/ steel plate. Installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED NOV 20 2003