

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

APR - 6 2009

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well

☐

Oil Well

☐

Gas Well

☒

Other P&A

2 Name of Operator

Yates Petroleum Corporation

3a Address

105 S. 4th Str., Artesia, NM 88210

3b Phone No (include area code)

575-748-1471

4 Location of Well (Footage, Sec., T, R., M., OR Survey Description)

1980'FNL & 1980'FWL of Section 23-T15S-R29E (Unit F, SENW)

5 Lease Serial No

NM-100552

6 If Indian, Allottee or Tribe Name

NA

7 If Unit or CA/Agreement, Name and/or No

NA

8 Well Name and No

Carthel BGT Federal #3

9 API Well No

30-005-64031

10. Field and Pool or Exploratory Area

Undes. Sulimar; Queen

11 County or Parish, State

Chaves County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

☐

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☒

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☐

Recomplete

☐

Temporarily Abandon

☐

Water Disposal

☐

Water Shut-Off

☐

Well Integrity

☐

Other

13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

APPROVED AS TO PLUGGING OF THIS
WELL BORE. LIABILITY UNDER BOND
IS RETAINED UNTIL SURFACE RESTORATION
IS COMPLETED

3/10/09 Drilled to 1890'. Hit water at 1883'.
3/11/09 Drilled to 1900'. Made several bailer runs - all 100% water recovery. Had 200' fluid in hole when ended tower.
3/12/09 TD 1900'. Bailed hole 60 times. Initially had 200' fluid, after bailing had 150'. ND and installed capping flange. Rig released at 1:00 PM on 3/12/09.
3/16/09 RU unit. NU BOP. RIH with tubing and tagged at 1890'. Circulated 133 bbls 9.5 ppg mud. Pulled tubing to 1693'. Spotted 80 sx Class "C" cement plug. POOH with tubing. Waited 2 hrs. RIH with tubing and tagged at 1524'. Pulled tubing to 420'. Spotted 40 sx Class "C" and calcium 14.8# cement plug. Wait 2 hrs. RIH with tubing and tagged at 300'. POOH with tubing. Pumped surface plug 14.8# Class "C" cement. ND BOP and shut down.
3/18/09 Cut off wellhead. Installed dry hole marker as per BLM. Cleaned location. **WELL IS PLUGGED AND ABANDONED.**

14 I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Tina Huerta

Title

Regulatory Compliance Supervisor

Signature

Date

March 25, 2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DRIC, SGP, DAVID E. GLASS

Title

PETROLEUM ENGINEER

Date

MAR 30 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)