

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

APR 28 2009

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-015-35194

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

EDDY BD STATE

8. Well Number 2

9. OGRID Number 13645

10. Pool name or Wildcat

GOLDEN LANE; MORROW (GAS)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

LYNX PETROLEUM CONSULTANTS, INC.

3. Address of Operator

P. O. BOX 1708, HOBBS, NM 88241

4. Well Location

Unit Letter B : 660 feet from the NORTH line and 1980 feet from the EAST line

Section 32 Township 20S Range 30E NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3385' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Perforate Additional Pay ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU. Kill well w/40 bbls. 2% KCL TFW. ND tree. NU hydraulic BOP.
2. Unseat 5 1/2" AS-1X packer @ 12258'. Tally tubing OOH.
3. RU Schlumberger. Set composite bridge plug @ 12330'. Spot 10' cement on top of BP. WOC overnight.
4. Load hole w/2% KCL TFW. RU Schlumberger (full fabricator). Perforate middle Morrow sands w/4 JSPF from 12244-46', 12270-79', and 12306-08'.
5. TIH w/5 1/2" AS-1X packer, F profile nipple, and on-off tool. Set packer @  $\pm$  12100'.
6. NU BOP. NU tree. Load annulus w/corrosion inhibited 2% KCL TFW and test to 500 psi.
7. RU Swab.
8. Additional stimulation may be recommended depending on swab results.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Debbie McKelvey TITLE AGENT DATE 4/23/09

Type or print name Debbie McKelvey E-mail address: \_\_\_\_\_ Telephone No. 505-392-3575

For State Use Only

APPROVED BY: Jaqueline R TITLE Geologist DATE 5/16/09