	. *,				
Submit 3 Copies To Appropriate District Office	State of New Me	N N	1AY 29 2009	Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	ral Resources '	WELL API NO.	June 19, 2008	
District II	OIL CONSERVATION	DIVISION	30-015-36792		
1301 W Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE F	EE 🗍	
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease N		
1220 S St Francis Dr, Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Ag	reement Name	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			GJ West Coop Unit		
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other		8. Well Number			
				269 9. OGRID Number	
2. Name of Operator COG Operating LLC			229137		
3. Address of Operator			10. Pool name or Wildcat		
550 W. Texas Ave., Suite 1300 Midland, TX 79701			GJ;7RVS-QN-GB-Glorieta	-Yeso 9/558	
4. Well Location Unit Letter L: 1650 feet from the South line and 330 feet from the East line					
Section 15	Township 17S Range	29E NMI			
The same of the sa	11. Elevation (Show whether DR,				
3549 GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
	••		•	05	
NOTICE OF II PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON □	REMEDIAL WOR	SEQUENT REPORT	OF: NG CASING □	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR			
PULL OR ALTER CASING		CASING/CEMEN	T JOB É		
DOWNHOLE COMMINGLE					
OTHER:			Completion		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.			······································	F	
04/06/09 Perf @ 5070-5270 w/ 2	2 SPF, 48 holes. Acidize w/ 2500	gal 15% acid. Fra	ac w/ 116,000 gal Silverste	m gel, 144,301#	
basf + 35091#crc 16/30 sand. PBTD 5440. Perf @ 4800-5000 w/ 1 SPF, 29 holes. Acidize w/ 2500 gal 15%acid Frac w/					
116,000 gal Silverstem gel, 146,122# BASF +31,630#CRC. Set comp plug @ 5030. Perf @ 4530-4730 w/ 1 SPF, 29 holes Acidize w/ 2500 gal 15% acid. Frac w/ 115,000 Silverstem gel, 140,869,# basf + 36917#. Set comp plug @ 4760. Perf @					
3980-4231 w/ 1 SPF, 29 holes. Acidize w/3000 gal 15% acid. Frac w/ 108,000 Silverstem gel, 106,400basf & 31060#CRC.					
Set comp plug @ 4260. 04/16/09 Drill out plugs, Clean out PBTD 5440.					
04/17/09 RIH w/181jts 2-7/8" J55 tbg, SN @ 5057'.					
04/18/09 RIH w/ 2 1/2"x2"x20" RHBC pump. Hang on well.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE SHOW	TITLE A	gent for COG	DATE05/27/	09	
Type or print name Chasity Ja	ckson E-mail address: cjack	son@conchoresour	ces.com PHONE: 432	-686-3087	
For State Use Only					
APPROVED BY:	TITLE C	zaclasist	DATE 6	11/20na	
Conditions of Approval (if any):	V	0			