Form 3160-5 (August 2007)

## OCD-ARTESIA

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NM-91078

6 If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and OTE VED SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well NOV -4 2009 8. Well Name and No Oil Well Other Gas Well Longview Federal 1-14 2. Name of Operator RKI - Exploration & Production, LLC 9. API Well No. 30-015-37324 NMOCD ARTESIA 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area Bone Spring 3817 NW Expressway, Ste. 950, OKC, OK. 73112 405.949.2221 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State EDDY, NM 810 FNL & 990FEL of Sec. 1-23S-28F 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Acidize Deepen Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Plug and Abandon Change Plans Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) RIG UP AND SPUD IN 10-18-2009. DRILLED 17-1/2" HOLE TO 290'. Ran 7 joints (294.99 ') of 13-3/8", 54.5#, J-55, STC CASING. LANDED CASING @ 295', CEMENT W/SCHLUMBERGER AS FOLLOWS: W/300 SKS, CLASS "C" + 1% S001@ 14.8 LBS/BBL, DISPLACE W/39 BBLS FRESH WATER, PLUG DOWN @ 05:40 HRS, HAD 25 BBLS OF FULL CEMENT RETURNS, BUMPED PLUG TO 1900 PSI, BLED BACK TO "0", FLOAT HELD DRILLED OUT SHOE 31. HOURS AFTER CEMENT IN PLACE. BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE Reported spud & cement job to Terry Wilson @ BLM 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Production Superintendent Gene Simer Title Date Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached Approval of this notice does not warrant or certify Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U S C Section 1001 and Title 43 U S C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,