

UNITED STATES
DEPARTMENT OF THE INTERIOR **OCD-ARTESIA**
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

RM

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on page 2**

| | | | |
|--|--|--|--|
| 1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other | | RECEIVED MAR 08 2010 | 5. Lease Serial No. NMNM 2748 |
| 2. Name of Operator BURNETT OIL CO., INC. | | | 6. If Indian, Allottee or Tribe Name |
| 3a. Address 801 CHERRY STREET, SUITE 1500 UNIT #9 FORT WORTH, TX. 76102-6881 | | 3b. Phone No. (include area code) (817) 332-5108 | 7. If Unit or CA/Agreement, Name and/or No. |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT F. 1650' FNL. 1650' FWL. SEC 11. T17S. R30E- SURF & BH | | | 8. Well Name and No. GISSLER B #49 |
| | | | 9. API Well No. 30-015-36824 S1 |
| | | | 10. Field and Pool, or Exploratory Area LOCO HILLS GLORIETA YESO |
| | | | 11. County or Parish, State EDDY COUNTY, N.M. |

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|---|---|---|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input checked="" type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other ALL PERFS |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | OPEN |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

12/28/2009 POOH w/tbg & sub pump, **set RBP @ 4930'**. RU W/L, perforate @ 4612', 4623', 4629', 4639', 4647', 4654', 4660', 4663', 4663', 4672', 4675', 4679', 4702', 4708', 4713', 4717', 4738', 4745', 4757', 4763', 4773', 4787', 4797', 4803', 4803', 4811', 4816', 4824', 4835', 4842', 4845', & 4864' - total 60 holes @ 2 SPF. 1/03/2010 Acidize these perfs w/3500 Gals 15% NeFe acid. POOH w/pkr & tbg. ND BOP, NU Frac valve. Slickwater frac w/845,712 gals FR-56 water, 20,000# 100 mesh white sand, 240,394# 40/70 mesh sand. 1/04/10 ND frac valve, NU BOP, GIH w/ 2-7/8" tbg w bailer, tag sand @ 4860' clean out to RBP @ 4933'. POOH w/ tbg & bailer. 1/5/10 GIH w/143 jts(4556") 2-7/8" 6.50# J55 R2 EUE T&C tubing and submersible pump. 1/14/2010 Test is 110 BO, 951 BW, 272 MCFG pumping to the Gissler B #3-1 tank battery on the lease. 2/15/10 POOH w/tbg & sub pump. 2/16/10 GIH w/tbg, bailer & ret tool. Clean out to top of RBP & release RBP @ 4930'. POOH w/RBP, bailer & tbg. 2/17-18/10 GIH w/bit, circ out sand down to CIBP @ 5340', drill out plug. Circulate hole clean to 5870'. 2/19/10 RIH w/154 jts (4906") 2-7/8" 6.50# J55 R2 tbg w/sub pump. All perforations (5403'-5649' TTL 34, 4981'-5275' TTL30, 4612'-4864' TTL 60) are now open in this well bore. Well is pumping to the existing Gissler B#3-1 tank Battery on the lease.

14. I hereby certify that the foregoing is true and correct.)

Name (Printed/Typed)

MARK A. JACOBY

Title ENGINEERING MANAGER

Signature

Mark A. Jacoby

Date

2/23/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date MAR 3 2010

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

J. J. 3-15-10