

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
RECEIVED
OIL CONSERVATION DIVISION
FEB 06 7004
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-01908
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator H. DWANE PARRISH JR		6. State Oil & Gas Lease No. 647
3. Address of Operator 1306 S 9th Artesia NM 88209		7. Lease Name or Unit Agreement Name Welch
4. Well Location Unit Letter <u>K</u> : <u>1570</u> feet from the <u>S</u> line and <u>1570</u> feet from the <u>W</u> line Section <u>17</u> Township <u>18 S</u> Range <u>28 E</u> NMPM County <u>Lea</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 009259
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

We tagged plug 1770 ft.
Set 100 ft plug inside + out 1870 1770 Tagged
pump 100ft cement plug inside + out 488-588 - did not tag
next day pump again cement inside + out 488-588 - tagged
perforated 272 ft pump 100ft plug cement all of casing string
inside + out 172-272 ft tagged. Perf all string 60 ft. Plug 60 ft
of cement inside part of all string 0-60 ft. Tag. Set dry hole
marker, cleaned location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE OWNER DATE 2-5-04

Type or print name
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE FEB 10 2004

Conditions of approval, if any