Office State of New Mexico	Form C-103
<u>District 1</u> Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-38076
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	McCoy State
1. Type of Well: Oil Well Gas Well Other	8. Well Number
	4
2. Name of Operator	9. OGRID Number
COG Operating LLC	229137
3. Address of Operator	10. Pool name or Wildcat
550 W. Texas Ave., Suite 1300 Midland, TX 79701	Empire; Glorieta-Yeso, East 96610
4. Well Location	
Unit Letter I: 2310 feet from the South line and 425	feet from the <u>East</u> line
Section 8 Township 17S Range 29E NM	PM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, et	
3606' GR	
12. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data
12. Check Appropriate Box to maleate Nature of Notice	t, report of other bata
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO	
	RILLING OPNS.□ PAND A □
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
DOWNHOLE COMMINGLE	_
DOWNHOLE COMMINGLE	_
OTHER:	Completion
	Completion
OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	Completion and give pertinent dates, including estimated date
OTHER: OTHER: OTHER:	Completion and give pertinent dates, including estimated date
OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	Completion and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok.	Completion and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel,	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold,
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Fexas Gold, 30,483# 16/30 SLC.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Fexas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date:	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well.	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date:	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date:	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE Regulatory Analys	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC. 10/28/10 10/28/10 DATE 12/20/10
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date: TITLE Regulatory Analys Type or print name Chasity Jackson E-mail address: cjackson@conchoresc	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC. 10/28/10 10/28/10 DATE 12/20/10
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date: TITLE Regulatory Analys Type or print name Chasity Jackson E-mail address: cjackson@conchoresc For State Use Only	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC. 10/28/10 10/28/10 DATE 12/20/10 purces.com PHONE: 432-686-3087
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. 11/11/10 Test csg to 3500# for 30min, ok. 11/12/10 Perf Lower Blinebry @ 4990 - 5190 w/ 1 SPF, 26 holes. 11/15/10 Acidize w/ 3,500 gals 15% acid. Frac w/ 115,134 gals gel, 34,373# 16/30 SLC. Set CBP @ 4960. Perf Middle Blinebry @ 472 w/ 3,500 gals 15% acid. Frac w/ 139,986 gals gel, 154,008# 16/30 11/16/10 Set CBP @ 4680. Perf Upper Blinebry @ 4450 - 4650 w/ gals 15% acid. Frac w/ 114,993 gals gel, 129,302# 16/30 Texas Go 11/21/10 Drill out plugs, Clean out PBTD 5345'. 11/22/10 RIH w/158jts 2-7/8" J55 tbg, SN @ 4981'. 11/23/10 RIH w/ 2 1/2"x2-1/4"x24'x28' pump. Hang on well. Spud Date: 10/18/10 Rig Release Date: TITLE Regulatory Analys Type or print name Chasity Jackson E-mail address: cjackson@conchoresc	Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 148,172# 16/30 Texas Gold, 0 - 4920 w/ 1 SPF, 26 holes. Acidize Texas Gold, 30,483# 16/30 SLC. 1 SPF, 26 holes. Acidize w/ 5,880 ld, 28,864# 16/30 SLC. 10/28/10 10/28/10 DATE 12/20/10 purces.com PHONE: 432-686-3087