Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

DCD-ARTHSIA

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000

## 5. Lease Serial No.

	A IA	4 2 1 2 4	በ41	70
- 1	· IVIIV	HMIVI	1 1/4 1	/h

SUNDRY NOTICES AND REPORTS ON WELLS 96 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well 8. Well Name and No. X Oil Well Gas Well Lost Tank 3 *#*15 2. Name of Operator Federal OXY USA Inc. 16696 9. API Well No. 3a. Address 3b. Phone No. (include area code) 30-015-37951 P.O. Box 50250, Midland, TX 79710-0250 432-685-5717 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Lost Tank Delaware, West SL - 2558 FNL 235 FWL SWNW(E) Sec 3 T22S R31E BH - 1530 FSL 653 FWL NWSW(L) 11. County or Parish, State NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Other Completion Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) RUPU 1/3/11, Drill out DV Tools and clean out to PBTD @ 8199'. Perf 1 SPF 8166-8004, 7892-7472, 7416-7340, 7226-7224, 7098-7094, 7034-6956, 6920-6532, 6430-6424' Total 78 holes. Frac w/ 62944g Treated Water followed by 8011gal 7-1/2% NeFe HCl acid followed by 16745gal Water Frac GR-21 followed by 204052gal Delta Frac 200 R-16 w/ 247059# sand, RD Halliburton. Swab and flow back to clean up well. RIH w/ 2-7/8" tbg and rod pump, Put well on pump 2/23/11 and test well for potential. Shut-In well pending C-104 approval. RECEIVED Accepted for record - NMOCD APR 11 2011 11-PG-H Dell NMOCD ARTESI 14. I hereby certify that the foregoing is true and correct Name (*Printed/Typed*) Title David Stewart Sr. Regulato Date 2011 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. DURFAU OF LAND MANAGEMENT ARI SBAD FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to prake to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.