Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Artes

iE	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
	5. Lease Serial No. NMNM-106718
	6. If Indian, Allottee or Tribe Name
1	7. If Unit or CA/Agreement, Name and/or No.
t	8. Well Name and No.
1	TAYLOR DEEP 12 FED #6 \smile
t	9. API Well No.
1	30-015-38143
T	10. Field and Pool, or Exploratory Area
1	Tamano; Bone Spring
	11. County or Parish, State
1	Eddy, New Mexico
ŧ	Eddy, New Mexico

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Öil Well Gas Well Other 2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC 3a. Address 3b. Phone No. (include area code) PO BOX 1936 ~ ROSWELL NM 88202-1936 575/623/6601 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 400' FNL & 510' FEL, Sec. 12: T18S, R31E, NE/4, NE/4 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R TYPE OF SUBMISSION TYPE OF ACTION Acidize Water Shut-Off Production (Start/Resume) Deepen Notice of Intent Alter Casing Reclamation Well Integrity Fracture Treat Other Completion Casing Repair New Construction Recomplete Subsequent Report Change Plans Temporarily Abandon Sundry Plug and Abandon Final Abandonment Notice Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) BLM Bond No. NMB00520 Surety Bond No. B004230 ACCEPTED FOR REC 1/19/11-MIRU PU, test casing to 2500 psi for 30 min-OK 1/20/11-Run CBL from PBTD to SURF. TOC-2104 Perforate 8702-8798, 0.4" 20 total 1/21/11-Acidize 8702-8798 w. 1500 gal HCL 2/22/11-Frac 8702-8798 w/ 103,029 gal gel + 211,506 #'s 16/30 prop. 2011 ΔPR Set Comp BP @ 8670, Perforate 8548-8622, 0.4" 22 total Frac 8548-8622 w/ 75,358 gal gel + 164,770#'s 16/30 prop. 2/23/11-Drill out Comp BP @ 8670, Clean out to PBTD. 2/24/11-RIH w/ production tubing 2 7/8" 6.4#, J-55. RIH w/ pump & rods. AU OF LAND MANAGEMENT 2/25/11-Place well on production. CARLSBAD FIELD OFFICE Accepted for record - NMOCD I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Production Tech Tammy R. Link 03/25/2011 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.