Submit 1 Copy To Appropriate District Office	State of I	New Mexico		C-103
District I	Energy, Minerals	and Natural Resources		13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-015-33165	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE STEE	
District IV Santa Fe, NM 8/505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Grandi ~	Name
1. Type of Well: Oil Well Gas Well Other			8. Well Number	
2. Name of Operator			9. OGRID Number	
Devon Energy Production Company, LP			6137 -	
3. Address of Operator 20 North Broadway, Oklahoma City, OK 73102 405.552.4615			10. Pool name or Wildcat Esperanza; Delaware	
4. Well Location	<del></del>			
Unit Letter D: 660 feet from	the North line and 66	0 feet from the West line		
Section 22	Township 22S	Range 27E	Eddy County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.				
	3122 KB; 3103' GL			
12. Check Ap	propriate Box to Inc	dicate Nature of Notice,	Report or Other Data	
NOTICE OF INTI	ENTION TO:	SUE	SEQUENT REPORT OF:	
	PLUG AND ABANDON			NG 🗌
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐				
PULL OR ALTER CASING				
DOWNHOLE COMMINGLE OTHER:		□ OTHER:		
	ead operations (Clearly		nd give pertinent dates, including estim	otad data
	). SEE RULE 19.15.7.		ompletions: Attach wellbore diagram of	
Wellbore Plugged & Abandoned 5/5/1	1			7
1. 4/29/11: MIRU. POOH w/2-7/8" tubing and packer from 5090".			RECEIVED	
2. TIH and tag previous cmt plug @ 5396.			MAY 10 2011	
3. Spot 110 sx cmt @ 5396'. Tagged TOC @ 5080. Displace hole w/salt gel mud.			MAT 10 ZOTT	
<ol> <li>Spot 60 sx cmt @ 2200'. Calc. TOC @ 2014'. (Not required to tag)</li> <li>Spot 45 sx cmt @ 505'. Tagged TOC @ 375'.</li> </ol> NMOCD ARTESIA				
6. Circulate 55 sx cmt from 128'			Milious	<b>-</b>
7. 5/5/11Cut csg strings off 3'	BGL. Set dry hole mar	ker. RDMO. Wellbore plug	gged & abandoned.	
Spud Date:	Rig R	Release Date:		
5p <b></b> 2	1051	torouse Bute.		
			•.	
I hereby certify that the information ab	ove is true and complet	e to the best of my knowled	ge and belief.	
$\rho$ . $\rho_{I}$	•			
SIGNATURE KAMME STA	<u>ck</u> titl	LE_Operations Technician_	DATE 5-6-1	<u>/                                     </u>
True on mint name Pourie Sheet			•	
Type or print name Ronnie Slack For State Use Only	E-mail address: _	Konnie.Slack@dvn.com	PHONE: _405.552.4615	,
Alc Hath.				
APPROVED BY:	yeen TITL	E Approved for plugging of well Liability under bond is retain	bore only. DATE 5/1/2	04/_
Conditions of Approval (if any):		of C-103 (Subsequent Report	of Well Plugging)	
		which may be found at OCD Forms, www.cmnrd.state.nm.	Web Page under	
		The are, was welland restates that.		B

