

1. Date of Report
(Month, Day, Year)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT
NM Oil & Gas Commission
Artesia, NM 88210
Drawer DD

2. Well No. NM-36194
3. Name of Indian, Allotment or Tribe

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such projects.

1. TYPE OF WELL: GAS WELL OIL WELL OTHER

DEC 14 '87

2. NAME OF OPERATOR: McKay Oil Corporation

O. C. D. ARTESIA, OFFICE

3. ADDRESS OF OPERATOR: Post Office Box 2014, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface

610' ENL & 400' FEL

5. UNIT AGREEMENT NAME

6. FARM OR LEASE NAME: South Four Mile Draw Fee

7. WELL NO.: #6

8. FIELD AND POOL OR WILDCAT: W. Pecos Slope Abo

9. SEC., T., R., M., OR BLE. AND SURVEY OR AREA: Sec. 21-6S-22E

10. COUNTY OR PARISH: Chaves

11. STATE: NM

12. ELEVATIONS (Show whether OF, TO, or etc.): 4330' GL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF	
TEST WATER SHUT-OFF	PLUG OR ABANDON CASING	WATER SHUT-OFF	REPAIRING WELL
FRAC TREAT	RE-DEPTH COMPLETION	FRAC TREATMENT	ALTERING CASING
RE-DEPTH OR ACIDIZE	ABANDON*	RE-DEPTH OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE LEASE	OTHER	


Operator: Plug and abandon

(Note: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

17. SOURCE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and bearings and true vertical depths for all markers and zones pertinent to this work.)

Operator plans to plug and abandon well as follows:

1. Set CI Bridge Plug @ 2,870'
2. Set 20 sxs. cement, Plug @ 2,870' - 2,620'
3. Set 20 sxs. cement, Plug @ 1,800' - 2,050'
4. Set 20 sxs. cement, Plug 1,025' - 775'
5. Set 10 sxs. cement, Plug @ 100' - surface
6. Install Dry Hole Marker
7. Rehabilitate surface of location and road as directed by BLM




18. I hereby certify that the foregoing is true and correct

SIGNED Theresa Rodriguez TITLE Production Analyst DATE 12-8-87

(This space for Federal or State office use)

APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side