

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 14 1993

DEC 23 11 08 AM '92

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-54856

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Crow Flats Fed A #1

9. API Well No.

20-015-24876

10. Field and Pool, or Exploratory Area

Dog Canyon Wolfcamp

11. County or Parish, State

Eddy, NM

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator

W.O.G., Inc.

3. Address and Telephone No.

P. O. Box 1813, Midland, TX 79702 (915) 685-0738

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL & 760 FEL of Unit H

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

Notice of Intent
 Subsequent Report
 Final Abandonment Notice

TYPE OF ACTION

Abandonment
 Recompletion
 Plugging Back
 Casing Repair
 Altering Casing
 Other Re-entry
 Change of Plans
 New Construction
 Non-Routine Fracturing
 Water Shut-Off
 Conversion to Injection
 Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill out 60' Surface Plug
Drill out plugs at base of intermediate casing at 1956'
Drill out plug at 3984' to 4050' at top of casing stub
Run 5 1/4" casing and tie back on top of 5 1/2" casing at 4050'
Drill out plug at 6313'
Perforate and test Wolfcamp zone from 6490'-6560'
Existing CIBP + 5 sx plugged off at 7600-7550-will not drill out.

This work commenced June 25, 1992 and well tested and first production 8/7/92 (per 3160-4 already submitted)

14. I hereby certify that the foregoing is true and correct

Signed

Linda Johnston

Title

Agent

Date

12/22/92

(This space for Federal or State office use)

Approved by

David R. Glass

Title

Date

Conditions of approval, if any:

C/SF