Drawer DD

Artesia, NM 88210

Form Approved. Budget Bureau No. 42-R1424

## UNITED STATES **DEPAR**

UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE LC-028784-b 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME RECEIVED  8. FARM OR LEASE NAME NOV 18 1982
1. oil gas other Injection Well  2. NAME OF OPERATOR	Keely "B" NUV 1 8 1982  9. WELL NO. 6 O. C. D.
General American Oil Company of Texas  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAMESIA, OFFICE Grayburg-Jackson
P. O. Box 128 Loco Hills, N.M. 88255  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  Sec. 25, T-17S, R-29E
AT SURFACE: AT TOP PROD. INTERVAL: 660' FNL and 1980' FWL AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3599 DF
REQUEST FOR APPROVAL TO:  TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)  ROSIVELL, NE	(NOTE: Resource results of multiple completion or zone change on Form 9–330.)  0.1982  G.A.S.  G.T. SERVICE
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly starincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	te all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and int to this work.)*
NOTE: Cast iron bridge plug set @ 2/6/° with 50 Rule 705-A.	of coment on top to comply with
WE REQUEST TO:	Sounds the Loca Wills as follows:
1. Dig smarr work over prov	forate the Loco Hills as follows: 136' - 2440' 2 shots per ft.
2. Perforate the Metex as follows: 2579' - 2583' 2 shots per ft.	126' - 2428' 2 shots per ft.

## WE REQUEST TO:

- Dig small wo 1.
- 2. Perforate t

2579' - 2583

2553' - 2555' 2 shots per ft.

2545' - 2547' 2 shots per ft.

2506' - 2510' 2 shots per ft.

- Fracture treat the Metex and Loco Hills Zone.
- Place well on test.

Subsurface Safety Valve: Manu. and Type	Set @	_ Ft.
18. I hereby cartify that the foregoing is true and correct  SIGNED and all M. Hawkins TULE Lende H. Howkins Lende Superintendent	November 15, 1982	
APPROVED (This space for Federal or State office use)  APPROVED (This space for Federal or State office use)  APPROVED (STATE OF THE OF	:	
FOR JAMES A. GILLHAM DISTRICT SUPERVISORSee Instructions on Reverse Side		