

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other TA Status

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

250' FSL & 250' FEL (SESE, Unit P) of Section 31-T17S-R30E

5. Lease Designation and Serial No.

NMLC028936G

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Brigham #3

9. API Well No.

30-015-04397

10. Field and Pool, or Exploratory Area

Loco Hills Q-GB-SA

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Temporary Abandon

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to Temporary Abandon as follows:

- POOH with tubing and packer.
- RIH w/bit & scraper on tubing and clean out to 2795'. POOH.
- GIH w/5-1/2" CIBP and set at 2790'. Dump 35' of cement on top of CIBP. Pressure test casing to 500 psi. NOTE: Have OCD/BLM officials witness the test.
- If casing tests okay, install pressure gauge and move out pulling unit.

NOTE: NOTIFY OCD (748-1283) AND BLM (887-6544) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

14. I hereby certify that the foregoing is true and correct

Signed

Rusty Klein

Title Production Clerk

Date June 21, 1994

(This space for Federal State or Local Use)

(ORIG. SGD.) JOE G. LARA

Title

Petroleum Engineer

Date

7/25/94

Approved by
Conditions of approval, if any: