

## Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.

ALINE COMPLETE THIS SECTION

Print your name and address on the reverse so that we can return the card to you.

Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

## ARY E. JOHNSON Governor

**Betty Rivera** Cabinet Secretary



GPILENERGY INC.

8	August	2002

### Via Certified Mail

G P II Energy, Inc. P.O. Box 50682 Midland, Texas 79710

or in Enterior, inc
PO BOX 50682
MIDLAND TX 79710

		4. Restricted Delivery? (Extra Fee)				
rticle Number	7007					
Transfer from service lab	ነበበጉ	7440	0007	9971	3372	

PS Form 3811, August 2001

Domestic Return Receipt

102595-01-M-250

☐ Yes

COMPLETE THIS SECTION ON DELIVERY

Received by ( Printed Name)

D. Is delivery address different from item 17

If YES, enter delivery address below:

☐ Express Mail

☐ C.O.D.

☐ Return Receipt for Merchandis

A. Signature

Service Type Certified Mail

☐ Registered

Insured Mail

NMOCD Rule 19.15.9.703 and 19.15.9.705 NOTICE OF VIOLATION: RE:

半入 G P II Energy, Inc.

API# 30-015-04058 H-2-17-30 Burnham Grayburg SA Ut #3 API# 30-015-05034 Featherstone # 5 C-2-17-31 P-3-17-30 API# 30-015-20315 Federal KK # 1 D-3-17-30 API# 30-015-04068 Federal Q # 1

Dear Sirs:

# This letter shall serve as a Notice of Violation of the rules of the New Mexico Oil Conservation

All of these wells failed a MIT in February 2000 and G P II Energy, Inc. was notified verbally at the Inc. was by letters dated 4-5-2002, 5-31-2002, and 6-4-2002 notified about this matter. This certific part because all directives have brought no response. The OCD is in receipt of C-103 forms dated 3 indicating work will be done "when rig becomes available". Inspections in July and August found n

Rule 19.15.9.703 of the New Mexico Oil Conservation Division provides as follows:

## 19.15.9.703 OPERATION AND MAINTENANCE

A. Injection wells shall be equipped, operated, monitored, and maintained to facilitate periodic testing and to assure continued mechanical integrity which will result in no significant leak tubular goods and packing materials used and no significant fluid movement through vertical channels adjacent to the well bore.

B. Injection project, including injection wells and producing wells and all related surface facilities shall be operated and maintained at all times in such a manner as will confine the injected fluids to the interval or intervals approved and prevent surface damage or pollution resulting from leaks, breaks,

C. Failure of any injection well, producing well, or surface facility, which failure may endanger underground sources of drinking water, shall be reported under the "Immediate Notification" procedure of Rule 116.

D. Injection well or producing well failures requiring casing repair or cementing are to be reported to the Division prior to commencement of workover operations.

E. Injection wells or projects which have exhibited failure to confine injected fluids to the authorized injection zone or zones may be subject to restriction of injection volume and pressure, or shutin, until the failure has been identified and corrected.

[7-1-81...2-1-96; 19.15.9.703 NMAC - Rn, 19 NMAC 15.I.703, 11-30-00]