

Copy to 57.

MOCC COPY

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
Getty Oil Company ✓

3. ADDRESS OF OPERATOR  
P.O. Box 730 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
660 FSL AND 660 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)  
3907 D.F.

5. LEASE DESIGNATION AND SERIAL NO.  
LC-029418 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Skelly Unit

8. FARM OR LEASE NAME

9. WELL NO.  
36

10. FIELD AND POOL, OR WILDCAT  
Grayburg Jackson

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA  
14-17-31

12. COUNTY OR PARISH  
Eddy

13. STATE  
N.M.

RECEIVED

FEB 22 1978

O. C. C.  
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Bring cement above 7-Rivers

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- (1) Pull rods and tubing.
- (2) Run Cement Bond Log.
- (3) Perforate and bring cement above top of 7-Rivers.
- (4) Run Temperature Survey.
- (5) Drill out cement.
- (6) Rerun tubing and rods.
- (7) Place well on production.

RECEIVED

FEB 16 1978

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Walter G. Quahett*

TITLE Area Superintendent

DATE 2-14-78

(This space for Federal or State office use)

ACTING DISTRICT ENGINEER

FEB 22 1978