| Form 9-331 (May 1963) | | UNITED STATES | SUBMIT IN TRIPLICATE | Budget Bureau No. 42-K1424. |
|---|------------------------------------|---|--|--|
| | DEPAR | TY OF THE INTER | | 5. LEASE DESIGNATION AND SERIAL NO. |
| | | GEOLOGICAL SURVEY | V. M. O. C. C. COPY | LC - 029420 (A) |
| | SUNDRY NC | TICES AND REPORTS | ON WELLS | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| (Do not us | e this form for proj Use "APPL" | posals to drill or to deepen or plug CATION FOR PERMIT—" for such | proposals.) | |
| 1. | | | - 11/5 D | 7. UNIT AGREEMENT NAME |
| | VELL OTHER | F E | GEIVED | Skelly Unit |
| 2. NAME OF OPERA | TOR | | | 8. FARM OR LEASE NAME |
| Getty Oi | 1 Company | 네 - 트웨티 - 전 (1912 <u>년) -</u> | | |
| 3. ADDRESS OF OP | | 9. WELL NO. | | |
| P. O. Bo | x 730; Hobb | 29 | | |
| 4. LOCATION OF W. See also space | ELL (Report location | 10. FIELD AND POOL, OR WILDCAT | | |
| At surface | | Grayburg-Jackson 3 | | |
| II-i- M G | CO DCI and | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA | | |
| Unit M, C | 660 FSL and | OOO TWL | | |
| | | | | 15-17S-31E |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whether | DF, RT, GR, etc.) | 12. COUNTY OR PARISH 18. STATE |
| | | 3846' DF | | Eddy New Mexico |
| 16. | Charle | Annonciate Box To Indicate | Nature of Notice, Report, or | Other Data |
| | | • • | | |
| | NOTICE OF INT | TENTION TO: | SUBSE | QUENT REPORT OF: |
| TEST WATER S | HUT-OFF | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL |
| PRACTURE TRE | AT | MULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CABING |
| SHOOT OR ACII |)IZB | ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT® |
| REPAIR WELL | | CHANGE PLANS | (Other) | As a suplished completion on Wall |
| | - Bring ce | | Completion or Recom | ts of multiple completion on Well pletion Report and Log form.) |
| 17. DESCRIBE PROPO | SED OR COMPLETED (| OPERATIONS (Clearly state all pertin ctionally drilled, give subsurface lo | ent details, and give pertinent date cations and measured and true vert | s, including estimated date of starting any ical depths for all markers and sones perti- |
| nent to this | work.) * | - | • | |
| | | | | |
| | .1 tubing and | | | |
| 2. Run cement bond log. | | | | |
| 3. Perforate and bring cement above 7-Rivers. | | | | |
| | temperatur | —————————————————————————————————————— | | |
| | un tubing a | | | |
| 6. Pla | 6. Place well back on production. | | | |
| | | | | |
| | | | | |
| | | | | 요 요 그 중심하다 그 중심하는 그 그 그 생각이 없다. |
| | | | RECEIVED | 불발하험을 가장 생기하는 것 |
| | AUG \$0 1977 | | | 시 : 이렇음질륨이를 눈꾸기었다. |
| | | | | |
| | | 그는 그림 살림하는 것은 말이 되었다. | | |
| | | • | U.S. GEOLOGICAL SURVE | មក្រុម ស្មីទី១ ទី១១ ទី១១១ |
| | | Υ * * ******************************** | | |
| | | | | |
| | | | ARTESIA, NEW MEXICO | |
| | | | | |
| | | | | |
| | | | | |

18. I hereby certify that the foregoing is true and correct

SIGNED TITLE Area Superintendent

(This space for Federal or State office use)

APPROVED BY TITLE DATE

DATE

DATE

DATE

*See Instructions on Reverse Side

ACTING DISTRICT ENGINEER