

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "B"

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson G.O.SA

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

17-17S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Atlantic Richfield Company ✓

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)
See also space 17 below.)
At surfaceB.O.C.
ARTESIA, OFFICE

660' FSL & 1980' FEL (Unit letter O)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3368' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL Csg.

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3437'. Propose to repair hole in 7" OD csg @ approx 2540' and acidize OH 2904-3438' in the following manner: Set 7" cmt retainer @ 2300' & cmt w/200 sx Thixomix followed by 100 sx Cl C, .3 of 1% CFR-2 & 4# sd/sk. Drill out retainer & cmt. Press test csg to 500#. Run tbq to 3250' & acidize w/4000 gals 15% Hy-Sperse acid in 4 stages dropping 100 pounds of TLC-80 between each stage. Swab back and return to production.

RECEIVED

AUG 27 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 8/23/74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

AUG 30 1974
L. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side