Form 3160-5 (November 1983) (Formerly 9-331)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

UNITED _ 'ATES **DEPARTMENT OF THE INTERIOR** BUREAU OF LAND MANAGEMENT

SUBMIT D

Oi.	ons.	0191
	OnsDistrict Bureau No. 1004-0135 Expires August 31, 1985	$\mathcal{O}(\cdot)$

		Artesia, N	LC-029420-B N/1	SIZU	
SUNDRY NOTICES AND REPORTS ON WELLS			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
(Do not use this form for prop Use "APPLIC	posals to drill or to deepen or plug back to a CATION FOR PERMIT - " for such proposa	different reservoir. als.)			
OIL GAS OTHER			7. UNIT AGREEMENT NAME Skelly Unit		
WELL WELL					
2. NAME OF OPERATOR	/		8. WELL NO.		
The Wiser Oil Company			15		
3. ADDRESS OF OPERATOR P.O. Roy 2568 Hobbs, New	w Mexico 88240 (505) 392-979	97/03 55/50 55	9. API Well No 30-015-05332		
P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797 (5) (55) (57)		10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.)			Grayburg Jackson 7-Rivers-QN-GB-SA		
At surface			11. SEC., T., R., M., OR BLK. AND		
760' FSL & 660' FWL			SURVEY OR AREA Sec. 21-T17S-R31E		
Unit M					
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3794' DF		RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE	
Charle A	Appropriate Box to indicate Nature	a of Notice Penart or Othe	Eddy County	NM	
16. Check A	appropriate Box to indicate Natur	1			
NOTICE OF INTENTION TO:		BSEQUENT REPORT OF:			
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WEL	L 🔲	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASI	NG	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	G ABANDONMENT	•	
REPAIR WELL	CHANGE PLANS	(Other) Acidize Seven Rivers			
(0.1)		(Note: Report results of multiple completion on Well			
(Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any					
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)					
3/30/98 MIRU Pool Well Service. POH w/rods. NU BOP's. POH w/2-3/8" tbg. RIH w/2-7/8" orange peel mud jt., 2-7/8" x 2-3/8" crossover, SN & 2-3/8" tbg. Acidized Seven					
Seven Rivers 2131'-2210' w/500 gals. 15% NE-FE acid. ATP 1550# @ 1/2 bpm. MTP 1550# @ 1 bpm. ISIP 1450#. 5 min. 975#. 10 min. 750#. 15 min. 475#. RD Pool.					
ND BOP's. NU WH.					
3/31/98 RIH w/rods & 2" x 1-1/2" x 8' RWBC pump. Left well pumping to Battery "A" Sat. # 3. RDMO. ACCEPTED FOR RECORD					
			Lacy acy		
			ALEXIS C. SWOBODA PETROLEUM ENGINEER		
		L 			
18. I hereby certify that the foregoing is true a	nd correct.				
SIGNED Mary Os Junua TITLE Production Tech II			DATESeptember 29, 20	001	
Mary Jo Turner				· · · · · · · · · · · · · · · · · · ·	
(This space for Federal or State office use)					