

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TOP TRUE VERT. DEPTH
			ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
		DEPTH	Acidized w/15,000 gals 15% acid. Frac'd w/36,700 gals 30# gel + 40,000# 20/40 sand.			
		3270' -3823'	Acidized w/2500 gals 15% NEFE.			
		3206' -3849'				