

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other WIW
well well

2. NAME OF OPERATOR ARCO Oil & Gas Company
Div of Atlantic Richfield Co. ✓

3. ADDRESS OF OPERATOR
P. O. Box 1710, Hobbs, N M 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 900' FNL & 2310' FWL
AT TOP PROD. INTERVAL: as above
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) Cmt Sqz, CO & Acidize

5. LEASE
LC-029426 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
H. E. West "A"

9. WELL NO.
13

10. FIELD OR WILDCAT NAME
Grayburg Jackson QGSA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
3-17S-31E

12. COUNTY OR PARISH
Eddy

13. STATE
N M

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3975.7 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
APR 21 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up, install BOP. POH w/comp assy. Clean out to 3695' PBD.
2. RIH w/RBP, set BP @ 3450', spot sd on top of BP.
3. Spot acid across perfs 3419-28'. Set cmt retr @ 3380' & cmt sqz perfs 3419-28' w/35 sx Cl C cmt w/2% CaCl₂. WOC.
4. DO cmt retr & cmt. Press test sqz job.
5. Circ sd off BP & POH w/RBP.
6. Set trtg pkr @ 3435' & acidize perfs 3474-3686' in 3 stages w/ 5000 gal 15% NE FE. POH w/pkr.
7. RIH w/pkr & injection assy. Set pkr @ approx 3450' & resume injection.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct


SIGNED Peter W. Chester TITLE Dist. Drlg. Supt. DATE 4/19/82

APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE _____ DATE _____
(This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY:

APR 22 1982
FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side



ARCO Oil & Gas Company

Division of Atlantic Richfield Company

Blow Out Preventer Program

Lease Name H. E. West "A"

Well No. 13

Location 900' FNL & 2310' FWL
3-17S-31E, Eddy County, N M

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.

gds
4/19/82