

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Copy to SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED		5. LEASE DESIGNATION AND SERIAL NO. LC 028936 C	
2. NAME OF OPERATOR Anadarko Production Company		APR 28 1978		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 67, Loco Hills, New Mexico 88255		D. C. C.		7. PERMIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980 F&WLS Sec. 28, T-17S, R-30E Eddy County, New Mexico		ARTESIA, OFFICE		8. FARM OR LEASE NAME Federal S	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3631 GL		9. WELL NO. 6	
				10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28 - 17S - 30E	
				12. COUNTY OR PARISH Eddy	
				13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) Perforate Additional Grayburg <input checked="" type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. RuPU, pull rods and tubing.
2. Perforate additional Grayburg (Loco Hills 2878-84) and (Metex 3000-06 & 3030-36) at 2 SFF.
3. Acidize new perforations using packer and bridge plug.
4. Frac new perforations w/65,000 gals gelled water and 65,000% sand.
5. Return to production.
6. Pull rods, run production log, return to pump.

RECEIVED
APR 17 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed by Jerry E. Buckles	TITLE Area Supervisor	DATE April 14, 1978
(This space for Federal or State office use)		
APPROVED BY See Mr. Lara	TITLE ACTING DISTRICT ENGINEER	DATE APR 27 1978
CONDITIONS OF APPROVAL, IF ANY:		