

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other
2. NAME OF OPERATOR
Anadarko Production Company ✓
3. ADDRESS OF OPERATOR
P. O. Box 67, Loco Hills, New Mexico 88255
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
 AT SURFACE: **1980' FSL & 990' FWL**
 AT TOP PROD. INTERVAL: **Same**
 AT TOTAL DEPTH: **Same**
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- | | | |
|--|-------------------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input type="checkbox"/> |
| (other) Install Gas-lift Equip. | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

RECEIVED
 DEC 15 1981

5. LEASE
LC 028936 (d)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
~~Loco Hills Federal~~ **COMMUNITIZATION UNIT** RECEIVED

8. FARM OR LEASE NAME
Loco Hills Fed. Com. DEC 17 1981

9. WELL NO.
1 O.C.B.

10. FIELD OR WILDCAT NAME
~~South Loco Hills Morrow~~ **Wildcat Atoka** DISTRICT OFFICE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
29 - 17S - 30E

12. COUNTY OR PARISH 13. STATE
Eddy **New Mexico**

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3555.3' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
 U.S. GEOLOGICAL SURVEY
 ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- Laid 2" NPT 11 1/2 V line pipe from compressor discharge line connection to well.
 - Ran blanking plug on wireline to isolate production interval.
 - Unlatched tubing from Guiberson Uni-6 packer.
 - Displaced casing with KCL water to equalize BHP.
 - Tripped out of hole with tubing.
 - Hydrotested tubing and valves in hole, spacing gas lift valves as recommended by Gas Lift Sales & Service Representative.
 - Swabbed KCL water down to bottom gas lift valve until tubing was dry.
 - Latched back into packer.
 - Installed surface equipment.
 - Tripped in hole and recovered blanking plug.
 - Kicked well off & adjusted surface equipment to obtain maximum production.
- Note:** Well continues to produce from the Morrow Limestone perfs 10,782-86'.
 Well presently producing 3 BC + 310 MCFGPD.
- Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE **Area Supervisor** DATE **December 14, 1981**

APPROVED BY: **KEITH W. CHICKER** TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
DEC 16 1981

U.S. GEOLOGICAL SURVEY