

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
RECEIVED BY BOX 2088
SANTA FE, NEW MEXICO 87501
JUL 21 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease
State ☒ Fee ☐
3. State Oil & Gas Lease No.
E-4201

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
Name of Operator	Empire South Deep Unit
Harvey E. Yates Company	8. Farm or Lease Name
Address of Operator	9. Well No.
PO Box 1933, Roswell, New Mexico 88201	18
Location of Well	10. Field and Pool, or WHCcat
UNIT LETTER F, 1980 FEET FROM THE North LINE AND 1980 FEET FROM	Undesignated Wolfcamp
THE West LINE, SECTION 30 TOWNSHIP 17S RANGE 29E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3643.4' GR	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER P&A pull approx 3500' 5 1/2" csg ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOC @ 4010 by Temp Survey/PBID @ 7940'; perfs: 7859-70'.

- Set CIBP @ 7800± w/35' cmt on top. - Land hole w/mud
- Pump 100' plug from 7300-7200'. (Top of Wolfcamp).
- Pump 100' plug from 6000-5900'. (Top of Abo).
- Free point 5 1/2" 17# N-80 & J-55 csg. Cut & pull approx 3500' ± csg.
- Pump 100' plug (50' in & out of 5 1/2" cut off). + Tag
- Pump 100' plug from 2950-2850'. (Across 8 5/8" shoe). + Tag
- Pump 100' plug from 450-350'. (Across 12 3/4" shoe interval).
- Pump 50' surface plug.
- Install dry hole marker.

Notify N.M.O.C.C. in sufficient time to witness

Plugging

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Ray F. O'Neil TITLE Production Manager/Engineer DATE July 14, 1987

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE JUL 23 1987

CONDITIONS OF APPROVAL, IF ANY: